#### **ILLINOIS MARINE TOWING**

3. Barge Inspection Report Forms – (June 2015)

Vessel General Permit Compliance

Equipment	IN085166		Vessel/Asset	Windy City	
Company:	Ingram Barge Con	npany	Waterway:	Illinois River	/ 299.4
Inspection Date Time	06/01/2015 07.3	30	Location:	IMT Lemont (Lower C	
Load Status:	○ Empty ○ Par	tial <b>®</b> Loaded		<b>,</b>	,
boiler areas, machinery t from the barge(s), corre	essible areas where cr storage areas, wellded ctive action must be init	nemicals, oils, dry cargo, i ks and other areas). [Ref	or is more frequent. (2) Locations or other materials are slored, mix is VGP 4.1.1] (3) If pollutants or of the term "sheen" is to be under 1.3.4.4]	ed and used (including, as	s applicable, cargo holds,
Are Decks Clean?	[3]	Any Violat	ions Discovered during Insp	ection or any correcti	ve actions required?
if no were decks cle	aned? []				·
is the Water around the free of sheen?	e barge				
Was a sample taker	1? 🖺				
Voids or Hopper Pump	ed?				
Sheen present in wa pumping?	elerafter 🔲				
Inspected by (Printed)	brandon baer				
Approved by (Printed)	Nicholas Steiche	n	Approved by (Signatu	re) Washington	M Strolas

Emergia your Diporture 93s increases that the basis is these bespected it accordance as indicated upone and notice two articles has been intered for any property asked.



Vessel General Permit Compliance

Equipment:	CBY422		Vessel/Ass	et: Midwest Pride	
Company:	Canal Barge	Company	Waterwa	y: Illinois River	, 279
Inspection Date Time:	06/01/2015	07.55	Locatio	n: Empty Fleet	
Load Status:	€ Empty	○ Partia! ○	Loaded	, ,	
boiler areas, machinery s from the bargers), correc	ssible areas w lorage areas, v tive action mus	bere chemical welldecks and it be initiated. [	voyage, whichever is more frequent. (2) Locations, oils, dry cargo, or other materials are stored, other areas). [Ref: VGP 4.1.1] (3) if pollutants are type 4.1.1] (4) The term "sheen" is to be used [Ref: VGP 4.1.1].	mixed and used (including, or constituents of concern	as applicable, cargo holds,
Are Decks Clean?	Ø		Any Violations Discovered during Ir	aspection or any correc	ctive actions required?
If no, were decks de	aned?				
is the Water around the free of sheen?	barge 🗹				
Was a sample taken	? 🗆				
Voids or Hopper Pumpe	:d? []				
Sheen present in wa pumping?	terafter 🖂				
Inspected by (Printed)	james we>	elberg			
Approved by (Printed)	Tommy Wa	alter	Approved by (Signa	ature)	

Exterior your Digitative of the order that the compression is been connected as a constraint as a darked with containing a field.



#### Vessel General Permit Compliance

Equipment	ING5810		Vessel/Asset	Albert C	
Company	Ingram Barge Cor	mpany	Waterway:	Illinois River	1 299.4
Inspection Date Time	06/01/2015 08	00	Location:	IMT Lemont (Lower Crane)	
Load Status:	○Empty ○ Pa	rtial <b>©</b> Loaded		,	
builer areas, machinery s from the barge(s), correc	ssible areas where c forage areas, wellded the action must be ini	hemicals, bils, dry cargo, cks and other areas). [Re	or other materials are stored, ma i: VGP 4.1.1] (3) If pollutants or i i) The term "sneen" is to be und	is to be inspected: Safely accessible xed and used (including, as applicat constituents of concern are determiners tood as a concentration of oil or	ole, cargo holds,
Are Decks Clean?	$\square$	Any Viola	ions Discovered during Ins	pection or any corrective actio	ns required?
If no, were decks cle	aned?			ŕ	
is the Water around the free of sheen?	barge 💟				
Was a sample taken	? 🗆	Target and the same of the sam			
Voids or Hopper Pumpe	d? 🗍				
Sheen present in wa pumping?	1				
Inspected by (Printed)	westley Williams	s			4 477.15
Approved by (Printed)	Carl Aldrich		Approved by (Signatu	ire) —	(p) da

Energy your Denature fits intensities that the bargare cover here inspected a social status as and cated applya and connective econocias becoming the property order.



Equipment: (	BY422		Vessel/Ass	et: Midw	est Pride	
Company: (	anal Barge	Company	Waterwa	ay: Illinoi	s River	, 277
Inspection Date Time (	6/01/2015	12.15	Locatio	n: Mobil	l Cake Spout	
Load Status;	() Empty (	OPartial 📀	Loaded			
areas and all safely acces boiler areas, machinery sto from the barge(s), correcti	sible areas w rage areas, v ve action mus	here chemical welldecks and it be initiated. [	voyage, whichever is more frequent. (2) Locat s, oils, dry cargo, or other materials are stored, other aress). [Ref: VGP 4.1.1] (3) If pollutants Ref: VGP 4.1.1] (4) The term "sheen" is to be a c oils [Ref VGP Fact Sheet 3.4.4]	mixed and or constitu	d used (including, as a tents of concern are	applicable, cargo holds, determined to be orinipation
Are Decks Clean?	Z		Any Violations Discovered during l	nspection	n or any corrective	actions required?
lfino, were decks clear	ned?					
is the Water around the lifee of sheen?	oarge 🔽					
Was a sample taken?						
Voids or Hopper Pumped	ıs [ <sup></sup> ]					
Sheen present in water	ar affer					
pumping?	" "E					
Inspected by (Printed)	james wex	.elberg				
Approved by (Printed)	Tommy Wa	alter	Approved by (Sign	ature)		
Towning your Signmine File problems noted	indicated that	tibe befores	Navn been inspected fit spoordenae ae indicati	स्त हो.घ५		Company of the Company



Vessel General Permit Compliance

Equipment:	NG7708		VesseVAsset	Midwest Pride	
Company: J	ngram Barge Con	npany	Waterway.	Illinois River	/ 277
Inspedion Date Time   1	06/01/2015 16	00	Location	Mobil Coke Upper	
Load Status:	○ Empty ○ Par	tial <b>©</b> Loaded	•		
boiler areas, machinery st	isible areas where cr prage areas, wellded ive action must be inf	nemicals, oils, dry cargo iks and other areas) [Ri tisted, [Ret: VGP 4.1.1]	ver is more frequent. (2) Locations, or other materials are stored, most: VGP 4.1.1] (3) If pollutants or a (4) The term "sheen" is to be underset Sheet 3.4.4]	ced and used (including, as a	applicable, cargo holds,
Are Decks Clean?		Any Viola	ations Discovered during Insp	ection or any corrective	actions required?
if no, were decks clea	ned?				·
is the Water around the free of sheen?	barge 🔽				,
Was a sample taken?					
Voids or Hopper Pumper					
Sheen present in wate pumping?	erafter []				
Inspected by (Printed)	james wexelberg	1			
Approved by (Printed)	Tommy Walter		Approved by (Signatu	re)	
Totakon norūkanance Da	Christian Mattribus	ar sector also as a succession of			1. 6.

forming your Signature PM indicates that the unique's characters in accordance us indicated accordance in the state of the



Vessel General Permit Compliance

Equipment:	IMT212		Vessel/Asset:	Windy City	
Сотрапу	Canal Barge Cor	прану	Waterway:	Illinois River	/ 299.4
Inspection Date Time	06/01/2015 17	' 30		IMT Lemont (Clean)	,
Load Status:		anial 🔿 Loaded		,	
boiler areas, machinery s	ssible areas where i forage areas, wellde five action must be it	chemicais, olis, dry cargo cks and other areas) [R hitiated. [Ref: VGP 4.1.1]	ver is more frequent. (2) Locations, or other materials are slored, mix af: VGP 4.1.1) (3) If pollutants or of (4) The term "siteen" is to be undefact Sheet 3.4.4)	ed and used (including, as exastituents of concern so	s applicable, cargo holds,
Are Decks Clean?	Ø	Any Viol	ations Discovered during Insp	ection or any correcti	ve actions required?
If no, were decks de	aned?			·	
	ar e	7-0-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-			
is the Water around the free of sheen?	barge 🔽				
Was a sample taken	? 🔲				
Voids or Hopper Pampe	:d? 🗀				
Sheen present in wa pumping?					
Inspected by (Printed)	brandon baer				
Approved by (Printed)	Nicholas Steich	en	Approved by (Signatu	re) Alecharlisa	M Striker

Entering planting for consists to store that pure their to decide appropriate as into present controller or the backhair moder to the appropriate and



#### Vessel General Permit Compliance

Equipment.	IMT212		Vessel/Asset:	Windy City	
Company	Canal Barge Co	mpany	Waterway:	Illinois River	1 299.4
Inspection Date Time	06/01/2015 1	7 30	Location:	IMT Lemont (Clean)	
Load Status:	<b>⑥</b> Empty ○ F	onial O Loaded		•	
boiler areas, machinery from the barge(s), corre	ressible areas where storage areas, welld active action must be	i chemicals, oils, dry cargo lecks and other areas). [Ri	ver is more frequent. (2) Locations or other materials are slored, most: VGP 4.1.1] (3) If pollutants or (4) The term "sheen" is to be undeact Sheet 3.4.4]	ed and used (including, as constituents of concern are	applicable, cargo holds, determined to be origination
Are Decks Clean?	2	Any Viole	ations Discovered during Insp	ection or any corrective	e actions required?
If no, were decks cl	eaned?				
	and the second				
Is the Water around th	ne barge				
Was a sample take	n?				
Voids or Hopper Pump	ped?				
Sheen present in w pumping?	rater after				
Inspected by (Printed	t) brandon baer			<b>.</b>	
Approved by (Printed	) Nicholas Steic	hen	Approved by (Signatu	re) Alphalde	M 大toolers

Foreing your Signature for moditions that the transports have been inspected in accordance as makeded above and corrective action has been intered for any problems solded.



Equipment	IN075096		Vesseli	/Asset	Midwest Pride	
Company:	Ingram Ba	arge Comp	arry Wat	erway.	Himois River	1 279
Inspection Date Time:	06/01/201	5 22 15	Lo	cation:	Load Fleet	
Load Status:	O Emp	ty C Partia	il <b>©</b> Losded			
boiler areas, machinery sl from the barge(s), correct	ssible areas brage areas live action m	. Where che s, welldecks nust be initie	per voyage, whichever is more frequent. (2) Enicals, oils, dry cargo, or other materials are sto and other areas). [Ref: VGP 4.1.1] (3) If pollutied [Ref: VGP 4.1.1] (4) The term "sheen" is to ganic oils [Ref VGP Fact Sheef 3.4.4]	ared, mi ants or	ixed and used (including constituents of concern	), as applicable, cargo holds,
Are Decks Clean?	(	<b>V</b>	Any Violations Discovered dนก	ng Ins	pection or any corre	ctive actions required?
If no, were decks clea	aned? [					
is the Water around the free of sheen?	barge [	Ø				
Was a sample taken	? [					
		The second secon				
Voids or Hopper Pumpe	d? [					
Sheen present in wat pumping?	erafter (					
Inspected by (Printed)	patrick e	rickson				
Approved by (Printed)	Tyshun C	Griffin	Approved by (S	Signate	•	
Potessoy your Signature Fol providens enter	l indicates t	en de ce trans	rifs in a wilbeem is specified to a coal leanch as in	r da Se di	ahov 🥰	I Agg



Vessel General Permit Compliance

Equipment:	CBY246		VesseVAsset	Windy City	
Company:	Canal Barge	Company	Waterway:	Illinois River	/ 329.9
Inspection Date Time:	06/02/2015	00:50	Location:	WALSH FLEET	
Load Stalus:	○ Empty (	Partial 🌘	Loaded		
areas and all safely acce boiler areas, machinery a from the barge(s), correc	ssible areas wi tersge areas, v tive action mus	here chemical velidecks and I be initiated. [	voyage, whichever is more frequent. (2) Locations is, oits, dry cargo, or other materials are stored, mix. other areas). [Ref: VGP 4.1.1] (3) if poliutants or c. [Ref: VGP 4.1.1] (4) The term "sheen" is to be unde ic oits. [Ref. VGP Fact Sheet 3.4.4]	ed and used (including, as onstituents of concern are	applicable, cargo holds,
Are Decks Clean?			Any Violations Discovered during Insp	ection or any correctiv	e actions required?
If no, were decks cle	aned? [☑]		Swept product from walkways, bow & stern		
is the Water around the free of sheen?	barge 🗹				
Was a sample taken	1?				
Voids or Hopper Pumps	ed? 🗀				
Sheen present in wa pumping?	iterafter				
Inspected by (Printed)	Roy Sparro	ow.		ı w	
Approved by (Printed)	Randy Barr	on	Approved by (Signatur	re) Rondell 7	: Xhun W.

Tricing your Special Physologisms that the margin symbol been called to according a class or maked show the margin's order.



Vessel General Permit Compliance

Equipment.	CBY230		Vessel/Asset: Wi	ndy City	
Company:	Canal Barg	e Company	Waterway: Illin	nois River	/ 329.9
Inspection Date Time	06/02/2015	01 20	Location: W	ALSH FLEET	
Load Status:	○ Empty	O Partial (	DLoaded		
areas and all safely acc boiler areas, machinery from the barge(s), corre	essible areas v storage areas, ctive action mu	vhere chemic welldecks an st be initiated	er voyage, whichever is more frequent. (2) Locations to als, oils, dry dargo, or other materials are stored, mixed a d other areas.). [Ref: VGP 4.1.1] (3) if polutants or cons. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understonic oils. [Ref. VGP Fact Sheet 3.4.4]	and used (including, as applicable stituents of concern are determine	, cargo holds, ed to be originatino
Are Decks Clean?		)	Any Violations Discovered during Inspect	tion or any corrective actions	required?
If no, were decks cle	eaned? 💆		Swept product from walkways, bow & stern		
is the Water around th	e barge	0			
Was a sample take	n? [	)			
	-				
Voids or Hopper Pump	ed?	)			
Sheen present in w pumping?	alerafler [	]			
Inspected by (Printed	) Roy Span	10 Yy		· •	
Approved by (Printed)	) Randy Ba	កសា	Approved by (Signature)	Foundall F. Kan	in. W.

Indemagnetic Scotter and PRC a pleases that the bengank indexe paper inspection in account ordinarials indicated at on

Equipment:	IN085166		Vessel/Asset.	Albert C	
Company.	Ingram Barge Cor	npany	Waterway:	Illinois River	/ 298
Inspection Date Time	06/02/2015 08:	55	Location.	IMT Lemont (NRF)	
Load Status:	○ Empty ○ Pa	dial 🏵 Loaded			
boiler areas, machinery s	ssible areas where c forage areas, wellded tive action must be ini	hemicals, oils, dry cargo iks and other areas) [Re tiated. [Re1: VGP 4.1.1]	rer is more frequent. (2) Location, or other materials are stored, more VSP 4.1.1] (3) If pollutants or of (4) The term "sheen" is to be under act Sheet 3.4.4]	red and used (including, as	s applicable, cargo holds, e determined to be orininating
Are Decks Clean?	$oldsymbol{ol}oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{ol}}}}}}}}}}}}}}$	Any Viole	itions Discovered during Ins	pection or any correctiv	/e actions required?
If no, were decks cle	aned?				
Is the Water around the free of sheen?	ebarge ☑				
Was a sample taker	1?				
Voids or Happer Pumpe					
Sheen present in wa					
pumping?		1			
Inspected by (Printed)	Westlev William	ıs			
Approved by (Printed)	•		Approved by (Signatu	re)	•
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					L Denlas
l Mering your Rightstore k proteinnik miles	El articules that the b	atgers, have need inche	end is accordance as industed a	novert	L Verlas

Equipment, II	1065407		Ves	ssel/Asset:	Albert C	
Company: Ir	ngram Barge	Company		Waterway:	Illinois River	/ 293
Inspection Date Time 0	6/02/2015	11.10		Location.	OXBOW	
Load Status:	○ Empty ○	Partial <b>®</b> Lo	oaded			
boiler areas, machinery sto from the barge(s), correcting	sible areas whe rage areas, we re action must t	ere chemicals, elidecks and on oe initiated. [Re	yage, whichever is more frequent. oils, dry cargo, or other materials ar her areas) [Ref: VGP 4.1.1] (3) If p f: VGP 4.1.1] (4) The term "sheen" ils [Ref VGP Fact Sheet 3.4.4]	e stored, mo pollutants or d	sed and used (including	ig, as applicable, cargo holds.
Are Decks Clean?	V		Any Violations Discovered	during Inst	pection or any corr	ective actions required?
If no, were decks clear	ned?					
is the Water around the t	oarge [☑]					
Was a sample taken?		a de la companya de l				
Volds or Hopper Pumped	?					
Sheen present in wate pumping?	rafter 🗀					
Inspected by (Printed)	Westley Wil	liams				
Approved by (Printed)	Robert Derba	s	Approved I	by (Signatu	re)	•
- Entechig y dan Sipromere Pro- andeh her ofer	releaser that t	er hacens sa	ଏକ ଅନ୍ୟୁଷ୍ଟ ଅନ୍ତର୍ଶ ହେଉଛି ଓ ଅନୁସ୍ଥାନ ପ୍ରଥମ ହେଉଛି । ସ	in distributes d	no Rober	£ 2 Derlas



Equipment:	N065407		Vessel/Asset:	Windy City	
Company:	ngram Barge Cor	mpany	Waterway:	Illinois River	/ 301.15
Inspection Date Time:	06/02/2015 13.	50		Heritage Slip	
Load Stalus:	○ Empty ○ Pa	rtial ® Loaded		• .	
boller areas, machinery st	isible areas where c orage areas, wellder live action must be in	hemicels, oils, dry cargi iks and other areas). [F äisted. (Ref: VGP 4.1,4]	ever is more frequent. (2) Locations o, or other materials are stored, mo lef: VGP 4.4.1) (3) if polutions or o l (4) The term "sheen" is to be unde Fact Sheet 3.4.4)	ced and used (including	g, as applicable, cargo holds,
Are Decks Clean?		Any Vio	lations Discovered during Insp	pection or any corre	ective actions required?
lfino, were decks clea	ned? 💟	SYD crew sv	vept product from barge covers		
Is the Water around the free of sheen?	barge 💟				
Was a sample taken?	· □	3			
Voids or Hopper Pumper	d? 🗀				
Sheen present in wat pumping?	erafter				
inspected by (Printed)	Roy Sparrow			ı. ₩	
Approved by (Printed)	Randy Barron		Approved by (Signatu	re) Randell	7. Down. Jr.
Fortesand year Sonnellor (6) Estanologicales	contributes monthly	aroris ha o hastiking	ମଧ୍ୟର ବିଶ୍ୱର ବିଶ୍ୱର ବିଶ୍ୱର ଅଧିକ୍ର ହେଉଛି । ଆଧାର	167	J. Januari J.



Equipment: f	RCI255B			Vessel/Asset	Albert C	
Company: (	Canal Barge	e Company		Walerway:	Illinois River	/ 299
Inspection Date Time; 🥻	6/02/2015	14:00		Location:	Lemont Drydock	
Load Status:	Empty	○Partial ○L	Loaded		·	
boller areas, machinery sto from the barge(s), correcti	sible areas w Frage areas, t ve action mus	rhere chemicals, welldecks and o at be initiated. IR	royage, whichever is more fri , olfs, dry cargo, or other mat ther areas). [Ref: VGP 4.1.1] lef: VGP 4.1.1] (4) The term " oils [Ref VGP Fact Sheet 3.	erible are stored, mx } (3) if politiants or c 'sheen" is to be unde	red and used (including, as constituents of concern as	s applicable, cargo holds, e determined to be orinication
Are Decks Clean?	V		Any Violations Disco	overed during Insp	pection or any correction	ve actions required?
If no were decks clea-	ned?					
is the Water around the I free of sheen?	barge 🗹					
Was a sample taken?						
	4 . *					
Voids of Hopper Pumped	i? 🗍					
Sheen present in wate pumping?	erafier 🗌					
Inspected by (Printed)	Westley V	Villiams				
Approved by (Printed)	Robert Der	bas	Арр	roved by (Signatu		•
Potenius y Les 3 grab ex 1979 diopsis is soled	esticeres es	donatary, soo	avoltem i speciel v i popu	damba as intrakata	no Robert	6 Derlas



Vessel General Permit Compliance

				•		
Equipment:	IN107015	,		Vessel/Asset:	Windy City	
Company:	Ingram B	arge Com	pany	Waterway:	Illinois River	/ 293
Inspection Date Time.	06/02/20	15 17 1	5	Location:	OXBOW	
Load Status:	() Emi	oty O Part	ial <b>®</b> Loaded			
boiler areas, machinery	essible area: storage area ective action :	s where ch is, welldeck must be initi	emicals, oils, dry cargo, is and other areas). [Re ated. [Ref: VGP 4.1.1] (	er is more frequent. (2) Location or other materials are stored, mi f: VGP 4.4.1] (3) If pollutants or 4) The term "sheen" is to be und act Sheet 3.4.4]	xed and used (including constituents of concern	), as applicable, cargo holds,
Are Decks Clean?		<b>2</b>	Any Viola	tions Discovered during Ins	pection or any corre	ective actions required?
If no, were decks of	eaned?					
is the Water around the	ne barge	<b>2</b>				
Was a sample take	en?					
Voids or Hopper Pump	ped?					
Sheen present in w pumping?	rater after					
Inspected by (Printed	d) brandor	baer				
Approved by (Printed	i) Nicholas	Steicher	1	Approved by (Signatu	tologija (en	- 如 Similar

Chemna your Sicardon Pr. Matostas that the barging that ribben inspects an accordance as invested above and contemb author has been enuted for any problem accord.



Equipment	PB2013		Vessel/Asse	t: Eileen C	
Company:	Canal Bar	ge Company	Waterway	y: Illinois River	/ 298
Inspection Date Time:	06/02/201	5 18:26	Location	n: IMT Lemont (NRF)	
Load Stalus:	○Emp	ty 🔾 Partial 🍕	Loaded	·	
boiler steas, machinery st from the barge(s), correct	isible areas orage areas live action m	where chemic; s, welldecks an nust be initiated.	r voyage, whichever is more frequent. (2) Locationals, oils, dry cargo, or other materials are stored, indicates a case of the careas. [Ref: VGP 4.1.1] (3) if pollutants of [Ref: VGP 4.1.1] (4) The term "sheen" is to be unice oils [Ref VGP Fact Sheet 3.4.4]	nixed and used (including, as r constituents of concern are	s applicable, cargo holds, e determined to be priningtin
Are Decks Clean?		<b>교</b>	Any Violations Discovered during In:	spection or any correcth	ve actions required?
If no, were decks clea	ined? {				
is the Water around the free of sheen?	barge (	<b>S</b>			
Was a sample taken	? [				
Voids or Hopper Pumpe	•				
Sheen present in wat pumping?	eraffer (				
Inspected by (Printed)	leahey				
Approved by (Printed)	Shannon	Morlang	Approved by (Signa	ine) Stannah m	c114167
Cathing your Signature for problems noted	i muales t	that the bargare	. Pore that his sected in socialdance an included	500.	Z trany



Equipment:	T13707		Vessel/Asse	et: Eileen C	
Company:	ngram Barge Con	npany	Waterwa	y: Illinois River	/ 298
Inspection Date Time:	06/02/2015 18:	26	Locatio	n: IMT Lemont (NRF)	,
Load Status:	○ Empty ○ Par	tial <b>®</b> Loaded		,	
boller areas, machinery st	sible areas where ci prage areas, wellded ive action must be int	hemicals, oils, dry iks and other area listed. [Ref: VGP+	hichever is mere frequent. (2) Locati cergo, or other materials are stored, s). [Ref: VGP 4.1.1] (3) If pollutants ( 4.1.1] (4) The term "sheen" is to be un VGP Fact Sheef 3.4.4]	mixed and used (including, or constituents of concern	as applicable, cargo holds,
Are Decks Clean?	$oldsymbol{ol}oldsymbol{oldsymbol{oldsymbol{oldsymbol{oldsymbol{ol}ol}}}}}}}}}}}}}}}$	Any	· Violations Discovered during In	spection or any correc	tive actions required?
if no, were decks clea	ned? 🗌				
is the Water around the tree of sheen?	barge ☑				
Was a sample taken?					
Voids or Hopper Pumpe	1?				
Sheen present in wate pumping?	erafter 🔲				
Inspected by (Printed)	leahey			n da Massacra actorio somo	oolineeli oolineerini keelikaa kaa kaa
Approved by (Printed)	Shannon Merlang	)	Approved by (Signa	ature) Accument	wetUalG?
Entering your Signature Pla problems raise	erficates that the is-	rgeis' have been	experient in populations as indicate	d abo	



Vessel General Permit Compliance

Equipment	IN085166		Vessel/Asset	Windy City	
Company	Ingram Bar	ge Company	Waterway:	Illinois River	ı 301.2
Inspection Date Time:	06/02/2015	18.40	Location:	IMT Lemont (Upper	Crane)
Load Status:	O Empty	○ Partial <b>⑥</b> L		, , ,	•
boiler areas, machinery from the barge(s), corre	essible areas v storage areas, ctive action mu	vhere chemicals, welldecks and of stibe initiated. [Re	oyage, whichever is more frequent. (2) Location oils, dry cargo, or other materials are stored, mit her areas). [Ref: VGP 4.1.1] (3) If pollutents or ef: VGP 4.1.1] (4) The term "sheen" is to be undoils [Ref VGP Fact Sheet 3.4.4]	xed and used (including, constituents of concerns	as applicable, cargo holds, tre defermined in he crimination
Are Decks Clean?		]	Any Violations Discovered during Ins	pection or any correc	tive actions required?
If no, were decks of	eaned? [	· on posturoneman dame			
is the Water around th	e barge	]			
Was a sample take	n? [_	]			
Voids or Hopper Pump	t	]			
Sheen present in w pumping?	aterafter [				
Inspected by (Printed	•			ar b t	and the second
Approved by (Printed	) Micholas S	Steichen	Approved by (Signato	ne) 出版和记忆上	M Sticker.

institutivyos. Signassie Pri Populares sustitient an euk insuk near institutes es an professivek institutes de velocitient elegantes des antitutes de velocities de veloci



Vessel General Permit Compliance

Equipment: Il	4117537		VesseVAsset:	Windy City	
Company: In	igram Barge Com	рапу	Walerway:	Illinois River	/ 301 2
Inspection Date Time 0	6/02/2015 18.4	10	Lecation.	IMT Lemont (Upper	Crane)
Load Status:	○ Empty ○ Part	ial 🖲 Loaded		,	,
boiler areas, machinery sto	ible areas where chi rage areas, welldeck re action must be initi	emicals, oils, dry cargo, is and other areas). [Re lated. [Ref: VGP 4.1,1] (	rer is more frequent. (2) Locations or other materials rife stored, nix f: VGP 4.1.1) (3) If poliutants or c 4) The term "sheen" is to be undeact Sheet 3.4.4)	ed and used (including, onstituents of concern :	as applicable, cargo holds,
Are Decks Clean?	<b>&gt;</b>	Any Viola	tions Discovered during Insp	ection or any correc	tive actions required?
lf no, were decks clear	red? []				
is the Water around the b	arge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	? []				
Sheen present in wate pumping?	rafter [7]				
Inspected by (Printed)	brandon baer			i k r	
Approved by (Printed)	Vicholas Steicher	ï	Approved by (Signatus	e) Allerberterz	a) Status

Existing your Signature for an instance that the bettern our sunderest in accommute an indicated above and connective action has been all view for any property order.



Vessel General Permit Compliance

Equipment.	IMT119		Vessel/Asset	Midwest Pride	
Company:	Canal Barge Con	npany	Waterway:	Illinois River	/ 279
Inspection Date Time	06/02/2015 20	:32	Location:	Empty Fleet	
Load Status:	<b>⊚</b> Empty ○ Pa	erlial 🔿 Loaded			
areas and all safely acces holler areas, machinery at	ssible areas where of forage areas, wellde tive action must be in	chemicals, oils, dry cargo cks and other areas). [Ri itiated. [Ref: VGP 4,1,1]	ver is more frequent. (2) Locations, or other materials are stored, mixel: VGP 4.1.1] (3) If pollutants or of (4) The term "sheen" is to be undersect Sheet 3.4.4]	ed and used (including constituents of conce	ig, as applicable, cargo holds In are determined to be originati
Are Decks Clean?	$\Box$	Any Viole	ations Discovered during Insp	ection or any corr	ective actions required?
If no, were decks clea	ined?				
is the Water around the tree of sheen?	barge 💟				
Was a sample laken	? 🗍				
Voids or Hopper Pumpe	d? []				
Sheen present in wal pumping?	terafter				
Inspected by (Printed)	jason franklin				
Approved by (Printed)	Tyshun Griffin		Approved by (Signatu	re)	
E nedto year Signature <sup>os</sup> pauluras auted	N vicigales to tillie t	sigeir shake beer mape	रास्त्री पे व्यापनार्वेषकास स्वयोक्तां क	day S	I Long

The state of the s



Vessel General Permit Compliance

Equipment:	MT119		Via de la constant de	essel/Asset.	Midwest Pride	
Company: (	Canal Barge C	ompany		Waterway:	Illinois River	1 279
Inspection Date Time: 0	6/02/2015	20:32		Location:	Empty Fleet	·
Load Status:	⊕ Empty ○	Partial Ot	naded			
areas and all selely acces boiler areas, machinery sto from the barge(s), correcti	sible areas whe erage areas, we ve action must t	re chemicals Noecks and o le initiated, (A	oyage, whichever is more frequent, oils, dry cargo, or other materials ther sress). [Reft VGP 4.1.1] (3) if ef: VGP 4.1.1] (4) The term "sheer oils [Reft VGP Fact Sheef 3.4.4]	are stored, mb i pollutants or i	ced and used (including constituents of concer	ig, as applicable, cargo holds,
Are Decks Clean?	V		Any Violations Discovere	đ during Insj	pection or any corr	ective actions required?
If no, were decks clear	ned?					
is the Water around the I	barge 🔽					
Was a sample taken?						
Voids or Hopper Pumped	13 🗍					
Sheen present in wate pumping?	erafter 🔲					
Inspected by (Printed)	jason franklii	ì				
Approved by (Printed)	Tyshun Griffi	١	Approve	d by (Signatu	ire)	
Fotering your Signature PSN Leableds cored	indicates that t	₩ Dange-5 r	iave deer lesperied in aprordance	as morested :	attoy 🥰	I Had

VCDEACH VNCE

Vessel General Permit Compliance

parge mapechon Kepott F

Equipment:	ING6536B		Vessel/Asset:	Windy City	
Company	Ingram Barge Com	pany	Waterway:	Illinois River	/ 293
Inspection Date Time:	06/02/2015 20 6	55	Location:	OXBOW	
Load Status:	○ Empty ○ Part	ial 🍥 Loaded			
boiler areas, machinery s from the barge(s), corre	essible areas where ch Horage areas, welldecl Dive action must be init	or per voysge, whichever is m emicals, oils, dry cargo, or othe is and other areas) (Ref: VGP ated [Ref: VGP 4.1.1] (4) The organic oils [Ref VGP Fact Sh	er materials are stored, ma 4.1.1[(3) if politiants or of term "sheen" is to be unde	ced and used (including, ;	63 applicable, cargo holds, tre determined to be orininating
Are Decks Clean?	<b>.</b>	Any Violations	Discovered during Insp	pection or any correct	live actions required?
If no, were decks cle	aned?				·
is the Water around the free of sheen?	e barge				
Was a sample taker	1?				
Voids or Hopper Pump					
Sheen present in wa pumping?	mer aner				
Inspected by (Printed)	brandon baer				
Approved by (Printed)	Nicholas Steicher	1	Approved by (Signatu	rei Michalisz	M Stewar

Interning your Stichature less indicates that the barger is leave bear inspected in enculdance as indicated enough and connective action has been intalled for explorations includ-



Equipment II	√17119			Vessel/Asset	Eileen C	
Company (	anal Barge Con	npany		Waterway:	Illinois River	/ 279
Inspection Date Time 0	6/03/2015 05	48		Location:	Faimer Bobs	
Load Status:		artial O Loaded				
Instructions: (1) This form is to be compareds and all safety access boiler areas, machinery sto from the barge(s), correction the barge(s), with a brocating oils, hydraulic oil	sible areas where i rage areas, welde re action must be in	chomicals, oils, dry cks and other area: titlated, [Ref: VGP 4	cargo, or other mate s). [Ref: VGP 4.1.1] l.1.1] (4) The term "	erials are stored, mixe [ (3) If pollutants or c [sheen" is to be unde	ed and used (including, pastituents of concern a	as applicable, cargo holds,
Are Decks Clean?	Image: section of the	Any	Violations Disco	vered during Insp	ection or any correc	live actions required?
il no, were decks clear	ied?					
is the Water around the tifree of sheen?	oarge					
Was a sample taken?		THE REAL PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE P				
Voids or Hopper Pumped	? [_]					
Sheen present in wate pumping?						
Inspected by (Printed)	perylous crew					
Approved by (Printed)	Curtis Logsdon		Арр	roved by (Signatur	e) (	Jando-
- Enterog your Sajnature Pill. - profilens heted	indicates that the t	sargers) have been	inspected in accord	fance as indicated al		. 009,50



Equipment: I	N107015		Vessel/Asset, Albe	ert C	
Company: I	ngram Barge	Company	Waterway: Illino	ois River	/ 301.15
Inspection Date Time: - (	6/03/2015	08:15	Location: Heri	tage Slip	
Load Status:	○ Empty ○	) Partia! 🎯 L	Loaded		
areas and all safety acces boiler areas, machinery sto from the barge(s), correcti	sible areas wh orage areas, w ve action must	ere chemicals elidecks and o be initisted. [R	royage, whichever is more frequent. (2) Locations to be, oils, dry cargo, or other materials are stored, mixed another areas). [Ref: VGP 4.1.1] (3) If pollutants or constitef: VGP 4.1.1] (4) The term "sheen" is to be understoonis [Ref VGP Fact Sheet 3.4.4]	nd used (including, as applic fuents of concern are deter	able, cargo holds, mined to be priningting
Are Decks Clean?	$oldsymbol{oldsymbol{arphi}}$		Any Violations Discovered during Inspection	on or any corrective act	ions required?
lfina, were decks clea	ned?		n/a		
is the Water around the free of sheen?	barge 🖸				
Was a sample taken?					
Voids or Hopper Pumper	1?				
Sheen present in wate pumping?	erefter $\Box$				
Inspected by (Printed)	westley willi	ams			
Approved by (Printed)	Robert Derb	as	Approved by (Signature)	•	•
Conting your Signature PP	undicales that	the t-arge(s) h	tave been inspected in accordance as it digited abov	Robert L	Derlas



Equipment: I	4G6536B		Vessel/Asset	Albert C	
Company: In	igram Barge Con	npany	Walerway.	Illinois River	/ 301.15
Inspection Date Time: 0	6/03/2015 08:	15	Location:	Heritage Slip	
Load Status:	○ Empty ○ Par	rtial © Loaded			
boiler areas, machinery sto	able areas where cl rage areas, wellded ve action must be ini	hemicals, oils, dry cargo, o iks and other areas). [Ref: itiated. [Ref: VGP 4,1,1] (4	r is more frequent. (2) Locations rether malerials are stored, mix VGP 4.1.1) (3) If pollutants or c) The term "sheen" is to be under the Sheet 3.4.4)	ed and used (including, a constituents of concern a	is applicable, cargo holds, re determined to be acinination
Are Decks Clean?	$\overline{\mathbf{v}}$	Any Violati	ons Discovered during Insp	ection or any correct	ive actions required?
If no, were decks clear	ned? []	n/a			
Is the Water around the l free of sheen?	parge				
Was a sample taken?					
Voids or Hopper Pumped	?				
Sheen present in wate pumping?	rafter				
Inspected by (Printed)	westley williams				
Approved by (Printed)	Robert Derbas		Approved by (Signatu		•
- Enter ng your Sig lettere Pal profiler is Neted	ndicates frantise by	argers, bave heer invigent	ed in activider.ce as (ಚರೆ caled) a	in Robert	- L Derlas



Vessel General Permit Compliance

Equipment	1 13970				Vessel/Asset	Midwest Pride		
Company:	Jogram Ba	arge Con	ipany		Waterway.	Illinois River		/ 277
Inspection Date Time.	06/03/201	15 09 4	15		Location:	Mobil Cake Upp	)et	
Load Status:	OEmp	oty 🔾 Par	tial <b>©</b> Loaded					
Instructions: (1) This form is to be considered and all safety accidences, machinery from the barge(s), correlabricating oils, hydraulic	essible areas storage area ctive action r	s where cl s, welldec must be int	iemicals, cils, dry c ks and other areas! lated. (Ref; VGP 4,	argo, or other materi }={Ref: VGP 4.1.1} ( 1.1} (4) The term "sh	als are stored, mi 3) If poliulants or reen" is to be und	xed and used (include constituents of cond	ding, as applicable, cern are determined	, cargo holds, d to be originat
Are Decks Clean?		( <u>?</u> )	Any	Violations Discove	erec during Ins	pection or any co	rrective actions	required?
If no, were decks cle	eaned?							
is the Water around th	e barge	<b>7</b>						
Was a sample take	n?							
Voids or Hopper Pump	ed?							
Sheen present in w pumping?								
Inspected by (Printed	f) james v	vexelbarç	}					
Approved by (Printed	) Tommy	Walter		Аррге	oved by (Signat	ure)		
Differing your Pignative processing indeed	Phaliphto Hek	that the is	Artan Kritana harar	spected mistabilds	z w as maigsled	arc.	ì	i

VGPEXCHANGE

Equipment	CBY227			Vessel/Asset	Aggre-C	
Company:	Canal Barg	je Company		Waterway.	Illinois River	7 329 9
Inspection Date Time	06/03/2015	10 17		Location:	WALSH FLEET	
Load Status:	() Empt	y 🔾 Partie! 🌘	Loaded			
areas and all safely acco boiler areas, machinery :	essible arees storage areas, ctive action m	where chemical , welldecks and ust be initiated. [	s, oits, dry cargo, or othe other areas). [Ref: VGP Ref: VGP 4.1.1] (4) The	r materials are stored, mix 4.1.1] (3) It pollutants or d term "sheen" is to be unde	ed and used (including, a constituents of concern a	accessible deck end cargo as applicable, cargo holds, are determined to be originatin on of oil or grease, including
Are Decks Clean?		2	Any Violations	Discovered during Insp	section or any correc	tive actions required?
If no, were decks cle	eaned? [	]				
is the Water around the free of sheen? Was a sample take	L:	<b>2</b>				
Voids or Hopper Pump	ed? (					
Sheen present in w pumping?	aterafter [					
Inspected by (Printed	) LLeffler					
Approved by (Printed	) Brad Bon	d		Approved by (Signati	'	<u></u>
Eatenny your Signature : Urobismo noted	Pluindicates i	ent the bargers	have been insperien in	acculdance as edicaled (	our Brown	& Bond



Equipment:	IMT 123		Versel/Asset	Aggie-C	
Company:	Canal Barge Com	трапу	Waterway:	Illinois River	7 329.9
Inspection Date Time	06/03/2015 10	17	Location:	WALSH FLEET	
Load Status:	○ Empty ○ Pa	ufial 🏵 Loaded			
bolier areas, machinery s	ssible areas, where o lorage areas, wellder tive action must be in	chemicals, oils, dry cargo cks and other areas) [Ri itiated. [Ref: VGP 4,1,1]	rer is more frequent. (2) Locations or other materials are stored, mixelf: VGP 4.1.1] (3) If pollutants or c (4) The term "sheen" is to be undeact Sheet 3.4.4]	ed and used (including, as onstituents of concern ar	s applicable, cargo hoids, is defermined to be orinication
Are Decks Clean?	( <u>~</u> )	Any Viole	ations Discovered during Insp	ection or any correcti	ve actions required?
If no, were decks cle	aned?				
Is the Water around the free of sheen?	barge 🔀				
Was a sample taken	? 🗀				
Voids or Hopper Pumpe	<b>₫?</b> []				
Sheen present in wa pumping?	ter after				
Inspected by (Printed)	LLeffler				
Approved by (Printed)	Brad Bond		Approved by (Signatur	'e)	<i></i>
Entering your Signature Pi	D reducates that the b	raige sybave fleen mape	cten in accordance as indicated a	now Brook	Bond

Equipment:	RC(256B		Vessel/Asset	Aggie-C	
Company:	Canal Barge Com	ipany	Waterway:	Illinois River	7 329.9
Inspection Date Time	06/03/2015 10	:17	Location:	WALSH FLEET	
Load Status;	○ Empty ○ Fa	rtial 🕲 Loaded			
areas and all salely acce boiler areas, machinery s	ssible areas where o torage areas, wellded tive action must be in	themicals, oils, dry cargo, cks and other areas). [Re kialed. [Ref; VGP 4.1.1]	rer is more frequent. (2) Locations or other materials are stored, more frequent. (4) Follutants or (4) The term "sheen" is to be undeact Sheet 3.4.4)	ed and used (including, a constituents of concern ar	s applicable, cargo holds. 6 determined to be originatin
Are Decks Clean?	Ø	Any Viola	itions Discovered during Insp	ection or any correcti	ve actions required?
If no, were decks cle	aned?				
Is the Water around the free of sheen?	e barge				
Was e şəmple taker	? []				
Voids or Hopper Pumpe	ed?				
Sheen present in wa pumping?	nterafter				
Inspected by (Printed)	LLeffler				
Approved by (Printed)	Brac Bond		Approved by (Signatu	ie)	
Entering your Cigambire P problems well'd	To mit 2846 Hit Hat the B	raiges traveles colle	กในอากาลออกเปลกอย ลกากอักษาวิธีย	or Brod	Bond



Vessel General Permit Compliance

Equipment:	RCI255B		Vessel/Asset:	Windy City	
Company.	Canal Barge Com	pany	Waterway:	Minois River	7 296 6
Inspection Date Time.	06/03/2015 12	35	Location	WOEXO	
Load Status:	○Empty ○Pa	rtial 🌘 Loaded			
areas and all safely according a boiler areas, machinery s	esaibie areas where o storage areas, welder the action must be the	hemicals, oils, dry carr cks and other areas) [ iliated. (Ref: VGP 4.1.*	never is more frequent (2) Location: ge, or other materials are stored, mis Ref: VGP 4.1.1) (3) if poliutants or o [] (4) The term "sheen" is to be under P Fact Sheet 3.4.4]	red and used (including, constituents of concern	as applicable, cargo holds, are determined to be originating
Are Decks Clean?	Ø	Any Vio	plations Discovered during Insp	ection or any correc	ctive actions required?
fino, were decks cle	aned?	Manual Processing Control of the Con			
is the Water around the tree of sheen?	e barge				
Was a sample taker	17 🗌				
	Fermi				
Voids or Hopper Pump					
Sheen present in wa pumping?	erecauet []	And the second second			
Inspected by (Printed	) Justin Grooms				
Approved by (Printed)	Paul Roman		Approved by (Signatu	ne) Apolis	nurhaman
Firemo your Rightitus F you hous colod	The sexistes that the c	argues fear been his	perted in accordance an indicates :	stra.	

VGPEXCHANGE

Vessel General Permit Compliance

Equipment	ID075177		Vess	el/Asset	Midwest Pride	
Company:	Ingram Ba	arge Company	14	/alerway:	Illinois River	± 277
Inspection Date Time	06/03/201	5 15 00	L	.ocation.	Mobil Cake Spout	
Load Status;	○€mp	ity O Partial ® t	.oaded			
areas and all safely accomboiler areas, machinery the formation before the barge (s), corre	essible areas storage areas ctive action n	: where chemicals s, welldecks and c nust be initiated. [F	royage, whichever is more frequent. (2 , oils, dry cargo, or other materials are: ither areas). [Ref: VGP 4.1.1]. (3) If poli lef: VGP 4.1.1]. (4) The term "sheen" is oils. [Ref VGP Fact Sheef 3.4.4].	stored, mo lutants or	xed and used (including, as constituents of concern are	applicable, cargo holds, determined to be originating
Are Decks Clean?		[7]	Any Violations Discovered di	enl gninu	pection or any correctiv	e actions required?
if no, were decks cla	aned?					
Is the Water around th free of sheen?	e barge	<b>3</b>				
Was a sample take	n?	n				
Voids or Hopper Pump	ed?					
Sheen present in wa pumping?	ater after					
Inspected by (Printed	) james w	rexelberg				
Approved by (Printed)	) Tommy I	Walter	Approved by	(Signate	ire)	
Cetoring your Sigernure ( proxiemo i oled	Moindicales :	that the nargers of	taur heed inspected in accordance as	esdecated	atr.	

VGPEXCHANGE

Equipment: [	M <b>[1</b> 19	Vessel/Asset: Windy City
Company: (	Canal Barge Com	any Waterway: Illinois River / 296
Inspection Date Time: (	16/03/2015 17:	5 Location: IMT MMH (MMH)
Load Status;	<b>⑥</b> Empty ○ Par	• ,
boiler areas, machinery sto from the berge(s), correcti	sible areas where cr irage areas, wellded we action must be init	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safely accessible deck and cargo enticals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, as and other areas). [Ref: VGP 4.1.1] (3) if pollutants or constituents of concern are determined to be originating ated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	[2]	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clea	ned? []	
is the Water around the lifee of sheen?	oarge ☑	
Was a sample taken?		
Voids or Hopper Pumped	ış [ <u>]</u>	
Sheen present in wate pumping?	erafter []	
Inspected by (Printed)	eric hanson	
Approved by (Printed)	David Cultinan	Approved by (Signature)
Entering your Signature P87 problems noted	ardicales that the ba	general Never been inspected in accordance as indicated abov Delegan Level Level Contract

Equipment: 1	N075177		Vessel/Asset:	Midwest Pride	
Company: i	ngram Barg	e Company	Waterway:	Illinois River	1 279
Inspection Date Time: 0	6/03/2015	19:55	Location:	Farmer Bobs	
Load Status:	○ Empty	○Partial ® L	.oaded		
boller areas, machinery sto from the barge(s), correcti	sibe areas w irage areas, v ve action mus	nere chemicals. Nelidecks and b it be initiated. [R	oyage, whichever is more frequent. (2) Location oils, dry cargo, or other materials are stored, mighter areas? (Ref: VGP 4.1.1) (3) if pollutants or ef: VGP 4.1.1) (4) The term "sheen" is to be undials [Ref VGP Fact Sheet 3.4.4]	xed and used (including, constituents of concern	, as applicable, cargo holds,
Are Decks Clean?	( <u>.</u> )		Any Violations Discovered during Ins	pection or any corre	ctive actions required?
lf no, were decks clea.	ned? []				.,
is the Water around the i	barge ☑				
Was a sample taken?					
Voids or Hopper Pumped	ı? []				
Sheen present in water pumping?	er after	Westpool or and a Marie			
Inspected by (Printed)	jason frank	lin			
Approved by (Printed)	Tyshun Gri	ffur	Approved by (Signatu	ire)	
Cothrologiya ir Gignebilik P3: protionis nalad	northeres to p	file bargo e in	aur been respected in accordance as indicated i	that CAT	T. Lange



Vessel General Permit Compliance

Equipment. (	CBY230			Vessel/Asset:	Eileen C	
Company; (	Canal Barge	Company		Waterway	Illinois River	, 298
Inspection Date Time (	06/03/2015	21.49		Location:	IMT Lemont (NRF)	
Load Status:	○ Empty (	) Partial 🕲 L	oaded		,	
boiler stess, machinery sta from the barge(s), correcti	sible aleas with DIBGE aleas, with the action must	ere chemicals, eldecks and o be initiated. [R	oyage, whichever is more freq. oils, dry cargo, or other materisther areas). [Ref: VGP 4.1.1] (et: VGP 4.1.1] (4) The term 'shoils [Ref VGP Fact Sheet 3.4.4	als erstored, mb 3) If poliutants or d seen " is to be unde	ced and used (including, a	s applicable, cargo holds,
Are Decks Clean?	V	-	Any Violations Discove	ered during Insp	ection or any correcti	ve actions required?
lfino, were decks cles	ned?					
is the Water around the ifree of sheen?	barge 🗸					
Was a sample taken?						
Voids or Hopper Pumped	17 📋	**************************************				
Sheen present in wate pumping?	arañer []					
Inspected by (Printed)	James Cunt	oigham				
Approved by (Printed)	Curtis Logso	lon	Аррго	ved by (Signatu	re)	1-01
Fotoring your Signature Psi	nolicates that	the barge(s) h	ave taen inspected in accorda:	Tão as indicateo a	to Cuih	132120-



problems noted

Equipment: (	BY246		Vessel/Asset	Eileen C	
Company. (	Canal Barge Com	pany	Waterway:	Illinois River	7 298
Inspection Date Time: 0	6/03/2015 21	49	Location:	IMT Lemont (NRF)	
Load Status:	○Empty ○Par	tial 🏵 Loaded			
boiler areas, machinery sto	sible areas where ch rage areas, wellded ve action must be int	hemicals, oils, dry cargo, iks and other areas). {Re tiated, {Ref: VGP 4,1,1} /	er is more frequent. (2) Locations or other materials are stored, max f: VGP 4.1.1) (3) If pollutants or or 4) The term "sheen" is to be under act Sheet 3.4.4)	ed and used (including, as anathuents of concern are	applicable, cargo holds,
Are Decks Clean?	v	Any Viola	tions Discovered during Inspe	ection or any correctiv	e actions required?
If no, were decks clear	ned?				
is the Water around the I free of sheen?	oarge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	? 📋				
Sheen present in wate pumping?	er after				
Inspected by (Printed)	James Cunnigha	ım			
Approved by (Printed)	Curtis Logsdon		Approved by (Signatur	e) ( -1	2-1
Emering your Signature his	indicates that the ba	argers have been baper	ted in accerdance as indicated at	mey Childe	willes



Vessel General Permit Compliance

Equipment	RCI255B		Ves	sel/Asset	Eileen C	
Company	Canal Barge	Company	1	Waterway:	Illinois River	/ 298
Inspection Date Time:	06/03/2015	21 49		Location:	INT Lemont (NRF)	
Load Status:	○ Empty (	O Partiat ® L	oaded			
ereas and all safely acc boiler areas, machinery from the barge(s), corre	casible areas w storage areas, v ective action mus	here chemicals, velldecks and ol t be initialed. [Ri	oyage, whichever is more frequent. ( oils, dry cargo, or other materials are ther areas). [Ref: VGP 4.1.1] (3) If piet VGP 4.1.1] (4) The term "sheen" is like! VGP Fact Sheet 3.4.4]	e stered, mò ollutants er c	red and used (including, as constituents of concern are	applicable, cargo holds, determined to be originating
Are Decks Clean?	[J		Any Violations Discovered (	turing Inst	ection or any correctiv	re actions required?
if no, were decks cli	eaned? []					
is the Water around th	e barge					
Was a sample take	n? 🗀					
Voids or Hopper Punit	ed?					
Sheen present in w pumping?	eler after 📋					
Inspected by (Printed	t) James Cui	nnigham				
Approved by (Printed	) Curtis Logs	don	Approved t	oy (Signatu	ere)	Jandon-

Fineling your Oppositive PR indivisies that the barge is little been respected in accordance as indicated above or otherwise relactions.

Vessel General Permit Compliance

Equipment:	ING6538B			VesseVAsset:	Midwest Pride	
Company:	Ingram Barg	e Company		Waterway:	Illinois River	1 277
Inspection Date Time.	06/04/2015	10.15		Location:	Mobil Coke Spout	
Load Status:	C Empty (	⊃Partial <b>®</b> L	oaded			
<ul> <li>areas and all safely accident</li> <li>boler areas, machinery</li> <li>from the barge(s), corre</li> </ul>	cessible areas wi storage areas, v ective action mus	nere chemicals, velldecks and o' I be initiated [R	-vils, dry cargo, or other r ther areas) {Ref; VGP 4.	nateriais are stored, mo 1.1] (3) It pollutants or i m "sheen" is to be undi	ked and used (including, constituents of concern	r accessible deck and cargo as applicable, cargo holds, are determined to be originat on of oil or grease, including
Are Decks Clean?	[2]		Any Violations Dis	scovered during Insi	pection or any correc	tive actions required?
If no, were decks cl	eaned? []					
is the Water around thee of sheen?	ne barge 🗹					
Was a sample lake	en?					
Voids or Hopper Pump	oed?					
Sheen present in w pumping?	vater after []					
Inspected by (Printer	d) patrick eric	kson				
Approved by (Printed	)) Tonimy Wa	ilte:		approved by (Signal)	ire)	

Smidning your Dipolature PPF is charles that the harger's that we have inspected in accordance as a divised above problems noted.



Equipment:	N107033			Vesse	eW.eset:	Albert C		
Company:	ngram Barge	Company		W	aterway:	Illinois River		/ 293
Inspection Date Time (	06/04/2015	10 20		L	ocation:	OXBOW .		
Load Status:	○ Empty ○	) Partial 🏵 L	oaded					
Instructions: (1) This form is to be come areas and all safety accessibility areas, machinery strom the barge(s), correct lubricating oils, hydraulic of	sible areas wh orage areas, w ive action must	ere chemicais, elidecks and of be initiated. [Ri	, oils, dry cargo, or i ther areas) [Ref: \ .ef: VGP 4.1.1] (4) `	other materials are s /GP 4.1.1] (3) If poli The term "sheen" is:	stored, mi utents or	xed and used (inclu- constituents of con-	ding, as applicabl cern are determin	le, cargo holds, red to be originating
Are Decks Clean?	<b>☑</b>		Any Violatio	ns Discovered du	iring Ins	pection or any co	orrective action	is required?
If no, were decks clea	ned?							
Is the Water around the free of sheen?	barge 🗹							
Was a sample taken	? [_]							
Voids or Hopper Pumpe	d? []							
Sheen present in wa pumpin <b>g?</b>	terafter []							
Inspected by (Printed)	Peter Kosi	<b>K</b>						
Approved by (Printed)	Peter Kosił	(		Approved by	y (Signal	kire)	,	
t mering your Signature P protiems nuted	禁いわからお(es tha	t the dargeis . I	have been inspecie	d in accordance as	maicaten	som fitte	r Shil	£ for any

Vessel General Permit Compliance

Equipment: I	NG6538B		Ve	ssel/Asset:	Midwest Pride	
Company: li	ngram Barge	Сотрапу		Walerway;	Illinois River	ı 277
Inspection Date Time (	6/04/2015	10:25		Location:	Mobil Coke Upper	
Load Status:	○ Empty ○	Partial © Lo	paded			
Breas and all safety acces boiler areas, machinery sto from the barge(s), correcti	sible areas who stage areas, wo we action must	ere chemicals, i elidecks and oth be intilated. [Re	yage, whichever is more frequent. offs. dry cargo, or other materials a her areas) [Ref: VGP 4.1.1] (3) ff ft: VGP 4.1.1] (4) The term "sheen" ils [Ref VGP Fact Sheet 1.4.4]	re stored, mb pollutants or:	xed and used (including, as constituents of concern are	applicable, cargo holds, edetermined to be originating
Are Decks Clean?	V	i	Any Violations Discovered	i during ins	pection or any correctly	re actions required?
If no, were decks clea	ned?					,
is the Water around the i	barge 🖸					
Was a sample taken?						
Voids or Hopper Pumped	ı? 🗇	A CONTRACTOR OF THE CONTRACTOR				
Sheen present in water pumping?						
Inspected by (Printed)	patrick erick	.son				
Approved by (Printed)	Tommy Wal	161	Approved	by (Signati	nte)	

Entering your Signature Phondwidths that the barge is that either in spected in appointment as indicated above problems noted.



Equipment: II	1107033			Vessel/Asse	t: Albert C		
Company: Ir	igram Barge	Company		Waterwa	y: III.nois River		/ 299 4
Inspection Date Time: 0	6/04/2015	11 15		Location	n SYS		
Load Stalus:	C) Empty C	/Partial 🖲 Li	oaded				
instructions: (1) This form is to be complareas and all safely access boiler areas, machinery sto from the barge(s), correctional bardening oils, hydraulic oil	sible areas who rage areas, wo re action must i	ere chemicals, didecks and of se initiated. [Re	oils, dry cargo, or oth ther ereas). [Ref: VGI of: VGP 4.1.1] (4) The	er materials are stored, i P 4.1.1] (3) If poliufants of term "sheen" is to be ur	nixed and used (inc i constituents of ci	cluding, as applicab encero are determin	ile, cargo holds, ned to be originatin
Are Decks Clean?	V	and a special control of the special control	Any Violations	Discovered during In	spection of any	corrective action	ıs required?
if no, were decks clear	ned?						
is the Water around the t tree of sheen?	oarge ☑						
Was a sample taken?							
Voids or Hopper Pumped	i? []						
Sheen prosent in water pumping?	erafter []						
Inspected by (Printed)	Peter Kosik						
Approved by (Printed)	Peter Kasik			Approved by (Signa	ature)	_	
Emering your Signature Pel- problems noted	nocates that	Containers h	aave liber vibisalied v	i geopendance as inducate	a sizor	to the	S for any

Vessel General Permit Compliance

Equipment:	IN075177		VesseVAsset.	Midwest Pride	
Company:	ingram Barg	e Company	Waterway.	Illinois River	/ 278
Inspection Date Time	06/04/2015	11:40	Location	IMT Chan (Crane)	
Load Status:	○ Empty (	Partial 🖲	Loaded		
areas and all safely acc boiler areas, machinery from the barge(s), corre	essible areas wl storage areas, v ective action mus	here chemicals velldecks and t be initiated. [i	voyage, whichever is more frequent. (2) Location s, oils, dry cargo, or other materials are stored, midther areas.) [Ref: VGP 4.1.1] (3) If pollutents or Ref: VGP 4.1.1] (4) The term "sneen" is to be und to oils [Ref VGP Fact Sheet 3.4.4]	xed and used (including, as constituents of concern are	applicable, cargo holds, determined to be originatin
Are Decks Clean?		**	Any Violations Discovered during Ins	pection or any corrective	e actions required?
lfino, were decks ci	eaned? []				
Is the Water around th	e barge 🗵				
Was a sample take	n? 🗍	e bereigner in the second of			
Voids or Hopper Pump	oed? [1	TO DESCRIPTION OF THE PROPERTY			
Sheen present in w pumping?	rater after	THE REAL PROPERTY OF THE PERSON OF THE PERSO			
Inspected by (Printed	)) patrick eric	kson			
Approved by (Printed	) Tommy Wa	elter	Approved by (Signati	ure)	
C'a la cia a la companya de la comp	Chi - A - A - A			1 · 1 · 1 · 1 · 1	A STATE OF THE STA

Entering your Signature PET indicates that the bargers' have been inspected in accordance as indicated accordance white:



Vessel General Permit Compliance

Equipment:	N107033		Vessel/Asset	Windy City	
Company: I	ngram Barge	Company	Waterway:	Illinois River	/ 299.4
Inspection Date Time;	06/04/2015	12:25	Location:	IMT Lemont (Clean)	
Load Status:	O Empty (	) Partial ® Lo	paded		
areas and all safely acces boiler areas, machinery st from the barge(s), correct	sible areas wi orage areas, w ive action must	iere chemicals, velidecks and otl be initiated. [Re	ryage, whichever is more frequent. (2) Location oils, dry cargo, or other materials are stored, mither areas). [Ref: VGP 4.1.1] (3) if pollutants or of: VGP 4.1.1] (4) The term "sheen" is to be und lils [Ref VGP Fact Sheet 3.4.4]	xed and used (including, a constituents of concern as	s applicable, cargo holds, re determined to be originali
Are Decks Clean?	Ŋ	•	Any Violations Discovered during Ins	pection or any correct	ive actions required?
if no, were decks dea	ined? []				
Is the Water around the free of sheen?	barge 🗹	The state of the s			
Was a sample taken	7 🗆				
Voids or Hopper Pumpe	d? []				
Sheen present in wat pumping?	erafter 🗌	Armony dry and war			
Inspected by (Printed)	justin gradi	ทร			
Approved by (Printed)	Paul Roma	n	Approved by (Signat	ure) Apalin	unhamais

Enter by your S-gosture PP and , size that the transpose flows been respected in accordance as indicated whose problems incled



Equipment:	114107015			Vessel/Asset:	Windy City		
Company:	Ingram Barge	Company		Waterway:	Illinois River	/ 301.2	
Inspection Date Time	06/04/2015	13.25		Location	IMT Lemont (Up	pper Crane)	
Load Status:	() Empty (	) Paniai 🏵 L	oaded				
areas and all safely acce boiler areas, machinery si from the barge(s), correc	saible areas wh lorage areas, w tive action must	ere chemicals, elidecks and o be initiated. [R	, olls, dry cargo, or other m ther areas). [Ref: VGP 4.1	atensis are stored, mb .1] (3) if poliulants or d n "sheen" is to be unde	ked and used (inclu- constituents of con-	Safety accessible deck and corg ding, as applicable, cargo hoids cern are determined to be origin, ntration of oil or grease, includin	etir
Are Decks Clean?	ভ		Any Violations Dis	covered during Inst	pection or any co	prrective actions required?	
if no were decks clea	ened?	, (1984)					
is the Water around the free of sheen?	barge [☑	esementantification — Arthur St. de Control					
Was a sample taken	?						
Voids or Hopper Pumpe							
Sheen present in wa pumping?	ter atter						
Inspected by (Printed)	justin groon	15					
Approved by (Printed)	Paul Romar	i	A	pproved by (Signatu	ire) Apo	linunheman	,
Røserieg your Olypaniste P crostients a bled	r. etrajes mar	Note that grant sold	the fitting of a fell to sta	udanče as militaleči.	ate,		



£4mb.usur	HC00090D			Vesserasset	windy Ony	
Company.	ngram Barg	е Сотряну		Waterway.	Illinois River	/ 301 2
Inspection Date Time	06/04/2015	13 50		Lacation.	IMT Lemont (Up	per Crane)
Load Status:	() Empty (	® teine4 ○	Loaded			
areas and all safely acces boiler areas, machinery st	isible areas wi prage areas, v ive action mus	here chemical velidecks and I be initiated. (	s, oils, dry carge, er e other areas). [Ref: V [Ref: VGP 4.1.1] (4) 1	ither materials are stored, mix GP 4.1.1] (3) if pollutants or c he term "sheen" is to be unde	ked and used (includ constituents of conc	ifely accessible deck and cargo ing, as applicable, cergo holds, ern are determined to be crigination tration of oil or grease, including
Are Decks Clean?	abla		Any Violation	as Discovered during last	ection or any cor	rective actions required?
If no, were decks clea	aned?					
Is the Water around the free of sheen?	barge 🗹					
Was a sample taken	? 🗆					
Voids or Hopper Pumpe	- ,	İ				
Sheen present in wat primping?	eraner []					
Inspected by (Printed)	justin gradi	าเร				
Approved by (Printed)	Paul Roma	វា		Approved by (Signatu	ire) Apol	inunhaman
- Emering your Right, 1964) - problems index	Vindostes fra	t sio turcos:	Eleven need an expection	in ac lordance as indicated a	sto.	



Vessel General Permit Compliance

Equipment:	T 13831	VesseVAsset	: Midwest Pride
Company.	Ingram Barge Com	oany Waterway	: Illinois River / 277
Inspection Date Time	06/04/2015 13.5	) Location	Mobil Coke Upper
Load Status:	○ Empty ○ Part	al (®) Loaded	
briess and all safely acc boiler areas, machinery from the barge(s), corre	essible areas where ch storage areas, welldeck ctive action must be initi	or per voyage, whichever is more frequent. (2) Location micals, oils, dry cargo, or other materials are stored, mis and other areas). [Ref: VGP 4.1.1] (3) if pollutants or tited. [Ref: VGP 4.1.4] (4) The term "sheen" is to be unarganic oils [Ref VGP Fact Sheet 3.4.4].	ixed and used (including, as applicable, cargo halds,
Are Decks Clean?	[ <del>]</del>	Any Violations Discovered during ins	spection or any corrective actions required?
if no, were decks cl	eaned?		
Is the Water around th	. ( <del>A</del> )		
Was a sample take	n? 🗔		
Voids or Hopper Pump Sheen present in w pumping? Inspected by (Printed	aterafler 🔲		
Approved by (Printed		Approved by (Signal	ure)
4 E	,	speroson of foligina	

Entring your Signature PPC indicates that the barge, so have been inspected in accordance as anothered above problems noted.



Equipment:	IN075026		Vessel/Asset	Albert C	
Company:	Ingram Barge Co	empany	Waterway:	Illinois River	/ 293
Inspection Date Time:	06/04/2015 14	V:10	Location:	WORKD	
Load Status:	○ Emply ○ Pa	artial © Loaded			
areas and all sately acces belier areas, machinery st	isible areas where i orage areas, welkie ive action must be in	chemicals, oils, dry ca ecks and other ereas) nitiated. [Ref: VGP 4.1	chever is more frequent. (2) Locations rgo, or other materials are slored, more [Ref: VGP 4.1.1] (3) If pollutants or c [.4] (4) The term "sheen" is to be under SP Fact Sheet 3.4.4]	ebd and used (including, as applicantification of concern are dete	icable, cargo holds,
Are Decks Clean?	<b>(∑</b> )	Any V	fiolations Discovered during Insp	ection or any corrective ac	tions required?
If no, were decks clea	ined? []	The same and the s			
is the Water around the free of sheen?	barge ☑				
Was a sample taker."	2 🗆				
Voids or Hopper Pumpe	d? []	11. A			
Sheen present in wat pumping?	erafter 🗍				
inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kusik		Approved by (Signalu	re)	
hmerny yan Bijamara Pi Guidens i ored	Ciacidates that the t	bargeis Bave been n	ispected in appropriation as monyter a	· fiter file	£ for any



Equipment i	MT119		1	vessel/Asset.	Albert C		
Company	Danat Barge Con	npany		Waterway:	Illinois River		/ 299 4
Inspection Date Time (	06/04/2015 15	45		Location:	SYS		
Load Status:		irtial () Loaded					
instructions: (1) This form is to be compareds and all safety accessionler areas, machinery statements to bricating oils, hydraulic o	sible areas where corage areas wellde arage areas wellde are action must be in	chemicals, cils, dry cks and other area itlated [Ref: VGP -	cargo, or other materials s) [Ret: VGP 4.1.1] (3) 4.1.1] (4) The term "shee	s are stored, mo It pollutents or	xed and used (incl constituents of cor	uding, as applicabl ncern are determin	e, cargo holds, ed to be ocioloatio
Are Decks Clean?	v	Any	Violations Discover	ea during Ins	pection or any c	orrective action	s required?
If no, were decks clea	ned?						
Is the Water around the free of sheen?	barge 🔽						
Was a sample takent							
Voids or Hopper Pumper	d? []						
Sheen present in wat pumping?	1						
Inspected by (Printed)	Peter Kosik						
Approved by (Printed)	Peter Kosik		Approve	ed by (Signati	ure)		
i mervio yeur li genirari Pe Listi inscholed	v odplatek (hattire t	Turgeva (kase) wer	This este Similar childens	ម ស្រាស់ស្រាស់	res fits	r fhe .	£ ran say

Equipment	HM 1 74 /			Vessel/Asset	Mary C	
Company.	Canal Bar	ge Compan	у	Waterway:	Illinois River	± 278
nspection Date Time	06/04/201	5 15 50		Location:	IMT Chan (Crane)	
Load Status:	○ Emp	ly O Partial	<b>⊕</b> Loaded			
boiler areas, machinery st	ssible areas lorage areas live action m	where chemia , welldecks a just be initiated	cals, oils, dry cargo, or o nd other areas) [Ref: V 3. [Ref: VGP 4.1.1] (4) T	more frequent. (2) Locations ther materials are stored, mix GP 4.1.1] (3) if pollutants or che term "sheen" is to be undesheet 3.4.4]	ed and used (including, a	es applicable, cargo holds,
Are Decks Clean?	[	ব	Any Violation	s Discovered during Insp	pection or any correct	ive actions required?
if no, were decks clea	aned? (					
is the Water around the free of sheen?	barge [	2				
Was a sample taken'	? [					
Voids or Hopper Pumpe	d? [					
Sheen present in wat pumping?	erafter [					
Inspected by (Printed)	BARNAF	RD/KUNTZA	WEAVER			
Approved by (Printed)	Robert S	mith		Approved by (Signatu	re)	
Estering your Signature Pa croomine noted	។ ១៧០៩៩៩	hai die barger	is thave their aispecial	n korvodence av miroded a	" Hobert la	Suit of the say

Equipment:	IN075026		Vessel/Asset: Windy City	
Company:	lagram Barg	e Company	Waterway, Illinois River	/ 299.4
Inspection Date Time:	06/04/2015	18:35	Location: SYS	
Load Status:	○ Empty	O Partial 🏵 L	oaded	
<ul> <li>Breas and all sately according areas, machinery sitem the barge(s), correct</li> </ul>	ssible areas w lorage areas, live action mus	here chemicals, welldecks and of stibe initiated. [Re	byage, whichever is more frequent. (2) Lacations to be inspected. Safety office, only cargo, or other materials are stored, mixed and used (including, a her areas). [Ref: VGP 4.1.1] (3) if pollutents or constituents of concern as ef: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentrational office (VGP Fact Sheet 3.4.4).	s applicable, cargo holds, re determined to be pripinating
Are Decks Clean?	[Z		Any Violations Discovered Juring Inspection or any correct	ive actions required?
If no, were decks cle	ared? [			
is the Water around the	haran			
free of sheen?	Daige 2			
Was a sample laken	?			
Voids of Hopper Pumpe	d? [	1		
Sheen presentin wa pumping?	terafter C			
Inspected by (Printed)	eric hanso	n		
Approved by (Printed)			Approved by (Signature)	
Estering your Signature F problems incled	la northies dia	athe haiçe s. v.	and these inspected to any or taking asyndronted above A facility	Rullman



Vessel General Permit Compliance

Vessel/Asset: Mary C

T13590

Equipment:

Company:	Ingram Barge	: Company		Waterway:	Hinois River	1 278
nspection Date Time	06/04/2015	20 00		Location	Rapps Fleet	
Load Status:	○Empty (	Partial ® Lo	oaded			
areas and all sately acces boiler areas, machinery si from the barge(s), correc	ssible areas wh lorage areas, w live action must	ere chemicals, elidecks and off be initiated. [Re	oyage, whichever is more frequents, dry cargo, or other maters her areas). [Ref: VGP 4.1.1] (at: VGP 4.1.1] (at: VGP 4.1.1] (but the firm "shifts [Ref VGP Fact Sheet 3.4.4)	els are stored, mb 3) if pollutents or a seen" is to be und	ked and used (including constituents of conce	ig, as applicable, cargo holds, on are determined to be originating
Are Decks Clean?	$\Box$		Any Violations Discove	ered during Insj	pection or any corr	ective actions required?
If no, were decks clea	aned?					
is the Water around the free of sheen?	barge 💟	- Alexandry - Alexandry				
Was a sample taken	? []					
Voids or Hopper Pumpe	:d? []	THE PARTY OF THE P				
Sheen present in wa pumping?	ler after					
Inspected by (Printed)						
Approved by (Frinted)	Carl Aldrich		Appro	oved by (Signati	ire) —	2/ Pld

Entering your figurature PIC hid defea that the barger's have been inspected to accordance as indicated above and corrective when has been intated for any problems acted.



Equipment	CBX5034	7		VeseeliAsset	Midwest Pride	
Company:	Canal Ba	arge Comp	pany	Waterway:	Illinois River	1 278
Inspection Date Time	06/04/20	15 20 8	56	Location:	Rapps Fleet	
Load Status:	○Em	pty O Pan	lial <b>©</b> Loaded			
boiler areas, machinery from the barge(s), corre	storage area storage area ctive action	as where ch as wellded must be init	iemicais, olis, dry cargo, o ks and other areas). IRef:	is more frequent. (2) Locations other materials are stored, mix VGP 4.1.1] (3) If pollutents or or the term "sheen" is to be under \$1.4.4]	ed and used (including,	as applicable, cargo holds,
Are Decks Clean?		<b>?</b>	Any Violati	ons Discovered during Insp	ection or any correc	tive actions required?
if no, were decks cle	eaned?					·
Is the Water around th	e b <b>a</b> rge	<b>9</b>				
Was a sample take	n?	To the state of th				
Voids or Hopper Pump	ed?					
Sheen present in wa pumping?	aler after					
Inspected by (Printed	) jason fr	anklin				
Approved by (Printed)	) Tyshun	Griffin		Approved by (Signatu	re)	
Entering your Signature L problems a clod	filis edmates	. Hist die ba	iyaya barr wapecii	ាច់ មែ ត្រូវបាលបាលខេត្ត es endicated ទ	ther	They -



Equipment	IMT134			Ve	sseVAsset	Midwest Pr	ide	
Company:	Canal Ba	arge Com	pany		Waterway:	Illinois Rive	I	1 278
Inspection Date Time:	06/04/20	15 20.	56		Location:	Rapps Flee	ef	
Load Status:	()Em	ipty () Par	tial 🕲 Loaded					
Instructions: (1) This form is to be consider areas, machinery strom the barge(s), correlations oils, hydraulic	essible area storage are: ctive action	as where cl as, wellded must be int	hemicals, oils, dry carg iks and other areas). I tiated. [Ref: VGP 4.1.1	p, or other materials a Ref: VGP 4.1.1] (3) if ] (4) The term "sheen	ere stored, mi pollutants or	xed and used ( constituents of	(including, as applicab I concern are determin	ele, cargo holds, ned to be orininati
Are Decks Clean?		$\square$	Any Vic	olations Discovered	during las	pection or an	ly corrective action	as required?
if no, were decks cle	eaned?							
is the Water around the free of sheen?	e barge	abla						
Was a sample taker	ገ?							
Voids or Hopper Pump	ed?							
Sheen present in wa	aler after							
pumping?		r "1						
Inspected by (Printed)	) jason fr	ranklin						
Approved by (Printed)	Tyshun	Griffin		Approved	l by (Signati	ne}		
fineling year Elginature f problems noted	Mil nationtes	s that the by	agens, hava been he	verted is about dance	as adicates	ater	SILL	<b>%</b>



Equipment.	PB2218			Vessel/Asset	Midwest Pride	
Company:	Canal Barge	Company		Waterway:	Illinois River	/ 278
Inspection Date Time	06/04/2015	20 56			Rapps Fleet	
Load Status:	○ Empty	🔾 Partial 🏵 L	_oaded			
boiler areas, machinery st from the barge(s), correct	isibie areas w orage areas, v ive action mus	here chemicals velidecks and o t be initiated. [R	, ails, dry cargo, or other ma other areas). [Ref: VGP 4.1.	iterials are stored, mix 1] (3) If pollutants or c . "sheen" is to be unde	ced and used (includin constituents of concer	ely accessible deck and cargo g, as applicable, cargo holds n are determined to be originating ation of oil or grease, including
Are Decks Clean?	[7]		Any Violations Disc	overed during Insp	ection or any corre	ective actions required?
If no were decks clea	ined? []					
Is the Water around the free of sheen?	barge 🗹					
Was a sample taken?	7 🗆					
Voids or Hopper Pumper	d? []					
Sheen present in wat pumping?	erafter 🗌					
Inspected by (Printed)	jason frank	lın				
Approved by (Printed)	Tyshun Grif	lin .	Ар	proved by (Signatu	re)	
Ettering your 2 gavillars fit stablishes often	e preinales rija	the hallgest is	ডিলে (ছল <u>গভালগভাই দি</u> ছলের	ារីសល់ស ភេស លេខិតកេរ៉ាស់ពី ៤	it is	I House



Equipment F	°B2013	Vesset/Asset: Midwest Pride
Company (	Canal Barge Comp	sny Waterway: Illinois River 1 279
Inspection Date Time (	6/04/2015 22.2	
Load Status:	○ Empty ○ Part	al ® Loaded
boiler areas, machinery sto from the barge(s), correcti	side steas where ch tage steas, welldeck ve action must be initi	riper voyage, whichever is more frequent. (2) Locations to be inspected. Safely accessible deck and cargo micals, oils, dry corgo, or other materials are stored, mixed and used (including, as applicable, cargo holds, and other areas). [Ref: VGP 4.1.1] (3) if pollutants or constituents of concern are determined to be original ted. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including riganic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	(A	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clear	ned? []	
is the Water around the tifee of sheen?	oarðe 🔼	
Was a sample taken?		
Voids or Hopper Pumped	?	
Sheen present in wate pumping?	rafter []	
Inspected by (Printed)	jason franklin	
Approved by (Printed)	Tyshun Griffin	Approved by (Signature)
Fracting year Signature FM problems to rea	larticates that the bar	icis) have been inspecifed in accordance as sidicatari abov



Vessel General Permit Compliance

Vessel/Asset: Mary C

Company:	Ingram Barge	Company		Waterway:	Ilfinois River	/ 279
Inspection Date Time: - : Load Status:		23-12 ) Partial <b>®</b> L	റുട്ടർ	Location	Farmer Bobs	
boiler areas, machinery st	pleted once per isible areas wh orage areas, w ive action must	week or per vo ere chemicals, elidecks and of be miliated. (Ri	oyage, whichever is mo oils, dry cargo, or othe ther areas) [Ref: VGP ef: VGP 4.1.1] (4) The i	rmaterials are stored, mi 4.1.1] (3) If pollutants or erm "sheen" is to be und	xed and used (includin constituents of concer	ely accessible deck and cargo g. as applicable, cargo holds, n are determined to be originating ation of oil or grease, including
Are Decks Clean?	P		Any Violations [	iscovered during ins	pection or any corre	ective actions required?
lf no, were decks clea	ined?				,	,
is the Water around the free of sheen?	barge [갓]	To the Market of Trade and the Control of the Contr				
Was a sample lakent	· []	A CALL OF THE PARTY OF THE PART				
Voids or Hopper Pumpe	d? <u>[</u> ]					
Sheen present in wat pumping?	er after					
Inspected by (Printed)	Carl Aldrich					a contract
Approved by (Printed)	Carl Aldrich			Approved by (Signate	ure)	21 pld
ាត្រាស់ (ការក្នុង ព្រះ គឺ កំពង់សែន ស៊ី)	eindichtes that	tre Narders i ha	s. E beer wobscied in a	troidance as minated	ahs of and Foreach is a	iction are from edition for an

or the property of the propert



Equipment:

IN075096

Vessel General Permit Compliance

Equipment.	CBY422			Vessel/Asset	Midwest Pride	
Company:	Canal Barge Co	mpany		Waterway:	Illinois River	/ 278
Inspection Date Time:	05/04/2015 2	23:42		Location:	Rapps Fleet	
Load Status:	○ Empty ○ F	eoJ 🌖 leins	ded			
boller areas machinery st	isible areas where orage areas, welk ive action must be	e chemicals, pils decks and other initiated. (Ref; '	., dry cargo, or other mater areas) [Ref: VGP 4.1.1] VGP 4.1.1] (4) The term "s	ials are stored, mb (3) if pollutants or heen" is to be und	xed and used (includin Constituents of conce	lely accessible deck and cargo ng, as applicable, cargo holds, rn are determined to be originat ation of oil or greese, including
Are Decks Clean?	[7]		Any Violations Discov	rered during ins	pection or any corr	ective actions required?
If no, were decks clea	ned?					
is the Water around the free of sheen? Was a sample taken?						
Voids or Hopper Pumper Sheen present in wat pumping?	*					
Inspected by (Printed)	jason franklin					
Approved by (Printed)	Tyshun Griffin		Аррг	oved by (Signati	ne)	
Philosopy, har Signature Philosophia interfere	Controlled Bog the	ithight have	teen miletten makind	toga as odugala¢.	shav Ç	I Year

VGFEXCHANGE

#### Vessel General Permit Compliance

Equipment: I	NG6538B		Vessel/Asset.	Midwest Pride	
Company: I	ngram Barge Con	npany	Waterway:	Illinois River	1 278
Inspection Date Time (	06/05/2015 02 :	59	Location:	Rapps Fleet	
Load Status:	○ Emply ○ Par	tial 🏵 Loaded			
areas and all safely acces boiler areas, machinery sto	sible areas where of prage areas, welided we action must be into	nemicals, oils, dry cargo, ks and other areas) [Re liated, [Ref: VGP 4.1.1]	ver is more frequent. (2) Location, or other materials are stored, not off VGP 4.1.1] (3) If pollutants or (4) The term "sheen" is to be und act Sheet 3.4.4]	xed and used (including, a constituents of concern a	sa applicable, cargo holds,
Are Decks Clean?	V	Any Viola	ations Discovered during Ins	pection or any correct	ive actions required?
If no, were decks clea	ned?				
is the Water around the tree of sheen?	barge 🗹				
Was a sample taken?	. 🗆				
Voids or Hopper Pumper	1? [ ]				
Sheen present in wate pumping?	erafter ()				
Inspected by (Printed)	jason franklin				
Approved by (Printed)	Tyshun Griffin		Approved by (Signatu	ure)	
Faceous y an Signature (4) gesplows noted	Codesales that the ca	PŞ603 balelon DSK¢	den in sochidence as indicated.	ato, SZ	- Horas



Equipment:

ING6538B

#### Vessel General Permit Compliance

Vessel/Asset: Midwest Pride

Company:	Ingram Barg	e Company		٧	Vaterway.	Illinois River	i	/ 27€
Inspection Date Time	06/05/2015	02 59			Location.	Rapps Flee	t	
Load Status:	○ Empty	(© leineq(	Loaded			• ,		
Instructions: (1) This form is to be compress and all safety acception of the barge (s), correct lubricating oils, hydraulic of	ssible areas w lorage areas, v tive action mus	here chemical velidecks and t be initiated. [	s, oils, dry cargo, or other areas) {Ref: ' Ref: VGP 4.1.1} (4)	other materials are VGP 4.1.1] (3) if po The term "sheen" is	stored, mb listants or	ked and used ( constituents of	including, as app concern are del	olicable, cargo holds, lermined to be originating
Are Decks Clean?	Ø	-	Any Violatic	ons Discovered d	មរាំពិព្ធ lnsi	pection or an	y corrective a	ctions required?
If no, were decks clea	aned?	e description of Management of						
is the Water around the free of sheen?	barge 🗹		,					
Was a sample taken	? []							
Voids or Hopper Pumpe	d? []							
Sheen present in war pumping?	ler after							
Inspected by (Printed)	jason frank	lin						
Approved by (Printed)	Tyshun Gr	fin		Approved by	y (Signati	ıre)		
Entering your Signature Pi prot have haded	L indicates tha	l the barce's -	oave then perecie	ପ୍ରମାନ୍ତ୍ୟ (ପ୍ରଥମତ୍ର କର	indicated :	8 <i>0</i> ( V		Y Yasis



Equipment.

ING7708

Vessel General Permit Compliance

Equipment: (	CBX2065		Vessel	/Asset:	Mary C	
Company: (	Sanal Barge	Company	₩at	terway:	Illinois River	ı 279
Inspection Date Time: (	6/05/2015	03 15	Lo	cation:	Lemont-Trader	
Load Status:	⊕ Empty (	Partial OL	oaded			
boiler areas, machinery sto from the barga(s), correcti	sible areas wh vrage areas, w ve action must	ere chemicals, elidecks and ot be initialed. [Re	oyage, whichever is more frequent. (2) L oils, dry cargo, or other materials are sto her areas). [Ref: VGP 4.1.1] (3) If pollut. of: VGP 4.1.1] (4) The term "sheen" is to oils [Ref VGP Fact Sheet 3.4.4]	ored, mix ante or o	ed and used (including,	as applicable, cargo holds,
Are Decks Clean?	V		Any Violations Discovered duri	ing Insp	ection or any correc	tive actions required?
ił no, were decks clea	ned?				·	
is the Water around the I free of sheen?	oarge 🕎					
Was a sample laker.?	$\Box$					
Voids or Hopper Pumped						
Sheen present in wate pumping?	erafter 🗍					
Inspected by (Printed)	Cail Aldrich					
Approved by (Printed)	Carl Aldrich		Approved by (S	Signatu	(e)	2/1/1/

Cotaring your Signature Ptt. Indicates that the baryers, have been inspected in accordance as indicated of one and corrective action has been intered for any problems noted.



Vessel General Permit Compliance

Equipment	CBX2135		Vessel/Ass	et: Mary C	
Company:	Canal Barge	Company	Waterwa	y. Illinois River	/ 279
Inspection Date Time:	06/05/2015	03:15	Locatio	n: Lemant-Trader	
Load Status:	@ Empty	○Partial ○L	oaded		
areas and all safely acc boller areas, machinery from the barge(s), corre	essible areas w storage areas, ctive action mus	here chemicals, welldecks and o stipe initiated. [R	oyage, whichever is more frequent. (2) Locat oils, dry cargo, or other materials are stored, ther aress). [Ref: VGP 4.1.1]. (3) if pollutants ef: VGP 4.1.1]. (4) The term "sheen" is to be u oils [Ref VGP Fact Sheet 3.4.4].	mixed and used (including, as or constituents of concern are	i applicable, cargo holds, e determined to be orioinatino
Are Decks Clean?	IZ.		Any Violations Discovered during h	rspection or any correction	ve actions required?
If no, were decks d	eaned? [¨]				
Is the Water around th	ie barge				
Was a sample take	n?				
Voids or Hopper Pump	ped?	r van			
Sheen present in w pumping?	raterafter _				
Inspected by (Printed	n) Carl Aldric	h			
Approved by (Printed	) Carl Aldric	ħ	Approved by (Sign	alure) -	2/ D/JA

Entering your Signature Fact nonstes that the bargers these treatmented in secretarities as indicated and corrective setting has been estated for any problems noted.



Vessel General Permit Compliance

Equipment:	CBY272			Vessel/Asset:	Mary C	
Company:	Canal Barge	Company			Illinois River	/ 279
Inspection Date Time:	06/05/2015	03 15			Lemont-Trader	, 2, 3
Load Status:	Empty	○ Partial ○ L	bebeo.			
holer areas, machinery from the barge(s), corre	storage areas, victive action mus	welldecks and o the initiated IR	, olis, dry cargo, or other mai ther areas). [Ref: VGP 4.1.1	terials are stored, mb ] (3) If pollutants or t "absent is to be unde	ted and used (including	ly accessible deck and cargo h, as applicable, cargo holds, h are determined to be originating tion of oil or grease, including
Are Decks Clean?	V		Any Violations Disc	overec during Insp	pection or any corre	ctive actions required?
lf no, were decks cle	eaned?					
is the Water around th	e barge 🕝					
Was a sample taker	n? 🗍					
Voids or Hopper Pump	ed? []					
Sheen present in wa pumping?	ater after					
inspected by (Printed)	Carl Aldrici	ì				
Approved by (Printed)	Carl Aldrich		Арр	roved by (Signatur	(8)	21 pld

Entering your Signature Plot and rafes that the hargers, have been dispersed in appointance as sidurated and telescope action has been interested in appointment and and are sed corrective action has been interested for any problems noted.



Vessel General Permit Compliance

Equipment:	CBY275		\	/essel/Asset	Mary C	
Company:	Canal Barge	Company			Illinois River	/ 279
Inspection Date Time:	06/05/2015	03.15		Location:	Lernont-Trader	, 2.0
Load Status:	Empty	ФPartial О ы	oaded			
boller areas, machinery from the barge(s), corre	essible areas, v storage areas, v ctive action mus	mere chemicals, welldecks and of it be initiated IRa	bysge, whichever is more frequently oils, dry cargo, or other materials her areas.) [Ref: VGP 4.1.1] (3) ef: VGP 4.1.1] (4) The term "sheet 3.4.4]	are stored, mi	ked and used (includin	g, as applicable, cargo holds,
Are Decks Clean?	$\square$	1	Any Violations Discovere	ed during Ins	pection or any corre	ective actions required?
ll no, were decks ck	aaned? []					,
Is the Water around the	e barge					
Was a sample taker	n? []					
Voids or Hopper Pump	212					
Sheen present in wa pumping?	ater after					
Inspected by (Printed	) Carl Aldricl	'n				75. 7
Approved by (Printed)	Carl Aldrich	ì	Approve	d by (Signatu	re)	7/ DISA

Entering your Signature Principles that the Estigation is taken inspected in amountance as included above and corrective action has been intered for any problems maken.



Vessel General Permit Compliance

Equipment.	RC1250B	Vessel'Asset Mary C
Company	Canal Barge Com;	,
Inspection Date Time	06/05/2015 03 1	
Load Status:	♠ Empty () Part	
boiler areas, machinery at from the barge(s), correct	orage areas, welldeci ive action must be incl	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safely accessible deck and cargo emicals, oils, dry cargo, or other materials rise stored, moled and used (including, as applicable, cargo holds, is and other areas). [Ref: VGP 4.1.1] (3) If poliutants or constituents of concern are determined to be originating lated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of o'llor grease, including organic oils. [Ref. VGP Fact Sheet 3.4.4]
Are Decks Clean?	9	Any Violations Discovered during Inspection or any corrective actions required?
lf no. were decks clea	ned?	
is the Water around the free of sheen?	barge 🗹	
Was a sample taken?		
Voids or Hopper Pumper	17	
Sheen present in wate pumping?	er after	
Inspected by (Printed)	Carl Aldrich	
Approved by (Printed)	Carl Aldrich	Approved by (Signature)

Entering your Dispature (vi) pagative that the thereis, have been inspected in accordance as indicated above and consisting accordance becoming a problem, or text.

PROFINANT POPERATINGS from



Equipment.	CBY227			Vessel/Asset:	Eileen C	
Company:	Canal Barge Cor	прапу		Waterway:	Illinois River	/ 298
Inspection Date Time	06/05/2015 04	1 20			IMT Lemont (NRF)	
Load Status:	○ Empty ○ P:	artial 🏵 Loade	σ		,	
boiler areas, machinery s	issipie breas where dorage areas, wellde dive action must be i	chemicals, oils, d ecks and other ar nitiated. [Ref: VG	ry cargo, or other materi eas). [Ref: VGP 4,1,1] ( iP 4,1,1] (4) The term "sh	als are stored, mb 3) if poliutants or d teen" is to be unde	ed and used (including,	y accessible deck and cargo, as applicable, cargo holds, are determined to be origination of oil or grease, including
Are Decks Clean?	V	Α	ny Violations Discove	ered during Inst	ection or any correc	ctive actions required?
If no, were decks cle	aned?					
Is the Water around the free of sheen?	barge 🔽					
Was a sample taken	?					
Voids of Hopper Pumpe	ed? []					
Sheen present in wa pumping?	ter after					
Inspected by (Printed)	JIM CUMNINGI	MAH				
Approved by (Printed)	Scottis Payne		Appro	ved by (Signatu	ге)	
Cuterino your Signature Pa problems voted	Mindipates hist the t	ostge/s' have be	en mapacied in abbookdar	nce as indicated a	bov X	



Vessel General Permit Compliance

Equipment.	MT123		Vessel/Asset:	Eileen C	
Company: (	Canal Barge Com	pany	Waterway:	Illinois River	1 298
Inspection Date Time: 0	6/05/2015 04	20		IMT Lemont (NRF)	, 200
Load Status:	○ Empty ○ Par	riial ® Loaded	·		
boiler areas, machinery sto	risge areas, welded ve action must be init	nemicais, ons, ory carg ks and other areas): [I tisted. [Ref: VGP 4.1.1	ever is more frequent (2) Locations c, or other materials are stored, mix left VGP 4.1.1} (3) If pollutants or c [ (4) The term "sheen" is to be unde Fact Sheet 3.4.4]	ed and used (including, as	applicable, carga holds,
Are Decks Clean?	図	Any Vio	lations Discovered during Insp	ection or any correctiv	e actions required?
lf no, were decks clear	ned?				, , , ,
is the Water around the t free of sheen?	oarge 🔄				
Was a sample taken?					
Voids or Hopper Pumped	?				
Sheen present in wale pumping?	rafter []				
Inspected by (Printed)	JIM CUNNINGH,	ΑM			
Approved by (Printed)	Scottis Payne		Approved by (Signatur	e)	
ी Hearing Local Signature Mr. Englishes Intello	10 Mas Hall Perha	i gras (Base gerkt) kap	acted makkinidasibe as Indikaled al	· Alaka	energia. La companya di seria

VGPEXCHANGE

Equipment	RCI256B		V	essel/Asset	±ileen C	
Company:	Canal Barge (	Company		Waterway	Illinois River	/ 298
Inspection Date Time	06/05/2015	04 20			IMT Lemont (HRF)	
Load Status	C Empty C	Partial 🌘 L	osded		, ,	
boiler areas, machinery st from the barge(s), correct	orage areas, we we action must i	aldecks and of the cks and of the initiated. (Ri	oyage, whichever is more frequentials, dry pargo, or other materials ther areas). [Ref: VGP 4.1.1] (3) hef: VGP 4.1.1] (4) The term "sheet of s [Ref VGP Fact Sheet 3.4.4]	are stored, mb (nobstanta or d	ced and used (including, as	applicable, cargo holds,
Are Decks Clean?	V		Any Violations Discovere	d during Insp	ection or any corrective	e actions required?
fino, were decks clea	ned?					
is the Water around the free of sheen?	barge ☑					
Was a sample taken?						
Voids or Hopper Pumper						
Sheen present in wate pumping?	erafter []					
(napected by (Printed)	JIM CUTIMIN	GHAM				
Approved by (Printed)	Scottis Payn	e	Approved	d by (Signalu	re)	
finsenng glava Bigmat vie Ka growterne rieted	अविशिष्ठातिक (nat p	mirangans ha	ue beet inspected in aeroccanda	នទ ១៥២.៨៤៩ ៛	a Late	

Vessel General Permit Compliance

Equipment !!	N075026		Vi	essel/Asset	Albert C	
Company li	igram Bargi	Company		Waterway.	Illinois River	i 299.4
Inspection Date Time: G	6/06/2015	08 00			IMT Lemont (Clea	
Load Status:	O Empty (	) Partiet 🀌 L	oaded		,	,
boiler areas, machinery sto from the barge(s), correction	rage areas, w reaction must	elidecks and of be initiated. [Re	oyage, whichever is more frequent oils, dry cargo, or other materials ther areas.) [Ref: VGP 4.1.1] (3) It of: VGP 4.1.1] (4) The term "sheer oils [Ref VGP Fact Sheet 3.4.4]	are stored, mo f poliutents or :	ced and used (including	g, as applicable, cargo holds,
Are Decks Clean?	( <u>~</u> )		Any Violations Discovered	d during Insp	ection or any corre	ective actions required?
If no, were decks clear	ned?				•	
is the Water around the b	arge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	? []					
Sheen present in wate pumping?	r sfler					
Inspected by (Printed)	Peter Kosik					
Approved by (Printed)	<sup>D</sup> eter Kosik		Approved	d by (Signatu	re)	
Entering your Signature Pilic problems noted	edicales that	the barge(s) no	ive been inspected in accordance	as indicated a	co. Peter	My S for any

IMT 0990

Equipment:	CBX2065	Vessel/Asset: Mary C	
Company:	Canal Barge Comp	· · · · · · · · · · · · · · · · · · ·	/ 278
Inspection Date Time	06/05/2015 09.0		, 210
Load Status:		• • • • • • • • • • • • • • • • • • • •	
bailer areas, machinery s from the barge(s), correc	torage areas, welldeck	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safely accessible micels, oas, dry cargo, or other nialerials are stored, mixed and used (including, as applicates and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determinated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or organic oils [Ref VGP Fact Sheet 3.4.4]	ble, cargo holds,
Are Decks Clean?	V	Any Violations Discovered during Inspection or any corrective actio	ns required?
lf no, were decks cle	aned?		
is the Water around the free of sheen?	parge 🖸		
Was a sample taken	?		
Voids or Hopper Pumpe	d? [¯]		
Sheen present in war pumping?	ler after		
Inspected by (Printed)	BARNARD/KUNT)	ZWEAVER	
Approved by (Printed)	Robert Smith	Approved by (Signature)	
Entering your Signature Po problems noted	Il indicates that the bar	cers in not a been it specied in accordance as resideted above following for such	for eny
		I	

Equipment.	T13828		Vessel/Asset	Albert C	
Company;	Ingram Barge Cor	трапу		Illinois River	/ 293
Inspedion Date Time:	06/05/2015 11	05	Location:		7 253
Load Status.	○ Empty ○ Pa	rlial 🔇 Loaded	Eddawii.	ONDOW.	
boiler areas, machinery st	orage areas, wellded ive action must be in	tiks and other steas)	thever is more frequent. (2) Eocations go, or other materials are stored, mix [Ref: VGP 4.1.1] (3) If pollutants or o 1] (4) The term "sheen" is to be unde P Fact Sheet 3.4.4)	eo and used (includia	ig, as applicable, cargo holds.
Are Decks Clean?	$\overline{\mathbf{Y}}$	Any Vie	Diations Discovered during Insp	ection or any corr	Active actions required?
fino, were decks clea	ned?			, , , , , , , , , , , , , , , , , , ,	Solve decions required:
is the Water around the lifee of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	ا 17				
Sheen present in water pumping?	erafter				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signatur	e)	
Four my your Signature Fig. 1711 Hos moved	microster was media	(Gris 19876 been leg	erredici ankardande as monateo sr	in Ster	In Some

Equipment:	IMT 119	Vessel/Asset:	Alberi C	
Company:	Canal Barge Comp		Illinois River	7 299
Inspection Date Time.	06/05/2015 12.0	^	Lemont Drydock	
Load Status:	<b>©</b> Empty ○ Parti			
boiler areas, machinery st from the barge(s), correct	orage areas, welideck live action must be initial	or per voyage, whichever is more frequent. (2) Location imicals, oils, dry cargo, or other materials are stored, mis and other areas). [Ref: VGP 4.1.1] (3) If pollutants or ited. [Ref: VGP 4.1.1] (4) The term "sheen" is to be undirected oils [Ref VGP fact Sheet 3.4.4].	xed and used (including	ng, as applicable, cargo holds,
Are Decks Clean?	[2]	Any Violations Discovered during Ins	pection or any corr	rective actions required?
lfino, were decks clea	ined? []		·	
is the Water around the free of sheen?	barge 🗹			
Was a sample laken?	· [			
Voids or Hopper Pumper	d? []			
Sheen present in wat pumping?	erafter [			
Inspected by (Printed)	Peter Kosik			
Approved by (Printed)	Fleter Kosik	Approved by (Signatu	re)	,
foleorgypac Algoriths FP. prodeins puled	concates that the half	ièls i na lé been inspectes in accordance as inducted a	in fiter	Jan & to any




Equipment:	CBX2065		Vessel/Asset:	Midwest Pride	
Company:	Canal Barge Com	ipany		illinois River	1 277
Inspection Date Time	06/05/2015 13	10	•	Mobil Coke Spout	7 217
Load Status:	○ Empty ○ Pa	rtial 🕲 Loaded		wood conc copuli	
boiler areas, machinery a	lorage areas, wellded live action must be in	oks and other areas) [R tisted. (Ref: VGP 4.4.4)	ever is more frequent (2) Locations b, or other materists are stored, mix ef: VGP 4.1.1] (3) If pollutants or or (4) The term "shear" is to be under Fact Sheet 3.4.4]	ed and used (including, as i	applicable, cargo holds,
Are Decks Clean?	V	Any Viol	ations Discovered during insp	ection or any corrective	actions required?
If no, were decks clea	aned? □			,	
is the Water around the free of sheen?	barge ☑				
Was a sample taken	?				
Voids or Hopper Pumpe	ø? <u>□</u>				
Sheen present in wat pumping?	erafter 🗀				
inspected by (Printed)	patrick erickson				
Approved by (Printed)	Tommy Walter		Approved by (Signatur	•	
lintering your Dignature Pa problems noted.	condicates that the ba	tocis chave been inspe	Clad in accordance as indicated in	nev (in the control of the control o	1. J.



Equipment:	CBY272		Vessel/Asset:	Eileen C		
Company:	Canal Barge Com	pany		Illinois River		/ 278
Inspection Date Time:	06/05/2015 16	35	•	Rapps Fleet		, 210
Load Status:	<b>®</b> Emply ○ Pa	rtial O Loaded				
boiler areas, machinery s	storage areas, wellded	tks and other areas) [Re itisted, [Ref: VGP 4.1.11]	er is more frequent. (2) Locations or other materials are stored, mix f: VGP 4.1.1) (3) If pollutants or c 4) The term "sheen" is to be undesct Sheet 3.4.4)	ed and used (in	cluding, as applicab	le, cargo holds,
Are Decks Clean?	V	Any Viola	tions Discovered during Insp	ection or any	corrective action	as required?
lf no, were decks cle	aned?					
is the Water around the tree of sheen?	barge					
Was a sample taken	, <u>П</u>					
Voids or Hopper Pumpe	ed? []					
Sheen present in wa pumping?	terafter 🗌					
Inspected by (Printed)	Scottis Payne					
Approved by (Printed)	Scottis Payne		Approved by (Signatur	e)		
Entering your Synature Pr orthiseus dolod	ර්ගා ජනත්වන ගැන ඇතු දිව	Mgelt have been begen	ton in accomplehous as religiated as		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	A Company



Equipment	RC:250B			Vessel/Asset	Eileen C	
Company:	Canal Barge	Company			Illinois River	1 278
Inspection Date Time;	06/05/2015	16.35			Rapps Fleet	7270
Load Status:	<b>⑤</b> Empty ○	) Partial () L	oaded	2000.011	Tropps Fisat	
boiler areas, machinery str	orage areas, v. ive action must	elidecks and of	ther areas) [Ref: VGP 4.1]	iterials are stored mod [1] (3) If pollulants or o	ed and used (including	ely accessible deck and cargo y, as applicable, cargo holds, o are determined to be originate tion of oil or grease, including
Are Decks Clean?	V		Any Violations Disc	overed during Insp	ection or any corre	ctive actions required?
If no, were decks clea	ned?			- '		on a denoted required:
is the Water around the i	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	l? []					
Sheen present in wate pumping?	4,,0					
Inspected by (Printed)	Scottis Pay	1e				
Approved by (Printed)	Scottis Payr	ìe	Ap	proved by (Signatur	e)	
Covering your Signalura Lite Lite Covering to Lock	minimates high s	he harçek i na	A transfer teater in gards	taande as no ryfed et	n Zind	



Equipment 1	F13828		Vessel/Asset	Albert C	
Company:	ngram Barge C	empany		Illinois River	/ 299.4
Inspection Date Time (	06/05/2015 1	6 35	Location:		1205.4
Load Status:	○ Empty ○ F	artial 🖲 Loaded	200000		
boiler areas, machinery sto	orage areas, welld we action must be	ecks and other areas) [ initiated [Ref: VGP 4.1]	never is more frequent. (2) Locations po, or other materials are stored, mix Ref: VGP 4.1.1] (3) If pokulants or or (4) The term "sheen" is to be under Fact Sheet 3.4.4)	ed and used (includin	ig, as applicable, cargo holds,
Are Decks Clean?	<b>[</b> ⊋]	Any Vic	plations Discovered during Insp	ection or any corr	ective actions required?
If no, were decks clear	ned?		,	,	control demons regulated:
is the Water around the t free of sheen?	oarge 🔄				
Was a sample taken?	П				
Voids or Hopper Pumped	?				
Sheen present in wate pumping?	rafter 🗀				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Koaik		Approved by (Signature	e)	
Entering to un Stonature P8. Croblems coded	indicates that the	bargeris) nære been insp	écléd in acot rosoce as isocated at	in liter	Jef S. Brown



		Vessel General Permit Compilance
Equipment:	CBY227	Versel/Asset, Midwest Pride
Company:	Canal Barge Com	pany Waterway, Illinois River / 279
	06/05/2015 18	, — · <del>·</del>
Load Status:	○ Empty ○ Pa	rial 🍥 Loaded
boiler areas, machinery si from the barge(s), correct	orage areas, wellded	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo remicals, oils, dry cargo, or ether materials are stored, mixed and used (including, as applicable, cargo holds, its and other areas). [Ref: VGP 4.1.1] (3) if pollutants or constituents of concern are determined to be originating listed. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	9	Any Violations Discovered during Inspection or any corrective actions required?
ll no, were decks clea	ned? [])	sequired:
is the Water around the free of sheen?	barge ☑	
Was a sample taken?	e C	
Voids or Hopper Pumper	J? 🔲	
Sheen present in wate pumping?	-4-5	
Inspected by (Printed)	jason franklin	
Approved by (Printed)	Tyshun Griffin	Approved by (Signature)
Enfecting your Signature FE. problems noted	redicates that the had	(95-5) have been inspected in accordance as indicated abov



Equipment;	IM1 123	Vessel/Asset Midwest Pride
Company:	Canal Barge Com	vany Waterway: Illinois River / 279
	06/05/2015 18	· · ·
Load Status:	○Empty ○ Par	ial 🏵 Loaded
boiler areas, machinery so from the barge(s), correct	lorage areas, wellded live action must be inc	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safely accessible deck and cargo emicals, pils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, a and other areas). [Ref: VGP 4.1.1] (3) if pollutants or constituents of concern are determined to be originating ated. [Ref: VGP 4.1.1] (4) The term "streen" is to be understood as a concentration of pil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	[2]	Any Violations Discovered during inspection or any corrective actions required?
If no, were decks clea	aned?	
Is the Water around the free of sheen? Was a sample taken?	区	
Voids or Hopper Pumper	d? 📋	
Sheen present in wal pumping?	er after	
Inspected by (Printed)	jason franklin	
Approved by (Printed)	Tyshun Griffin	Approved by (Signature)
Process, case Especture to conducts noted	s crammas and the tia	(A 18 thaus maze a substitute due accompance las mércales accom



Equipment:	RCI255B	Vessel/Asset: Midwest Pride	
Company:	Canal Barge Compa	ny Waterway: Illinois River	+ 279
Inspection Date Time:	05/05/2015 18.34		
Load Status:	○Empty ○ Partia	⊎ ® Lo3ded	
boiler areas, machinery st from the barge(s), correct	ssible areas where chem lorage areas, welldecks tive action must be initiati	r per voyage, whichever is more frequent. (2) Locations to be inspected. Safely accessible micals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or graphic oils [Ref VGP Fact Sheet 3.4.4]	E, Cargo holds.
Are Decks Clean?	$oldsymbol{oldsymbol{arphi}}$	Any Violations Discovered during Inspection or any corrective actions	s required?
If no, were decks clea	aned?		
Is the Water around the free of sheen?	barge [▽]		
Was a sample taken?	, 0		
Voids or Hopper Pumpe	d? []		
Sheen present in wat pumping?	erafter (1)		
Inspected by (Printed)	jason franklin		
Approved by (Printed)	Tyshun Griffin	Approved by (Signature)	
Foresting your Signature Fo	condiciences that the transpi	BIS Male silven instanced in accordance as consider and	



Vessel General Permit Compliance

Equipment:	T 13828		Vessel/Asset:	Albert C	
Company;	Ingiam Barge Cor	npany		Illinais River	/ 299.4
inspection Date Time.	06/06/2015 00	40		IMT Lemont (Lowe	Ÿ · · · ·
Load Status:	○ Empty ○ Pai	rtial <b>©</b> Loaded	25501011.	MAL CAMON (COMS	Crane;
boiler areas, machinery sto	prage areas, welkded ive action must be ini	cks and other areas) [Ridled [Ref: VGP 4 1 1]	ver is more frequent. (2) Locations, or other materials are stored, mix. et: VGP 4.1.1] (3) If poliutants or c (4) The term "sheen" is to be underfact Sheet 3.4.4]	ed and used (including	, as applicable, cargo holds
Are Decks Clean?	Q	Any Viola	ations Discovered during Insp	ection or any corre	rtive actions required?
If no, were decks clea	ned?		,		ense acmond tedanea;
is the Water around the I free of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	l? []				
Sheen present in water	r off ar				
puntping?					
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)			Approved by (Signature	e)	
Potening your Signature PS, problems a ded	ordicates that the ba	igers have been mape	iten in accordance as indicated ab	. Ater	In S for any

VGPEXCHANGE

Equipment:	MT119			Vessel/Assel	Apple-C	
Company: (	Canal Barge	Company			Illinois River	/ 300
Inspection Date Time. 0	6/06/2015	07.25		-	IMT Lemont (TRD)	7 300
Load Status:	€ Empty (	D Partial O Lo	caded	coconon.	non compactively	
Instructions: (1) This form is to be complaress and all safety access boiler areas, machinery sto from the barge(s), correcting oils, hydraulic oils.	rage arees, w relaction must	elidecks and off	her areas). [Ref: VGP 4.1 of VGP 4.1 11 (4) The term	interials are stored, mod [.1] (3) If pollutants or o	ed and used (including, as	applicable, cargo holds,
Are Decks Clean?	[·]	[	Any Violations Dis	covered during Insp	ection or any correctly	4 actions required?
lf no, were decks clear	ned? []				The state of the s	e actions tedaited:
s the Water around the b ree of sheen?	arge 🔽					
Was a sample taken?						
/olds or Hopper Pumped:						
Sheen present in water pumping?						
Inspected by (Printed)	.Leffler					
Approved by (Printed)	Brad Bond		Ар	proved by (Signatur	e)	<i>,</i> ~
Cotering your Signature Phy: problems noted	ndicates that t	hersige:s:na.	ve been inspected in acco	ordance as indicated an	no Brad	Bond



Equipment.	IMT119			Vessel/Asset:	Aggie-C	
Company:	Canal Barge C	Company			Illinois River	/ 300
Inspection Date Time.	06/06/2015	07.25			IMT Lemont (TRD)	, 300
Load Status;		Partial () Loade	ď		mir comon (ite)	
Instructions: (1) This form is to be compressed and all safely accessorier areas, machinery strom the barge(s), correct lubricating oils, hydraulic compressed.	orage areas, wei	lidecks and other ar e initiated. TRef: VC	ny cargo, or other mate reas) [Ref: VGP 4,1,1] iP 4 1 11 (4) The term is	nals are stored, mod (3) If politiants or d	ed and used (including, as	s applicable, cargo holds,
Are Decks Clean?	<b>\text{\ti}\}\\ \text{\te}\}\tittt{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\text{\text{\text{\tex{\text{\text{\text{\text{\text{\texi}\tiex{\text{\ti}}}}\tinttitex{\text{\text{\text{\text{\ti}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}}</b>	A	Any Violations Discov	rered during (nsp	ection or any correctiv	ve actions required?
If no, were decks clea	ined?			- '	,	
is the Water around the free of sheen?	barge ☑					
Was a sample taken?						
Voids or Hopper Pumper	d? []					
Sheen present in wate pumping?	erafter []					
Inspected by (Printed)	LL effler					
Approved by (Printed)	Brad Bond		Appro	oved by (Signatur	e)	<u>^</u>
- Énteung your Righdide Ph - problems incled	( wdv ara that th	e brigers male be	en respected in encouds	ance as indicaled as	a Brad	Bond



Equipment:	IMT119			Vessel/Asset	Aggie-C	
Company:	Canal Barg	ge Company			Illinois River	<i>)</i> 300
Inspection Date Time	06/06/2019	5 07 25			IMT Lemont (TRD)	, 300
Load Status:	Empt	y ○ Parlial ○	Loaded		The second secon	
boiler areas, machinery a from the barge(a), corre	storage areas ctive action m	welldecks and ust be initiated.	voyage, whichever is more fis, oils, dry cargo, or other mis other areas) [Ref: VGP 4.1.] [Ref: VGP 4.1.1] (4) The term croils [Ref VGP Fact Sheet 3	ieriais are stored, mix i] (3) II pollutants or c	ed and used (including, as	s applicable, cargo holds,
Are Decks Clean?	5	6	Any Violations Disc	overed during Insp	ection or any correctiv	ve actions rennired?
If no, were decks cle	aned? [				,	
Is the Water around the free of sheen?	e barge	3				
Was a sample taken	? [	]				
Voids or Hopper Pumpe	ed? []	7				
Sheen present in wa pumping?	***					
Inspected by (Printed)	LLeffler					
Approved by (Printed)	Brad Bond	i	Арр	eroved אַל (Signatur	e)	
Er iering yaar Signature M problems noted	ti indicates in	arine targers,	have then inspected histogr	ව්වශාල මහ පාර්තෙක්වල් අද	a Brod	Bond



Equipment:	IMT119			Vessel/Asset	Aggie-C	
Company:	Canal Barge	Company			Illinois River	/ 300
Inspection Date Time	06/06/2015	07.25		Location	IMT Lemont (TRD)	, 300
Lead Status:	Empty 9	○Panīal () L	.oaded		,	
boiler areas, machinery st from the barge(s), correct	orage areas, v ive action mus	ricre chemicals, velidecks and o I be initiated. IR:	oyage, whichever is more free oils, dry cargo, or other mater ther areas) [Ref: VGP 4.1.1] ef: VGP 4.1.1] (4) The term "s oils [Ref VGP Fact Sheef 3.4	isis are stored, mb (3) If poliutants or ( heen" is to be upda	ed and used (including, as	applicable, cargo helds,
Are Decks Clean?	<b>[</b> 2]		Any Violations Discov	ered during Insp	ection or any correctiv	/e actions required?
If no, were decks clea	ined?			· .	,	o bottomo reguireu.
is the Water around the free of sheen?	barge 🗹					
Was a sample taken?	· □					
Voids or Hopper Pumper	J? []					
Sheen present in water pumping?						
Inspected by (Printed)	Heffler					
Approved by (Printed)	Brad Bond		Appro	oved by (Signatur	'e)	_
Entering your Signature Pit. problems noted	nocales thai	the barge(s) ha	ive been is specied in accorda	noe as indicated a	or Brod	Bond



Vessel General Permit Compliance

Equipment:	N005467	Vessel/Asset: Windy City
Company:	ngram Barge Cor	, ,
Inspection Date Time: (	06/06/2015 10	
Load Status:	○ Empty ○ Pa	• ,
boiler areas, machinery ste from the barge(s), correcti	orage areas, wellded we action must be in	k or per voyage, whichever is more frequent. (2) Locations to be inspected: Safely accessible deck and cargo chemicals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, cks and other areas). [Ref: VGP 4.1.1] (3) if poliutants or constituents of concern are determined to be originating tiliated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	$\Box$	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clea	ned? []	any torrotare detailed:
is the Water around the I free of sheen?	parge 🔁	
Was a sample taken?		
Voids or Ropper Pumped	? [.]	
Sheen present in wate pumping?		
Inspected by (Printed)	Paul Roman	
Approved by (Printed)	Paul Roman	Approved by (Signature)  App Unumhouston  App Unumhouston  App Unumhouston
Entering your Alghature (7) processes coled	o bitales final frei by	argers, have these inspected in accompance as edicated above.

VGPEXCHANGE

Equipment: I	NG5892	Vessel/Asset: Windy City
Company:	ngram Barge Con	
Inspection Date Time (	6/06/20 <b>1</b> 5 10	,
Load Status:	○ Empty ○ Par	` ,
boiler areas, machinery sto from the barge(s), correcti	rage areas, wellded ve action must be init	or per veyage, whichever is more frequent. (2) Locations to be inspected. Safely accessible deck and cargo smoats, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, is and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originating ited. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including rigenic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	Ø	Any Violations Discovered Juring Inspection or any corrective actions required?
II no, were decks clear	ned?	Jan parameter and a control actions required:
Is the Water around the t	narge 🗹	
Was a sample taken?		
Voids or Hopper Pumped	? [_]	
Sheen present in wate pumping?	1	
Inspected by (Printed)	Paul Roman	
Approved by (Printed)	Paul Roman	Approved by (Signature)  Apalinguage Apali
Entering your Signals re III. Unoidens esten	odicates the the car	less that is used in accordance as indicated abov.



Ecuipment:	IMT124		Vessel/Asset.	Aggie-C	
Company:	Canal Barge Com	pany		Illinois River	/ 328 8
Inspection Date Time:	06/06/2015 21	53	Location	CALUMET RIVER	
Load Status:	○ Empty ○ Par	rlial 🏵 Loaded			
boiler areas, machinery st	orage areas, wellded ive action must be ini	itemicals, olls, ory cargo. iks and other areas). [Retiated, [Ret]. VGP 4.1.11	ver is more frequent. (2) Locations or other materials are stored, most: VGP 4.1.1] (3) if pollutants or c (4) The term "sheen" is to be undeact Sheet 3.4.4]	ed and used (including,	as applicable, cargo holds,
Are Decks Clean?	$oldsymbol{arphi}$	Any Viole	itions Discovered during Insp	ection or any correc	tive actions required?
if no, were decks clea	ned?				1-11-11
Is the Water around the Iree of sheen?	barge ☑				
Was a sample laken?					
Voids or Hopper Pumped	1?				
Sheen present in wate pumping?	erafter 🗍				
Inspected by (Printed)	r kulas				
Approved by (Printed)	Brad Bend		Approved by (Signatur	<b>e</b> }	
Potervis your Signature bit. procleme noted	indicates that the ca	uge's have been rist ed	Wed in accordance as indicated ar	Bros	l Bond



Equipment:	M085166		Vessel/4	Asset 2	Albert C	
Company:	Ingram Barge (	Company			llinois River	/ 298
Inspection Date Time	06/06/2015	22 30			MT Lemont (NRF)	, 200
Load Status:	○ Empty ○	Partial 🌘 Lo			in comen (MIXI )	
boiler areas, machinery at from the barge(s), correct	orage areas, wei ive action must be	decks and oth	rage, whichever is more frequent (2) Lo ils, dry cargo, or other materials are stor er areas) [Ret: VGP 4.1.1] (3) If polluter f: VGP 4.1.1] (4) The term "sheen" is to b is [Ref VGP Fact Sheet 3.4.4]	ed mixe	o and used (including as	applicable, cargo holds,
Are Decks Clean?	$\Box$	}	Any Violations Discovered durin	g Inspe	ction or any corrective	actions required?
If no, were decks clea	ned?	U	one		•	
Is the Water around the i	oarge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	· · · · ·					
Sheen present in wate pumping?	r after					
Inspected by (Printed)	patrick dong					
Approved by (Printed)	Antonio Lopez		Approved by (Sig	gnature	)	
Antourig your Signedure Poli problems noted	sidecales that the	luaige≀s, ha∵	e been inspected in accordance as indic	aled abo	Antonis	Lopez

Equipment:	NG5855	Vessel/Asset: Albert C
Company j	ingram Barge Cor	
Inspection Date Time: (	06/06/2015 22	1
Load Status:	○Empty ○ Pa	• •
boiler areas, machinery ste from the barge(s), correcti	orage areas, wellded we action must be in	k or per voyage, whichever is more frequent (2) Locations to be inspected. Safely accessible deck and cargo hemicals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, cks and other areas). [Ref: VGP 4.1.1] (3) If poliulants or constituents of concern are determined to be originat intend. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	J	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clea	ned?	none
is the Water around the tifree of sheen?	parge 🔀	
Was a sample taken?		
North and the name of the same	. F*****	
Voids or Hopper Pumped Sheen present in wate		
pumping?		
Inspected by (Printed)	patrick dong	
Approved by (Printed)	Antonio Lopez	Approved by (Signature)
Ceresisa y pur Signet. (e fili. ponidensis kutesi	nduales Haribella	their have been respersed to accompance as sidinated about



Equipment:	CBX2054		Ve	sseVAsset	Aggie-C	
Company.	Canal Barge	Company			Illinois River	7 331.3
Inspection Date Time; (	06/06/2016	22.39		Location:		, 65 (.6
Load Status:	C Empty (	) Partial 🕲 L	oaded			
boiler areas, machinery at- from the barge(s), correct	orage areas, v ive action mus	rere chemicais, velidecks and o I be initiated. [R	oyage, whichever is more frequent oils, dry caigo, or other materials a ther areas). [Ref: VGP 4.1.1] (3) if ef: VGP 4.1.1] (4) The term "sheen oils [Ref VGP Fact Sheet 3.4.4]	ire Stored, mb Dollutants or (	ked and used (including	i, as applicable, cargo holds,
Are Decks Clean?	N		Any Violations Discovered	. during Insp	pection or any corre	ctive actions required?
If no, were decks clea	ned?				·	
is the Water around the i	barge ☑					
Was a sample taken?						
Voids or Hopper Pumpec	15 []					
Sheen present in wate pumping?	erafter []					
Inspected by (Printed)	r kulas					
Approved by (Printed)	Brad Bond		Approved	by (Signatu	ге)	_
Enlerng your Dignature Pru Grotiems Loted	ndicates that	the range(s) hi	s in Then vispected vi accordance i	8 <b>5</b> ខាងលេខខែសំខ	new Bro	& Bond



Equipment: F	B2234	Vessel/Asset: Aggie-C
Сотралу (	anal Barge Com	
Inspection Date Time: 0	6/08/2015 01	, 040 0
Load Status:	○Empty ○ Pa	
boiler areas, machinery sto from the barge(s), correction	rage areas, wellded	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo emicals, oils, dry cargo, or other materials are stored, moved and used (including, as applicable, cargo holds, as and other areas). [Ref: VGP 4.1.1) (3) If pollutants or constituents of concern are determined to be originating ated, [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	$oldsymbol{oldsymbol{arphi}}$	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clear	ned?	light sweeping
is the Water around the b	arge	
Was a sample taken?	C)	
Voids or Hopper Pumped	? []	
Sheen present in water pumping?	rafter 🗍	
Inspected by (Printed)	leffler	
Approved by (Printed) J	ohn Klaas	Approved by (Signature)
Entering your Signature Plv i	ndicales that the be	gets thave been inspected in accordance as indicated abov.



Equipment:	PB2351			Versel/Assel.	Aggie-C	
Company:	Canal Barge	Company			Illinois River	/ 328.8
Inspection Date Time: (	06/08/2015	01-22			CALUMET RIVER FLEI	
Load Status:	○ Empty (	Partial 🌘	Loaded		The second second second second	Linto
boiler areas, machinery sto from the barge(s), correcti	orage areas, wi ive action must	elidecks and a be initiated. If	vbyage, whichever is more fra , oils, dry cargo, or other mate other aress). [Ref: VGP 4.1.1] Ref: VGP 4.1.1] (4) The term oils [Ref VGP Fact Sheef 3.4	rrais are stored, mix   (3) if poliutants or c sheen" is to be unde	ed and used (including, as a	pplicable, cargo hokle,
Are Decks Clean?	₽		Any Violations Disco	vered during lasp	ection or any corrective	actions required?
flino, were decks clea	ned? []		light sweeping	- ·		zenona reguiteu:
Is the Water around the t	oarge ☑					
Was a semple taken?	О					
Voids or Hopper Pumped	i?					
Sheen present in wate pumping?	ar after					
Inspected by (Printed)	lieffler					
Approved by (Printed)	John Klaas		Appr	oved by (Signatur	re)	1 1
Entering your Signature PIV protiems noted.	indicates that	the bargers) h	ave Leen inspected in accord	ance as indicated at	An R	Doft.



Equipment:	CBX2020			Vessel/Asset	Apgie-C	
Company:	Canal Barg	e Company			Illinois River	/ 331.3
inspection Date Time:	06/08/2015	02:22		Location.		, 501.0
Load Status:	O Empty	O Partial 🕲	Loaded			
boiler areas, mechinery st from the barge(s), correct	orage areas, ive action mu	welldecks and st be intisted, (	voyage, whichever is more free s, cils, dry cargo, or other mater other areas; [Ref: VGP 4.1.1] Ref: VGP 4.1.1] (4) The term "s c cils [Ref VGP Fact Sheet 3.4	itals are stored, mb (3) If pollutants or ( been" is to be unde	ced and used (including	, as applicable, cargo holds,
Are Decks Clean?	[-	1	Any Violations Discov	ered during insp	ection or any corre	ctive actions required?
if no, were decks clea	ned?		bght sweeping		,	one actions roganics.
is the Water around the free of sheen?	barge 🗵					
Was a sample taken?	· []					
Voids or Hopper Pumper		affirmation and the second				
Sheen present in wate pumping?	erafter []	Attion				
(nspected by (Printed)	lleffler					
Approved by (Printed)	John Klaas		Аррго	oved by (Signatur	re)	. 1
ifmere glyd ei Tighature I.J. Brot Yerseintred	industes tha	t Medangala	in in the time the treatment of the	duk as no cated a	of the	and.



Equipment:	T13828		Vessel/Asset	Albert C	
Company:	Ingram Barge Co	mpany	Waterway:	Illinois River	/ 299.4
Inspection Date Time	06/08/2015 09	16	Location		7 200.4
Load Status:	○Empty ○Pa	artial 🏵 Loaded			
boiler areas, machinery s	storage areas, wellde ctive action must be in	cks and other areas) [R idiated, [Ref: VGP 4.1.1]	iver is more frequent (2) Locations b, or other materials are stored, mix ef: VGP 4.1.1] (3) If pollutants or o (4) The term "sheen" is to be under Fact Sheet 3.4.4]	ted and used (including	, as applicable, cargo holds.
Are Decks Clean?	V	Any Viol	ations Discovered during Insp	ection or any correc	Ctive actions required?
If no, were decks cle	aned?		- ,	, , , , , , , , , , , , , , , , , , , ,	
Is the Water around the	e barge				
Was a sample taker	s 🗀				
Voids at Hopper Pumpe					
Sheen present in wa pumping?	ler after				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signatur	re)	
Ectably you. Signature for problems acted	), inducates that the to	अञ्चलक । एवं एक एक एक हा आहा स	tted in assuradance as indicated at	in fiter	IN S to any

Equipment	ING5524		Ves	sel/Asset	Mary C.	
Company	Ingram Barge Cor	mpany			Illinois River	, 277
Inspection Date Time:	06/08/2015 09	50			Mobil Coke Spout	1211
Load Status:	○ Empty ○ Pa	rliat 🖲 Losded		E O CO HOTT.	Modifi Coke Spoti	
boiler areas, machinery s	torage areas, wellder tive action must be in	inted (Ref: VGP 4.1	[Ref: VGP 4.1.1] (3) if po	stored, mo	(eo and used (including, as	ccessible deck and carge s applicable, cargo fiolds, e determined to be originati of oit or grease, including
Are Decks Clean?	Ø	Any Vi	olations Discovered d	urina Insa	ection or any correcth	io actions required 2
If no, were decks clea	aned?			<b>-</b>	or day correction	se actions redailed s
s the Water around the free of sheen?	barge 🗹					
Was a sample taken'	? 🗆					
Voids of Hopper Pumpe	(_3					
Sheen present in wat pumping?	er after					
Inspected by (Printed)	BARNARD/KUN	ΓZ/WEAVER				
Approved by (Printed)	Robert Smith		Approved by	(Signatur	e)	
Ét teta) giyour Signature Pil problèms a eta d	i indicates that the ha	វឌ្គ ១(៦៧៤៩៦៩៩៩ ៣៩	ected in accordance as	indicated at	John Ser	methy way

Equipment:	N025311		V€sset/Asset:	Albert C	
Company:	ngram Barge Con	прапу	Waterway:	Illinois River	/ 293
Inspection Date Time (	06/08/2015 10:	20	Location:		, 223
Lead Status:	○ Empty ○ Par	rlial <b>®</b> Loaded			
boiler areas, machinery str	rage areas, wellded ve action must be int	iks and other areas). [Re tisted, [Ref: VGP 4.1.11	ver is more frequent. (2) Locations or other materials are stored, mix of: VGP 4.1.1] (3) If pollutents or c (4) The term "sheen" is to be undefact Sheet 3.4.4]	ed and used (including	g, as applicable, caryo holda,
Are Decks Clean?	I	Any Viola	itions Discovered during Insp	ection or any corr	ective actions required?
If no, were decks clear	nec?			,	
is the Water around the t free of sheen?	oarge ☑				
Was a sample taken?					
Voids or Hopper Pumped	? [_]				
Sheen present in wate pumping?	rafter 🔲				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signatur	e)	
Emering your Signature Pita problems noted	esticates that the ba	ageis - Nave been mubei	oted in accordance as indicated an	" Ister	Mr & Gar any



Equipment:	N025311			Vessel/Asset:	Albert C	
Cempany: J	ngram Barge	Company		Waterway:	Illinois River	/ 299.4
Inspection Date Time; 0	6/08/2015	11.45		Location:	SYS	7 200
Load Status:	○ Empty ()	Partial 🕲 Lo	paded			
boiler areas, machinery sto from the barge(s), correction	rage areas, we re action must b	ldecks and oth a indiated (Re	ons, ory cargo, or other mate ser areas: TRef: VCP 4.1.11	naks are stored, mix (3) if po#utants or ( sheen is to be unda	ed and used (includ	afely accessible deck and cargo ing, as applicable, cargo hokts, ern are determined to be originatin tration of oil or grease, including
Are Decks Clean?	<b>&gt;</b>		Any Violations Disco	vered during Insp	ection or any cor	rective actions required?
If no, were decks clear	ned?				·	1
is the Water around the b free of sheen?	arge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	? 🖂					
Sheen present in wate pumping?	rafter []					
Inspected by (Printed)	Peter Kosik					
Approved by (Printed)	<sup>D</sup> eter Kosik		Appr	oved by (Signalui	re)	
Foreign yn ar Signature fit. Dirblere eighed	odicales batis	ត បិនិស្មេ ១០២ភូទ	re then included a social	ance as indicated a	- Peter	My S tormay

Equipment:	IN025311		Vessel/Asset:	Albert C	
Company	Ingram Barge Cor	mpany	Waterway:	Minois River	/ 299.4
Inspection Date Time	06/08/2015 11	45	Location.		7 200.4
Load Status:	○Empty ○Pa	rtial ® Loaded			
boiler areas, machinery s	tarage areas, wellder tive action must be in	cks and other areas) Risted. (Ret: VGP 4.1.	thever is more frequent. (2) Locations 90. or other materials are stored, mix [Ref: VGP 4.1.1] (3) If pollutants or of 1] (4) The term "sheen" is to be under P Fact Sheet 3.4.4]	ed and used (includi	ng, as applicable, cargo holds,
Are Decks Clean?	V	Any Vi	olations Discovered during Insp	ection or any corr	rective actions required?
If no, were decks cle.	aned?			·	, , , , , , , , , , , , , , , , , , , ,
is the Water around the free of sheen?	barge ☑				
Was a sample taken	? 🗆				
Voids or Hopper Pumpe	d? [¨]				
Sheen present in wat	ice offine				
pumping?	El suel []				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signatur	·e)	
Entering your Signature Pil problems noted	indicales that the ba	stykis' have been ins	pecfed in accordance as indicated a	on leter	Jan & Grany

Equipment	IN025311		Vessel/Asset:	Albert C	
Company;	Ingram Barge C	Company		Illinois River	/ 299.4
Inspection Date Time	06/08/2015	12 35		IMT Lemont (Low	
Load Status:	○ Empty ○ F	adial (1) Loaded			or others
boiler areas, machinery str	orage areas, welk ive action must be	lecks and other areas)   Initiated   [Ref: VGP 4.1.	never is more frequent. (2) Locations go, or other materials are stored, mix Ref: VGP 4.1.1] (3) If pollutants or o 1] (4) The term "sheen" is to be unde P Fact Sheet 3.4.4]	ed and used (includin	g, as applicable, cargo holds,
Are Decks Clean?		Any Vi	plations Discovered during Insp	ection or any corre	Shariumar agnitos avitos
ll no, were decks clea	ned?			,	
Is the Water around the I free of sheen?	barge 🔀				
Was a sample laken?					
Voids of Hopper Pumped	17				
Sheen present in water pumping?					
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signatur	e)	
Entering your Dignature Par problems noted	indicates that the	bargers' have been ber	pacted in socardance as endicated at	sev Ster	Mis & for any

Equipment:	OR5212			Vessel/Asset.	Mary C	
Company:	Ingram Barg	e Company			Illinois River	) 277
inspection Date Time	06/08/2015	13:05			Mabil Coke Spout	) 241
Load Status:	○ Empty (	Partial ® Li	osded	2 position.	Mobil Ooke Opus	
boiler areas, machinery st	orage areas, vi	relidecks and off be initiated. (Re	her areas). [Ref: VGP 4.1. it: VGP 4.1.1 (4) The term	sterials are stored, mo .1] (3) if pollutants or o	s to be inspected: Safely a ked and used (including, as constituents of concern are cristood as a concentration	applicable, cargo holds,
Are Decks Clean?	N		Any Violations Disc	overed during Insp	ection or any correctiv	e actione required?
If no, were decks clea	ned?			_ ',		o serious requireur
is the Water around the free of sheen?	barge ☑					
Was a sample taken?						
Volds or Hopper Pumped	1? [_]					
Sheen present in wate pumping?	erafter 🗀					
Inspected by (Printed)	BARNARD/	KUNTZWEAY	VER			
Approved by (Printed)	Robert Smitt	n	Apj	proved by (Signatur	re)	
boterns your Signature Pita Stations only?	បាលិកាត់ម៉ោង ប៉ាក្រាង។	ë e 1 atgh⊊s⊹bh.	in beed my rivined in angle	೨ ೧೯೧೯ ಇಕ ಸಂಶಭಾಚಕನ at	That bes	with for any

Equipment	N995406			Vessel/Asset:	Albert C	
Company:	Ingram Bar	ge Company			Illinois River	<i>†</i> 293
	06/08/2015				OXBOW	7 233
Load Status:	O Empty	O Partial 🖲 L	osded		CHOCKY .	
boiler areas, machinery sta from the barge(s), correcti	orage areas, we action mu	welldecks and o st be initiated. IR	, blio, dry cargo, ar omer mater ther are≠x i li⊋ef: \/CDx 4 + 1 /	ials are stored, mo (3) if pollutaris or (	ced and used (includ	sfely accessible deck and cargo ing, as epplicable, cargo holds, ern are determined to be originatin tration of oil or grease, including
Are Decks Clean?	V	)	Any Violations Discove	ered during Insp	ection or any cor	rective actions required?
ll no, were decks clea	ned?	)			•	
	•					
Is the Water around the I free of sheen?	barge 🖸	}				
Was a sample taken?		)				
Voids or Hopper Pumped						
Sheen present in wate pumping?	erafter []					
Inspected by (Printed)	Peter Kosi	k				
Approved by (Printed)	Peter Kosil	k	Appro	ved by (Signalu	re)	
öntkinn yaar Siga ibise thi; ar rulenis solud	odicates em	रे पील १८४५७ हैं। इस्	au hour inspected by encorda-	rie as populated a	fiter	Mr S many

Equipment:	OR5337		\	vessel/Asset:	Midwest Pride	
Company	Ingram Barge	Company		Waterway:	Itlinais River	1 277
Inspection Date Time:	06/08/2015	16,05		Location	Mobil Coke Spout	,
Load Status:	○ Empty ○	Partial ® Lo	oaded		,	
boiler areas, machinery s from the barge(s), correc	ssible areas whe torage areas, we tive action must l	ere chemicals, o Hidecks and oth se initiated. [Re	yage, whichever is more freque oils, dry cergo, or other materials ner areas) {Ref: VGP 4.1.1} (3) f: VGP 4.1.1] (4) The term 'shea ils [Ref VGP Fact Sheet 3.4.4]	s are stored, mb If ontutants or a	ked and used (including, as constituents of concern as	s applicable, cargo holds,
Are Decks Clean?	<b>9</b>		Any Violations Discovers	ed during Inst	pection or any correcti	ve actions required?
lf no, were decks cle	aned?					
is the Water around the free of sheen?	barge 🔽					
Was a sample taken	?	and the second s				
Voids or Hopper Pumpe	d? []					
Sheen presentin wa pumping?	terafier []					
Inspected by (Printed)	patrick erick	son				
Approved by (Printed)	Tommy Walt	er	Approve	ed by (Signatu	,	
Entering your Rigoature Pr problems hoted	N industes that t	he bingers) he	ve boen megapted in annordand	e as mulcated a	abov .	s SAVAG



Vessel General Permit Compliance

Equipment	T13598		Vessel/Asset:	Mary C	9
Company:	Ingram Bar	ge Company	Waterway:	Illinois River	/ 277
Inspection Date Time	06/08/2015	21 00	Location:	Mohil Coke Upper	
Load Status:	○ Empt <sub>i</sub>	∕ ⊜Partial <b>®</b> Li	paded		
areas and all safety acc boiler areas, machinery from the barge(s), corre	ressible areas r storage areas, ective action mu	where chemicals, welldecks and ot ist be initiated. [Re	lyage, whichever is more frequent. (2) Location oils, dry cargo, or other materials are stored, miner areas? [Ref: VGP 4.1.1] (3) If pollutants or of: VGP 4.1.1] (4) The term "sheen" is to be und alls [Ref VGP Fact Sheet 3.4.4]	xed and used (including, as constituents of concern an	s applicable, cargo holds, re determined to be originatio
Are Decks Clean?		<b>a</b>	Any Violations Discovered during Ins	pection or any correcti	ve actions required?
if no, were decks c	eaned? [	ם ו			
is the Water around th	ne barge	ā			
Was a sample take	en? [	]			
Voids or Hopper Pump	pe <b>d</b> ? [				
Sheen present in w pumping?	/ater after [				
Inspected by (Printer	d) CALDRIC	H			and the second of the second
Approved by (Printed	t) Carl Aldri	ch	Approved by (Signat	ure) -	2/01

Entering your Signature PM, indicates that the bargets, have been inspected it accordance as modeted above and contective action has been intered for any problems included.



Vessel General Permit Compliance

Equipment:	CBX2021		Vessel/Asset:	Aggie-C	
Company	Canal Barge	Company	Waterway:	Illinois River	7 329.9
Inspection Date Time	06/09/2015	00 05	Location:	WALSH FLEET	
Load Status;	○ Empty	O Partial @	OLoaded		
areas and all safely acce boiler areas, machinery s from the barge(s), correc	ssible areas w torage areas, v tive action mus	here chemica weldecks and It be intlated.	r voyage, whichever is more frequent. (2) Location als, oils, dry cargo, or other materials are stored, mid other areas.) [Ref: VGP 4.1.1] (3) If pollutents or [Ref: VGP 4.1.1] (4) The term "sheen" is to be unduled oils [Ref VGP Fact Sheet 3.4.4]	ked and used (including, a constituents of concern a	is applicable, cargo holds, re determined to be originatin
Are Decks Clean?	v	# t- s.a.	Any Violations Discovered during Ins	pection or any correct	ive actions required?
if no, were decks de	aned? []		pumped out dow and stem tank		
is the Water around the free of sheen? Was a sample taken		1			
Voids or Hopper Pumpe	e <b>d</b> ? [✓				
Sheen present in wa pumping?	iterafter [				
Inspected by (Printed)	lawrence l	effler			
Approved by (Printed)	John Klaas	<b>;</b>	Approved by (Signate	ure)	Mod.
				1 the	( 1/30 T) I'

Estering your Bignature IPs indicates that the Largers' Lace peer it specified in apportance as indicated above profile is noted.



Equipment:	CBY261		Vessel/Asset:	Aggle-C	
Company	Canal Barge	e Company	Waterway:	Illinois River	/ 329.9
Inspection Date Time	06/09/2015	01 06	Lecation:	WALSH FLEET	
Load Status:	CEmpty	) Partial (	Loaded		
areas and all salely acces boiler areas, machinery si from the barge(s), correct	ssible areas v iorage areas, live action mu	vhere chemica welklecks and at be initiated.	voyage, whichever is more frequent. (2) Location is, oils, dry cargo, or other materials are stored, mit other areas.) [Ref: VGP 4.1.1] (3) If pollutants or [Ref: VGP 4.1.1] (4) The term "sheen" is to be und ic oils [Ref VGP Fact Sheet 3.4.4]	xed and used (including, as a constituents of concern are d	pplicable, cargo holds, fetermined to be originating
Are Decks Clean?	<b>~</b>	]	Any Violations Discovered during Ins	pection or any corrective	actions required?
If no, were decks clea	aned? [	]	pump bow and stern		
			pan pan anation		
•					
Is the Water around the free of sheen?	barge 🖸				
Was a sample taken	? [	)			
Voids or Hopper Pumpe	d? <u>√</u>				
Sheen present in wa pumping?	terafter [	)			
Inspected by (Printed)	heffler				
Approved by (Printed)	John Klaa	ş	Approved by (Signal	ure)	1
Fatering your Signature Pl propiems noted.	Do noticated th	al tre (argers	have been inspected to accordance as indicated	ure) att. Also Z	Doft.

Equipment:	CBY447		Vessel/Asset.	Aggie-C	
Company:	Canal Barge Com	ipany	Waterway:	Illinois River	7 329 9
Inspection Date Time	06/09/2015 01	06	Location:	WALSH FLEET	
Load Status:	○Empty ○Pa	rtial 🏵 Loaded			
areas and all safely acce boiler areas, machinery s from the barge(s), corret	essible areas where c storage areas, welder stive action must be in	themicals, oils, dry cargo, c cks and olher areas). [Ref	r is more frequent. (2) Locations other materials are stored, mix VGP 4.1.1) (3) If pollutents or of The term "sheen" is to be under Sheet 3.4.4)	ced and used (including, as constituents of concern ar	s applicable, cargo holds, re determined to be originating
Are Decks Clean?	<b>I</b>	Any Violat	ions Discovered during Insp	pection or any correcti	ve actions required?
If no, were decks cle	aned?				
Is the Water around the free of sheen?	e barge				
Was a sample taker	1?				
Voids or Hopper Pamp	e <b>d</b> ? [¨`]				
Sheen present in wa pumping?	1				
Inspected by (Printed	) Iteffler				
Approved by (Printed)	John Klaas		Approved by (Signate	ıre)	-1 1
Potonico year Pignetian F Scottenis cioled	Mil industrial that the city	raign(s) have been reper	ed in annerd rechies indicated r	and for	Work.

Equipment:	CBX2107		Vessel/Asset	: Aggie-C	
Company:	Canal Barg	e Company	Waterway	: Illinois River	7 329.9
Inspection Date Time	06/09/2015	02 38	Location	: WALSH FLEET	
Load Status:	○ Empty	OPartial <b>®</b> (	_oaded		
areas and all safely acc boiler areas, machinery from the barge(s), corn	cessible areas ( storage areas, ective action mu	where chemicals welldecks and ( ast be initiated, [F	royage, whichever is more frequent. (2) Location, oils, dry cargo, or other materials are stored, mother areas). [Ref: VGP 4.1.1] (3) If pollutants or left VGP 4.1.1] (4) The term "sheen" is to be unoblis [Ref VGP Fact Sheet 3.4.4].	ixed and used (including, as constituents of concern are	s applicable, cargo holds, e determined to be origination
Are Decks Clean?	S	9	Any Violations Discovered during Ins	pection or any corrective	ve actions required?
lfino, were decks c	leaned? [	)			
is the Water around ti	ne barge 🛭 🛭	0			
Was a sample take	en?	]			
Voids or Hopper Pum	ped?	]			
Sheen present in v pumping?	vater after				
Inspected by (Printer	d) larry leffle	ı			
Approved by (Printed	i) John Klaa	S	Approved by (Signat	ure)	M
Corendo vol i Sicentica	Characterist in	at the loares of t	to be the and the state of the second transfer on the second	the 1	The second second



Equipment t	MT 105			VessellAsset	Aggie-C	
Company: 0	Canal Barge	Company			Illinois River	/ 329.9
Inspection Date Time: (	06/09/2015	02:38		Location:	WALSH FLEET	
Load Status:	O Empty (	] ® leitne P	_oaded			
areas and all safely acces boiler areas, machinery sti from the barge(s), correct	sible areas wi orage areas, v ive action mus	rere chemicals velidecks and o t be initiated. [R	royage, whichever is more free, oils, dry cargo, or other mate other areas). [Ref: VGP 4.1.1] lef: VGP 4.1.1] (4) The term "s oils [Ref VGP Fact Sheet 3.4	rials are stored, mix (3) If pollutents or o theen" is to be unde	ed and used (including, as constituents of concern are	s applicable, cargo holds, e determined to be prininatio
Are Decks Clean?	<b>☑</b>		Any Violations Discov	rered during insp	ection or any correcth	ve actions required?
If no, were decks clea	ned? []					
Is the Water around the free of sheen?	barge 🗹					
Was a sample taken?	, 🗀					
Voids or Hopper Pumper	#? []					
Sheen present in wate pumping?	eratter 🗍					
Inspected by (Printed)	larry leffler					
Approved by (Printed)	John Klaas		Аррг	oved by (Signatu	re)	1 1
Emering your Dignative Pt professioned	endandes ma	the targets of	teve oppelings buy din someth	ande as equipated a	res	Thoft.



Equipment:	N995406		Vessel/Asset:	Windy City	
Company: l	ngram Barge Con	npany	Walerway	Illinois River	y 299,4
Inspection Date Time: (	06/09/2015 07 :	35	Location:	IMT Lemont (Lower	Crane)
Load Status:	○ Empty ○ Par	tiai 🌘 Loaded			
boiler areas, machinery sto	sible areas where ch prage areas, wellded we action must be inf	nemicals, oils, dry cargo, o ks and other areas). [Ref: liated. [Ref: VGP 4.1.1] (4	is more frequent (2) Locations of the materials are stored, moving 4.4.4] (3) If pollutants or of the term "sheen" is to be under 1 Sheet 3.4.4]	ced and used (including, constituents of concern	as applicable, cargo holds, are determined to be prininglish
Are Decks Clean?	$\square$	Any Violati	ons Discovered during Insp	pection or any correc	tive actions required?
If no, were decks clea	ned?				
is the Water around the lifee of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	J? []				
Sneen present in wate pumping?	er after				
Inspected by (Printed)	enc hanson				
Approved by (Printed)			Approved by (Signatu		
Entering your Signature PM numbers nated	i addates that the ba	tige s) have teen inspect	ed in accordance as indicated a	no Danie	1 Cullinger

Equipment:	OR4832		Ves:	sel/Asset Eil	een C	
Company:	ngram Barge Cor	mpany	,	Vaterway: IIIir	nois River	ı 277
Inspection Date Time: I	06/09/2015 09	44		Location: Mo	abil Cake Spout	
Load Status:	O Empty O Pa	rtial <b>©</b> Loadert			•	
Instructions:  (1) This form is to be compareds and all safely accessionler areas, machinery stafform the barge(s), correct lubricating oils, hydraulic o	sidie brebs where c drage areas, welider ive action must be in	inemicals, oils, dry carg iks and other areas) [f itiated, [Ref: VGP 4.1.f	o, or other materisis are Ref: VGP 4.1.1] (3) If po I (4) The term "sheen" is	stored, mixed a	and used (including, a	is applicable, cargo holds,
Are Decks Clean?		Any Vio	lations Discovered d	iuring Inspect	tion or any correcti	ive actions required?
lf no, were decks clea	ned? []					
is the Water around the free of sheen?	barge 🕝	THE TANK THE				
Was a sample taken?						
Voids or Hopper Pumped	J? []					
Sheen present in wate pumping?	erafter 🗍					
Inspected by (Printed)	austin brauns					
Approved by (Printed)	Curtis Lagsdon		Approved by	y (Signature)		1
Entering your Signature Pt. problems noted	indicates that the hi	argeischaue been insp	ected in accordance as	indicated abov	Cuith	gallyo-

Equipment: If	V135454			Vessel/Asset	Albert C	
Company. h	igram Barge Co	япрапу		Waterway:	Illinois River	1 293
Inspection Date Time 0	6/09/2015 10	0.55		Location:	OXBOW	
Load Status:	○ Empty ○ Pi	artial <b>©</b> Loaded				
boiler areas, machinery sto	sible areas, where rage areas, wellde ve action must be i	chemicals, oils, dry ca ecks and other areas) niliated. [Ref: VGP 4,1	irgo, or other material [Ref: VGP 4.1.1] (3) [.1] (4) The term "she	s are stored, mid of poliutants or e en" is to be unde	ted and used (includ constituents of conc	afely accessible deck and cargo ling, as applicable, cargo holds, ærn are determined to be origination tration of o'l or grease, including
Are Decks Clean?	$oldsymbol{\bigcirc}$	Any V	iolations Discover	ed during Insl	pection or any cor	rrective actions required?
if no, were decks clear	ned?					
is the Water around the t	oarge 🗹	1				
Was a sample taken?	[_]	AND THE PROPERTY AND TH				
Voids or Hopper Pumped	?					
Sheen present in wate pumping?	ri after 🔲					
Inspected by (Printed)	Peter Kosik					
Approved by (Printed)	Peter Kosik		Approv	ed by (Signati	ire)	
- Edler ng yosh Dignature Për Jesifena in Jeo	adicates that the	nament hove thes s	sympted in accordan	Ce as (१वंग, १४८३)	no liter	S to any

Equipment:	13598		,	Vessel/Asset.	Mary C	
Company: }	ngram Barge Co	mpany		Waterway:	Illinois River	, 278
Inspection Date Time: (	06/09/2015 11	55		Location:	IMT Chan (Crane)	)
Łoad Status:	○ Empty ○ Pa	rtial 🌘 Loaded				
<ul> <li>areas and all safety acces</li> <li>boiler areas, machinery sto</li> </ul>	sible areas where r trage areas, wellde live action must be in	themicals, oils, dry o cks and other areas illiated. [Ref: VGP 4	cargo, or other material () [Ref: VGP 4.1.1] (3) (1.1] (4) The term "she	is are stored, mid ) if poliutants or a :en" is to be und	ced and used (includir constituents of conce	fely accessible deck and cargo ng, as applicable, cargo holds, rn are determined to be originating ration of oil or grosse, including
Are Decks Clean?	<b></b>	Any	Violations Discover	ed during Insp	pection or any corr	rective actions required?
If no, were decks clea	neď?					
Is the Water around the free of sheen? Was a sample taken?						
Voids or Hopper Pumper	d? [7]					
Sheen present in wat pumping?						
inspected by (Printed)	BARNARD/KUI	NTZ/WEAVER				
Approved by (Printed)	Robert Smith		Аррточ	red by (Signati	ire)	
Paterna yawi Siyasi ne fil esane ne milaz	a istrinates abetifae i	ាស់ដូក្ខាស់ ស្នាល់ស្នាស់ សមាន	ಗ್ 1 -ಗಾಹೀಭ ಗ ಹಿರ್ದೇ∮ಕರ	De as extreated	Toket b	white for so,

#### Vessel General Permit Compliance

Equipment: If	N135454	Vessel/Asset.	Windy City	
Company: 1	ngram Barge Cor	ripany Waterway:	Illinois River / 299 4	
Inspection Date Time (	16/ <b>0</b> 9/ <b>2</b> 015 12	20 Location:	IMT Lemont (Lower Crane)	
Load Status:	○ Empty ○ Pa	tial 🏵 Loaded		
eress and all safety acces boiler areas, machinery sto from the barge(s), correcti	sible areas where c trage areas, wellde we action must be in	tor per voyage, whichever is more frequent. (2) Location hemicals, oils, dry cargo, or other materials are stored, micks and other areas.) [Ref: VGP 4.1.1] (3) If pollutants or tisted. [Ref: VGP 4.1.1] (4) The term "sheen" is to be undorganic oils [Ref VGP Fact Sheet 3.4.4]	xed and used (including, as applicable, cargo hold constituents of concern are determined to be prior	is, inalino
Are Decks Clean?	$\square$	Any Violations Discovered during ins	pection or any corrective actions required?	?
If no, were decks clea	ned?			
is the Water around the free of sheen?	barge 🗹			
Was a sample taken?	[]			
Voids or Hopper Pumper	1?			
Sheen present in wate pumping?	erafter []			
Inspected by (Printed)	Paul Roman			
Approved by (Printed)	Faul Roman	Approved by (Signati	are) Apolinanhaman	e D
Entering your Signature Fit	and cases that the t	argn(s) have been lespelled in accordance as indicated	806V	

VGPEXCHANGE

acoptems noted

Equipment:	MG5524		Vessel/Asse	Mary C	
Company:	lagram Bar	ge Company	Waterway	r Illinois River	7 278
Inspection Date Time:	06/09/2015	12 45	Location	: IMT Chan (Crane)	
Load Status:	○ Empty	O Partial 🌘	Loaded		
sreas and all safely acce boiler areas, machinery s from the barge(s), correc	ssible areas v torage areas, tive action mu	where chemicals welldecks and i ist be initiated. [I	voyage, whichever is more frequent. (2) Locatio i, oils, dry cargo, or other materials are stored, n other areas). [Ref: VGP 4.1.1] (3) If pollutants of Ref: VGP 4.1.1] (4) The term "sheen" is to be un oils [Ref VGP Fact Sheet 3.4.4]	nxed and used (including, a constituents of concern a	es applicable, cargo holds, re determined to be originatio
Are Decks Clean?	Ę	a	Any Violations Discovered during In:	spection or any correct	ive actions regulred?
lf no, were decks cle	aned? [ <u>"</u>	]			
is the Water around the free of sheen?	e barge	<u> </u>			
Was a sample taken	15 [	<b>3</b>			
Voids or Hopper Pumpe	ed? [				
Sheen present in wa pumping?	iterafter [	]			
inspected by (Printed)	BARNAR	D/KUNTZ/WE	AVER		
Approved by (Printed)	Robert Sr	nith	Approved by (Signa	ture)	
nmersig your Signature k your kins acts 3	°N 0.06 AE+S ti	ाती में स्वीत सहस्र (s.)	ិស ខេ ភិក្សា ស្រី៤ ២៧៦៩ a (១០ភាពខេត្តប្រភព អនុ សនិយន់ដែល	That he	Southly torany



Vessel General Permit Compliance

Equipment I	N135454			Vessel/Asset: VVir	idy City	
Company:	ingram Barge C	ompany		Waterway: Illin	ois River	1 299.4
Inspection Date Time:	06/09/2015 1	3:00		Location: IMT	Lemont (Lower Crane)	
Load Status:	○ Empty ○ F	artial 🕲 Loaded	j			
breas and all safely acces boiler areas, machinery st	isible areas where orage areas, walki ive action must be	chemicals, oils, dr ecks and other are initiated. [Ref: VG	ry cargo, or other mate eas) [Ref: VGP 4.1.1] P 4.1.1] (4) The term "	riels are stored, mixed a (3) if pollutants or const sheen" is to be understo	be inspected: Safety accessible indused (including, as applicate tituents of concern are determined as a concentration of oil or	ble, cargo holds, ined to be originating
Are Decks Clean?	$\Box$	А	ny Violations Dieco	vered during Inspect	ion or any corrective actio	ns required?
If no, were decks clea	rned?					
is the Water around the free of sheen?	barge ☑					
Was a sample taken'	? []					
Voids or Hopper Pumpe	d? []					
Sheen present in wat pumping?	erafter 🗍					
Inspected by (Printed)	Paul Roman					
Approved by (Printed)	Paul Roman		ДФД	roved by (Signature)	Apolinant	Resortato
Entering your Signature Pl	- marcales that the	targe(s) have ce	ег жүрөстеб ю арспл	sance as indicated show		_



procland inted

Equipment:	IN107013		Vessel/Asset	Eileen C	
Company:	Ingram Barge Co	mpany	Walerway:	Illinois River	1 277
Inspection Date Time:	06/09/2015 13	38	Location:	Mobil Coke Spout	
Load Status.	○ Empty ○ Pa	rtial 🖲 Loaded			
areas and all safety acc boiler areas, machinery from the barge(s), corre	essible areas, where o storage areas, welloe ctive action must be in	themicais, pils, dry cargo, or ( pks and other areas) [Ref: V	s more frequent (2) Location: uther materials are stored, mor GP 4.1.1] (3) It pollutants or of the term "sheen" is to be under Sheet 3.4.4]	ed and used (including, as constituents of concern ar	s applicable, cargo holds e determined to be originating
Are Decks Clean?	$ \mathbf{Z} $	Any Violatio	as Discovered during Insp	pection or any correcti	ve actions required?
If no, were decks di	eaned? []				
is the Water around th	e barge 🔽				
Was a sample take	n?				
Voids or Hopper Pump	ed?				
Sheen present in w pumping?	ater after				
Inspected by (Printed	) austin brauns				
Approved by (Printed	) Curtis Logsdon		Approved by (Signatu	ire)	Jandon
Enter up year Dignature modiferationed	PPI in housies II at the it	គឺវិទ្ធិកាទ ពិស មេ ២៩៩៩ កាន់ពុទ្ធប្រើបារ	strach, rdachde as malicated a	ator Owner	0395



Vessel General Permit Compliance

Equipment.	IN075026		Ve	ssel/Asset: A	ggie-C	
Company.	Ingram Barge	Company		Waterway: III	inois River	/ 298
Inspection Date Time	06/09/2015	16 15		Location: IN	AT Lemont (NRF)	
Load Status:	○ Empty (	Partial 🖭	Loaded		, ,	
boiler areas, machinery from the barge(s), corre	essible areas wi storage areas, w ective action must	iere chemicals relidecks and d . be initiated. [A	royage, whichever is more frequent, oils, dry cargo, or other materials a other areas). [Ref: VGP 4.1.1] (3) if Ref: VGP 4.1.1] (4) The term "shean oils [Ref VGP Fact Sheet 3.4.4]	re stored, mixed poliulants or cor	l and used (including, : istituents of concern a	as applicable, cargo holds, ce determined to be origination
Are Decks Clean?	$\square$		Any Violations Discovered	during Inspec	ction or any correct	ive actions required?
lf no, were decks of	eaned?					
is the Water around th	ne barge 🗹					
Was a sample take	n?					
Voids or Hopper Pump	ed?					
Sheen present in w pumping?	rater after					
Inspected by (Printed	l) rkulas					
Approved by (Printed	) John Klaas		Approved	Signature) על	M	Mod.

Inverse g(y) in Signature  $\Omega$  , in that is in a line through the vertices in apportunity and condended in assertunity and the second 


Vessel General Permit Compliance

Equipment	M107015		Vessel/As	set: Aggie-C		
Company:	Ingram Barge Cor	трапу	Water	way: Illinois Riv	√€1	/ 298
Inspection Date Time	06/09/2015 16	16	Loca	tion, HVIT Lemo	ont (NRF)	
Load Status:	○ Empty ○ Pa	rtial 🏵 Loaded				
areas and all safety acce boiler areas, machinery s	ssible areas where o lorage areas, wellde: tive action must be in	hemicals, oils, dry c cks and other areas itiated. [Ref; VGP 4	nichever is more frequent. (2) Loc eargo, or other materials are store ). [Ref: VGP 4.1.1] (3) If poliutan. 1.1] (4) The term "sheen" is to be VGP Fact Sheet 3.4.4]	d, mixed and used is or constituents	d (including, as applicat of concern are determ	ble, cargo holds. líned to be originatin
Are Decks Clean?	$\square$	Any	Violations Discovered during	Inspection or	any corrective actio	ns required?
If no, were decks clea	aned?					
is the Water around the free of sheen?	barge 👩					
Was a sample taken	?					
Vaids or Hopper Pumpe	ed? 🗀					
Sheen present in wa pumping?	terafler					
Inspected by (Printed)	rkulas					
Approved by (Printed)	John Klaas		Approved by (Si	gnature)	بر سر	1 1
Beternig your Signature F problems ealed	Hi indicates that the b	iarge (e - have then	inspensed & accordance as endic	ated abov	An W	of.

VGPEXCHANGE

Vessel General Permit Compliance

Equipment:	N117537			Vessel/Asset	Aggie-C	
Company:	Ingram Barge Cor	npany		Waterway:	Illinois River	/ 298
Inspection Date Time	06/09/2015 16:	16		Location:	IMT Lemont (NRI	F)
Load Status:	○Empty ○Pa	rtial <b>©</b> Loaded			,	,
boiler areas, machinery st	isible areas where c orage areas, wellded we action must be ini	hemicals, oils, dry c :ks and other areas listed. [Ref: VGP 4	argo, or other materia ) [Ref: VGP 4.1.1] (3 .1.1] (4) The term "shi	is are stored, mo } if poliutants or o een" is to be unde	ked and used (includi constituents of conce	fely accessible deck and cargo ng, as applicable, cargo holds, am are determined to be originatio ration of oil or grease, including
Are Decks Clean?	[\overline{\sigma}]	Any	Violations Discove	red during Ins	ection or any corr	rective actions required?
If no, were decks clea	ined?					
is the Water around the free of sheen?	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumpe	d? []					
Sheen present in wat pumping?	•					
Inspected by (Printed)	rkulas					
Approved by (Printed)	John Klaas		Approv	ved by (Signalu	ire)	-4 1
Entervig your Bignature Pa problems noted	Codustes that the in	arge(8) bake baer :	ខុសភូមិជាម្ចាប់ ២ ៤០០១១៨៩៧	ល់ 85 មជាក់គាត់នៃ វ	abov Chipa	Moff.

VGPEXCHANGE

Equipment:	T13828		Vessel/Asset	Aggie-C	
Company:	ngram Barge Cor	mpany	Waterway:	Illinois River	/ 298
Inspection Date Time: (	05/09/2015 16	16	Location:	IMT Lemont (NRF)	
Load Status	○Empty ○Pa	rtial 🎱 Loaded		1 -	
boller areas, machinery str	ision breas where c orage areas, weilder live action must be in	nemicals, oils, dry carg iks and other areas) (i fieted [Ref: VGP 4.1.1	ever is more frequent. (2) Locations o, or other materials are stored, mix Ref: VGP 4.1.1) (3) If pollutants or o ] (4) The term "sheen" is to be under Fact Sheet 3.4.4]	ed and used (including, as constituents of concern ar	s applicable, cargo holds,
Are Decks Clean?	$\checkmark$	Any Vio	lations Discovered during Insp	ection or any correctiv	/e actions required?
If no, were decks clea	ned?				
		55 L			
Is the Water around the free of sheen?	barge 🔽				
Was a sample taken?					
Voids or Hopper Pumper	¥3				
Sheen present in wate pumping?	eraffer []				
Inspected by (Printed)	rkulas				
Approved by (Printed)	John Klaas		Approved by (Signatu	r <del>e</del> )	1 1
Entering your Rightainee Al modifiers noted	r nationles that the h	aigē s have heen ner	ented in anuncidance as eldicated a	ner of the	Moff.



Equipment: (	CBX2135		Vessel/Asset:	Mary C	
Company: (	Canal Barge Com	ipany	Waterway:	Illinois River	/ 279
Inspection Date Time (	06/09/2015 16	27	Location:	Empty Fleet	
Load Status:	<b>⑤</b> Empty ○ Pa	rtial 🔿 Loaded		. ,	
boiler areas, machinery sto	sible areas, where c brage areas, welided we action must be in:	hemicals, oils, dry carr cks and other areas). [ itisted. [Ref: VGP 4.1.]	never is more frequent. (2) Location yo, or other materials are stored, mid Ref: VGP 4.1.1] (3) If pollutants or I] (4) The term "sheen" is to be undo P Fact Sheet 3.4.4]	ted and used (including, as	s applicable, cargo holds,
Are Decks Clean?	Image: Control of the	Any Vic	plations Discovered during Insp	pection or any correctiv	ve actions required?
If no, were decks clea	ned? []				,
is the Water around the ti	barge 🗹				
Was a sample taken?		T T T T T T T T T T T T T T T T T T T			
	•	} 			
Voids of Hopper Pumped	P? []				
Sheen present in water pumping?	er after	Managaraphy— at you			
inspected by (Printed)	BARNARD/KUN	tz/weaver			
Approved by (Printed)	Robert Smith		Approved by (Signatu	ire)	
Entering your Signature Pilv problems noted	indinates that the no	ørgris, bøve toen mis	rected in accordance as indicated a	snow Johel Cur.	nutty locary

Equipment:	H995400		Vessel/Asset:	Midwest Pnde	
Company:	ngram Barge Cor	npany	Waterway:	Illinois River	ı 277
Inspection Date Time:	06/09/2015 18	50	Location:	Mobil Coke Spout	
Load Status:	○ Empty ○ Pai	rtial 🏵 Loaded			
boiler areas, machinery sti from the barge(s), correct	isible areas where c prage areas, wellded ive action must be int	hemicals, elis, dry cargo, er iks and ether areas'i [Ref:	The term "sheen" is to be unde	ced and used (including constituents of concer	g, as applicable, cargo halds.
Are Decks Clean?	$\overline{\mathbf{v}}$	Any Violatio	ns Discovered during Ins	pection or any corre	ective actions required?
If no, were decks clea	ned?				·
Is the Water around the free of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumper	<b>:</b>				
Sheen present in wat pumping?					
Inspected by (Printed)	jason franklin				
Approved by (Printed)	Tyshun Griffin		Approved by (Signate	re)	
Esternis yella Righafara kil problema notes	i indicates that the by	nge si have deen inspecte	5 in accordance as indicated s	shev ——	I down



Equipment	IN946400		Vessel/Ass	set: Windy Cit	у	
Company	Ingram Bargi	Company	Waterw	ray: Illinois Riv	er	/ 293
Inspection Date Time:	06/09/2015	18.55	Locati	on. OXBOW		
Load Status:	() Empty (	DPartial 🕲	Loaded			
boiler areas, machinery st from the barge(s), correct	ssible areas wi lorage areas, w live action mus!	iere chemicals relidecks and be initiated. [1	voyage, whichever is more frequent. (2) Lock, oils, dry cargo, or other materials are stored other areas). [Ref: VGP 4.1.1] (3) If pollutants Ref: VGP 4.1.1] (4) The term "sheen" is to be oils [Ref VGP Fact Sheet 3.4.4]	mixed and used or constituents of	l (including, as applical of concern are determ	ble, cargo holds, ined to be orinipating
Are Decks Clean?	Image: section of the		Any Violations Discovered during	Inspection or a	By corrective actio	ns required?
If no, were decks clea	aned? []	Alle five te chabe de reconstruit e				
Is the Water around the free of sheen?	barge 🗸	Appendix and the special speci				
Was a sample taken	?					
Voids or Hopper Pumpe						
Sheen present in wat pumping?	ier aner					
Inspected by (Printed)	eric hansor	ı				
Approved by (Printed)	David Cullin	an	Approved by (Sign	•		
Farettikg your Signature Pl goos kinns noted	I. noldates toat	rhe bargeis.	Nave been a specified in accordance as indica	led abov. A	Paul C	ellinor

Equipment:	IN946400		Ve	essel/Asset:	Windy City	
Company:	Ingram Barge	Company		Waterway:	Illinois River	7 299.4
Inspection Date Time:	06/09/2015	20 05		Location:	SYS	
Load Status	○Empty ○	Partial <b>®</b> £0	Daded			
boiler areas, machinery s from the barge(s), correc	asibie bleas vyn Aprage breas, w. Hive action must	ere chemicals, i Blocks and off be inflated. [Re	yage, whichever is more frequent offs, dry cargo, or other materials a ner areas) [Ref: VGP 4.1.1] (3) If if: VGP 4.1.1] (4) The term "sheen ils [Ref VGP Fact Sheef 3.4.4]	are stored, ind Containents or	ked and used (including	y, as applicable, cargo holds.
Are Decks Clean?	[ <del>]</del>		Any Violations Discovered	d during Insi	pection or any corre	ective actions required?
If no, were decks cle	aned?					, , , , , , , , , , , , , , , , , , ,
Is the Water around the Iree of sheen?	barge 🗸					
Was a sample taken	?					
Voids or Kopper Pumpe	L,					
Sheen present in wa pumping?	terafter [					
Inspected by (Printed)	eric hanson					
Approved by (Printed)	David Cullina	ח	Approved	i by (Signatu	ıre)	
Entering your Signature Pl viothers noted	th indicates that t	he barge(s) ha	ve taan inspected in accordance	85 ಗಡಿಸುಕ್ಕಳ	ster Hair	1 Culling



Equipment	CBX2135		Vessel/Asset	Aggie-C	
Company:	Canal Barg	e Company	Waterway	Illinois River	1 279
Inspection Date Time	06/10/2015	60 10	Location	Dock Barge Fleet	
Load Status:	Empty	OPartial C	Loaded		
boiler areas, machinery st from the barge(s), correct	ssible areas v orage areas, tive action mu	there chemics welldecks and st be initiated.	r voyage, whichever is more frequent. (2) Location ils, oils, dry cargo, or other materials are stored, mid other greas). (Ref: VGP 4.1.1) (3) if pollutants or [Ref: VGP 4.1.1] (4) The term "shaen" is to be und ic oils [Ref VGP Fact Sheet 3.4.4]	ixed and used (including, a constituents of concern a	is applicable, cargo holds, re determined to be origination
Are Decks Clean?	G	1	Any Violations Discovered during Ins	pection or any correct	ive actions required?
f no, were decks clea	aned? [	)			
is the Water around the	barge	1			
free of sheen?	oarge 2	j			
Was a sample taken	? [	) [			
Voids or Hopper Pumpe	d? [	]			
Sheen present in wal pumping?	lerafier [	]			
Inspected by (Printed)	larry lefile				
Approved by (Printed)	John Klaa	3	Approved by (Signat	ure)	-1
Entering your Signati re Pl our blens noted	li naicates ti.	al tha traigeis	thave treen inspected to accordance as inclosed	story of the	Work.

Equipment: (	DBX2135		Vessel/Asset:	Windy City	
Company: (	Canal Barge Con	npany	Waterway:	Illinois River	/ 298
Inspection Date Time: (	6/10/2015 06	52	Location:	IMT Lemont (NRF)	
Load Status:	⊕ Empty ○ Pa	artial 🔾 Loaded			
areas and all safety acces boiler areas, machinery sig from the barge(s), correcti	sible areas where orage areas, wellde ve action must be in	chemicals, oils, dry cargo, or cks and other areas) [Ref:	is more frequent. (2) Lacations other materials are stored, mix VGP 4.1.1) (3) If pollutants or control to the term "sheen" is to be under Sheet 3.4.4)	ed and used (including, a constituents of concern a	as applicable, cargo holds. The determined to be originating
Are Decks Clean?	[ <del>-</del> ]	Any Violatio	ns Discovered during Insp	ection or any correct	tive actions required?
If no, were decks clea	ned?				
is the Water around the tree of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumper	ı? 🗀				
Sheen present in water pumping?	er after				
Inspected by (Printed)	eric hanson				
Approved by (Printed)	David Cullinan		Approved by (Signatu	ire)	
Thirting yero Signatuse PP	Endicates that me i	i argers, have been inspecto	ន៍ ៩) accordance as indicated a	ne December	Bulling

Equipment:	IN946400		Vessel/Asset Windy City	
Company:	Ingram Barge	Company	Waterway, Illinois River	1 299.4
Inspedion Date Time	06/10/2015	07.35	Location: IMT Lemont (Lower Crane)	
Load Status:	○ Empty (	) Partial 🎱 (	Loaded	
bries and all safely acce boiler areas, machinery s from the barge(s), correc	ssible areas wh torage areas, w tive action must	ere chemicals elidecks and o be initiated. [R	regage, whichever is more frequent. (2) Locations to be inspected: Safely accessible, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable) ther areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to the con	le, cargo holds. Sed to be origination
Are Decks Clean?	[ <del>·</del> ]	1	Any Violations Discovered during Inspection or any corrective action	is required?
If no, were decks cle	aned?			
is the Water around the tree of sheen?	e barge			
Was a sample taker	17			
Voids or Hopper Pumpe	e <b>d</b> ? []			
Sheen present in wa pumping?	terafter []			
Inspected by (Printed)	eric hanson			
Approved by (Printed)	David Cullin	an	Approved by (Signature)	
Entering your Supestine D Crobleme Hoted	II. nowales bat	Y c bargely r	TWO FEET PERSONS OF ACTION DATES AN INDICATED AT EACH AT ON Described AT ON Described AT ON THE ACTION OF THE ACTI	ellinal

Vessel General Permit Compliance

Equipment:	IN075415		Vessel	l/Asset.	Midwest Pride	
Company	Ingram Barge Co	mpany	Wa	terway:	Illinois River	ı 277
Inspection Date Time:	06/10/2015 09	9 50	Lo	cetion.	Mobil Cake Upper	
Load Status	() Empty () Po	artial 🏵 Loaded				
areas and all safely acci boiler areas, machinery:	essible areas where storage areas, wellde ctive action must be i	chemicals, oils, dry c ecks and other areas nitisted. [Ref; VGP 4,	ichever is more frequent. (2) t argo, or other materials are sto (Ref: VGP 4.1.1) (3) if point 1.1] (4) The term "sheen" is to GP Fact Sheet 3.4.4]	ored, mix tents or c	ed and used (including, as ap constituents of concern are di	oplicable, cargo holds, etermined to be originating
Are Decks Clean?	$\square$	Any	Violations Discovered dur	ing Insp	ection or any corrective	actions required?
If no, were decks cle	eaned?					
is the Water around the	e barge 💟					
Was a sample taker	us 🗀					
Voids or Hopper Pump Sheen present in wanter pumping?	ateratter []					
Approved by (Printed)			Approved by (	Sionatu	16)	n/ Plda
	•			2.9-1010		- U V

Fits any must be easily adjusted district marger of move us to a pended to provide a consisted the confidence and entertain action has been an acid to acy provides in text.



Equipment: C	BX2136			Vessel/Asset.	Windy City	
Company: C	Canal Barge C	Company		Waterway	Illinois River	/ 299.4
Inspection Date Time: 0	6/10/2015	10 35		Location.	SYS	
Load Status:	<b>©</b> Empty ○	Partial () L	oaded			
ereas and all safely access boiler areas, machinery sig from the barge(s), correcti	sible areas whe rage areas, we ve action must t	re chemicals, lidecks and of se initiated, [Re	oils, dry cargo, or other mat her areas) [Ref: VGP 4.1.1	erisls are stored, mit ] (3) If pollutants or "sheen" is to be und	xed and used (includin constituents of concer	ely accessible deck and cargo ig, as applicable, cargo holds, in are determined to be originating ation of oil or grease, including
Are Decks Clean?	$\mathbf{V}$	-	Any Violations Disco	overed during Ins	pection or any corre	ective actions required?
lfino, were decks clear	ned?					
Is the Water around the I	oarge 🔽					
Was a sample taken?						
Voids or Hopper Pumped	l? [ˈ]					
Sheen present in wate pumping?	***					
Inspected by (Printed)	eric hanson					
Approved by (Printed)	David Cullina	n	Арр	proved by (Signati	•	
Emethig your Nighather Pl 2016 of Science	inductes Basi	hi tagan h	क्यर हारका अन्त्र स्टास्ट के रहर है।	dance an olderated	ster Marc	I Cullinger

Vessel General Permit Compliance

Equipment:	CBX2135		Vessel/Asset: V	Vindy City	
Company:	Canal Bar	ge Compa	ny Waterway: III	linois River	/ 298
Inspection Date Time:	06/10/201	5 06.52	Location: IN	VIT Lemont (NRF)	
Load Status:	<b>⊕</b> Emp	ty 🔾 Partia	I 🔾 Loaded		
areas and all safely acc boiler areas, machinery from the barge(s), corra	essible areas storage area: ctive action n	where cher s, welldecks aust be initiat	per voyage, whichever is more frequent. (2) Locations to nicals, oils, dry cargo, or other materials are stored, mixed and other areas). [Ref: VGP 4.1.1]. (3) if pollutants or cor- ed. [Ref: VGP 4.1.1]. (4) The term "sheen" is to be unders ganic oils. [Ref. VGP Fact. Sheet. 3.4.4].	d and used (including, as applicable natificents of concern are determine	, cargo holds, ed to be originating
Are Decks Clean?		<b>2</b>	Any Violations Discovered during Inspec	ction or any corrective actions	required?
if no, were decks ci	eaned?				
is the Water around th	e barge	$\mathbf{Z}$			-
Was a sample take					
rres o sample take	11.7				
Voids or Hopper Pump	ed?				
Sheen present in w pumping?	ater after				
Inspected by (Printed	)) eric han	\$0fi			
Approved by (Printed	) David Cu	llinan	Approved by (Signature	•	
Entering your <b>Signat</b> ine problems nated	PUI indicates	rai the barg	Cost Pavo been mapeded in amordance वह indicated abo	a Daniel Cu	Winge

IMT 1051

Vessel General Permit Compliance

Equipment.	M946400		Ve:	ssel/Asset.	Windy City	
Company:	Ingram Barge	Company		Waterway:	Illinois River	/ 299.4
Inspection Date Time	06/10/2015	07.35		Location:	IMT Lemont (Lower Ctar.e)	
Load Status:	○ Empty (	) Partial ® Li	paded		,	
boiler areas, machinery st from the barge(s), correct	ssible areas wit orage areas, w tive action must	iere chemicals, elidecks and of be initiated. [Re	byage, whichever is more frequent, oils dry cargo, or other moterials a her areas) [Ref: VGP 4.1.1] (3) If j of: VGP 4.1.1] (4) The term "sheen" oils [Ref VGP Fact Sheet 3,4.4]	re stored, mo poliutants or	xed and used (including, as applic constituents of concern are detect	able, cargo holds,
Are Decks Clean?	덛	***************************************	Any Violations Discovered	during Ins	pection or any corrective acti	ions required?
If no, were decks clea	aned?					
is the Water around the free of sheen? Was a sample taken						
**						
Voids or Hopper Pumpe	<b>d</b> ?	, ,				
Sheen present in wat pumping?	erafter [					
Inspected by (Printed)	enc hanson					
Approved by (Printed)	David Cullin	an	Approved	by (Signate	-	
Entereig your Signature Pr protiens noted	Tindicales trat	មិត ចង់ខ្មែរ ១ ១៩	rue s sen may esten ar approvidance v	as indicated :	abor Denne 12	ulisman

**IMT 1052** 

#### Vessel General Permit Compliance

Vessel/Asset: Midwest Pride

JU075416

Equipment

Company:	igiam Baige Ci	ompany	٧V	aterway.	Illinois River	ı 277
Inspection Date Time 0	6/10/2015 0	9 50	L	ocation.	Mobil Cake Upper	
Load Status:	○ Empty ○ P	artial 🍥 Loaded				
instructions: (1) This form is to be compareds and all safely accessionler areas, machinery stotrom the barge(s), correction to the control of the correction of the correctio	sible areas where rage areas, welld ve action must be	chemicals, oils, dry ca ecks and other areas) initiated. [Ref: VGP 4.1	go, or other materials are s [Ref: VGP 4.1.1] (3) if poll .1] (4) The term "sheen" is	stored, mö lutents or e	ced and used (including, as constituents of concern are	applicable, cargo holds, determined to be originating
Are Decks Clean?	( <u>~</u> )	Any V	iolations Discovered du	ıring lnsı	pection or any correctiv	e actions required?
if no, were decks clea	ned?					
is the Water around the free of sheen?	oarge ☑					
Was a sample laken?						
Voids or Hopper Pumper	j? []					
Sheen present in wat pumping?	erafter [T]					
Inspected by (Printed)	caldrich					$\cdots \sim 1$ at $I^{res}$
Approved by (Printed)	Carl Aldrich		Approved by	y (Signati	ure)	n/pdx

The energian Signature PC incomes that the exercises of the Postegorial in according to the Remotive and contactive action to been obtained for paying a signature.



#### Vessel General Permit Compliance

Equipment: C	BY272		Vessel/Asset	Albert C	
Company: C	anal Barge Com	pany	Waterway.	Illinois River	7 293
nspection Date Time 0	6/10/2015 10	35	Location.	OXBOW	
Load Status:	○ Empty ○ Pa	rtial 🏵 Loaded			
areas and all safety access boiler areas, machinery sto	sible areas where c rage areas, wellded we action must be ini	hemicals, oils, dry car cks and other areas). itiated. (Ref; VGP 4.1.	hever is more frequent. (2) Education go, or other materials are stored, m [Ref: VGP 4.1.1] (3) If pollutants or 1] (4) The term "sheen" is to be und P Fact Sheet 3.4.4]	ixed and used (includi constituents of conce	ng, as applicable, cargo holds, ern are determined to be origination
Are Decks Clean?		Any VI	olations Discovered during ins	pection or any cor	rective actions required?
If no, were decks clea	ned?				
is the Water around the i	Darge 🔀				
Was a sample taken?	O				
Voids or Hopper Pumped	17 <b>[</b> ]				
Sheen present in water pumping?	*****				
Inspected by (Printed)	Peter Kosik				
Approved by (Printed)	Peter Kosik		Approved by (Signal	ture)	
Poternig your Signature Pili problems noted	Leidinales that he c	ergé(s) have been in	spected in accordance as indicated	abov After	Mr & to vily

Equipment:

CBY272

Vessel General Permit Compliance

Equipment:	T13606			Vessel/Asset:	Midwest Pride	
Company"	Ingram Barge	Company		Waterway:	Illinois River	1 277
Inspection Date Time	06/10/2015	14:36		Location:	Mobil Coke Upper	
Load Status;	○ Empty (	) Partial <b>®</b> L	.oaded ,			
<ul> <li>Breas and at safety accident areas, machinery from the barge(s), corre</li> </ul>	essible areas wh storage areas, w ective action musi	rere chemicals, reidecks and o libe initiated. [R	oyage, whichever is more fre oils, dry cargo, or other mate ther areas). [Ref: VGP 4.1.1] ef: VGP 4.1.1] (4) The term? oils [Ref VGP Fact Sheet 3.	rials are stored, mi i (3) If pollutants or sheen" is to be und	ked and used (including, constituents of concern a	as applicable, cargo holds, are determined to be originating
Are Decks Clean?		***	Any Violations Disco	vered during Ins	pection or any correc	tive actions required?
lfino, were decks cl	eaned? []					
Is the Water around the	ne barge					
Was a sample take	en?					
Voids or Hopper Pump	ned?					
Sheen present in w pumping?	vater after					
Inspected by (Printed	d) CALDRICH					
Approved by (Printed	f) Carl Aldrich	ì	Арр	roved by (Signati	nte) — — —	n/ D'da

Into inglicum Signature Pilo oblicates that the conjunct have need inspection in occurriance as indicated above and contective action has been charge for any produces noted.



Equipment	MTC727	Vessel/Asset, Midwest Pride
Company:	Heartland Transpi	ation Weterway: Illinois River / 277
Inspection Date Time	06/11/2015 10	Location: Mobil Coke Upper
Load Status:	○ Empty ○ Pa	el 🐑 Loaded
boiler areas, machinery s from the barge(s), correct	essible areas where c storage areas, wellded ctive action must be in	r per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo micals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, and other areas). [Ref: VGP 4.1.1] (3) If poliutants or constituents of concern are determined to be originatisted. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including rigonic oils [Ref VGP Fact Sheet 3.4.4].
Are Decks Clean?	V	Any Violations Discovered during Inspection or any corrective actions required?
lfino, were decks cle	aned?	
Is the Water around the free of sheen?	e barge ☑	
Was a sample taker	7 🗍	
Voids or Hopper Pumpi	ed?	
Sheen present in wa pumping?	10.00	
Inspected by (Printed)	patrick enckson	
Approved by (Printed)	Tyshun Griffin	Approved by (Signature)
Pritering your Stypparure R crapteres rate o	To instruction by anything a	selvi davis siest inspected in actinopance as entimated above.



Vessel General Permit Compliance

Equipment:	T13606		Vessel/Asset:	Mary C	
Company.	ingram Barge	Company	Waterway:	Illinois River	ı 27B
Inspection Date Time:	06/11/2015	10 35	Location:	Rapps Fleet	,
Load Status:	○ Empty (	) Partial 🌘 L	oaded .	,,	
boiler areas, machinery from the barge(s), corre	essiole areas, vi storage areas, vi ctive action must	elidecks and of be initiated. [Re	eyage, whichever is more frequent. (2) Location obs. dry cargo, or other materials are stored, mis her areas). [Ref: VGP 4.1.1] (3) If polititants or if: VGP 4.1.1] (4) The term "sheen" is to be und tills [Ref VGP Fact Sheet 3.4.4]	xed and used (including, a constituents of concern se	s applicable, cargo holds,
Are Decks Clean?	$\overline{\mathbf{Q}}$		Any Violations Discovered during Insp	pection or any correcti	ve actions required?
lf no, were decks cle	eaned?				ŕ
is the Water around the	e barge				
Was a sample laker	us 🔲	and the state of t			
Voids or Hopper Pump	ed?				
Sheen present in wa pumping?	aterafter []				
Inspected by (Printed	) Dave Kuntz				and the second second
Approved by (Printed)	Carl Aldrich		Approved by (Signatu	Ife)	2/0/00

Entering your Expeditive Provided that the burgers of all observe executed in occordance as the cuted above or dispute the color has been writted for any project in entering.



Vessel General Permit Compliance

Equipment:	IN096077			Vessel/Asset:	Albert C	
Company:	Ingram Barg	e Company		Waterway:	Illinois River	1 293
Inspection Date Time:	06/11/2015	12:30		1.ocation:	OXBOW	
Load Status:	CEmpty	○ Partial <b>®</b> L	oaded			
boiler areas, machinery s from the barge(a), correc	same aleas w lorage areas, v tive action mus	nere chemicals, velidecks and of t be initiated. (Ri	ols, dry cargo, or other materi her areas). [Ref: VGP 4.1.11 (:	Bls are stored, mb 3) If pollutants or : icen" is to be und:	s to be inspected: Sately accessi ked and used (including, as applic constituents of concerniare deter erstood as a concentration of oil o	able, cargo holds,
Are Decks Clean?	V		Any Violations Discove	ered during insi	pection or any corrective acti	ons required?
If no, were decks clea	aned? [∐		NONE			•
is the Water around the free of sheen? Was a sample taken	<b></b>					
Voids of Hopper Pumpe Sheen present in wa pumping?	******					
Inspected by (Printed)	PATRICK	ONG				
Approved by (Printed)	Antonio Le	pez	Аррго	ved by (Signalu	rre)	
Foreing your Signature Pr problems noted	Gladicates tha	t the narge in the	sve bako inspecied ir ancordai	Mice as មាប់ទេសមន្តិ ខ	Antonio C	-opez

VGPEXCHANGE

Vessel General Permit Compliance

Equipment:	IN075408	Vessel/Asset	Mary C
Company:	Ingram Barge Compai	y Waterway.	Illinois River / 277
Inspection Date Time:	06/11/2015 13:40	Location:	Mobil Coke Spout
Load Status:		CLoaded	
boiler areas, machinery from the barge(s), corre	essible areas where chemi storage areas, welldecks a ective action must be initiated	per yoyage, whichever is more frequent. (2) Locations cals, oils, dry cargo, or other materials are stored, mix no other areas). [Ref: VGP 4.1.1] (3) If pollutants or of [Ref: VGP 4.1.1] (4) The term "sheen" is to be undeasic oils [Ref VGP Fact Sheet 3.4.4]	ed and used (including, as applicable, cargo holds,
Are Decks Clean?	$\square$	Any Violations Discovered during Insp	pection or any corrective actions required?
If no, were decks d	eaned?		
is the Water around th	ie barge		
Was a sample take	n? 🗌		
Voids or Hopper Pump	ped?		
Sheen present in w pumping?	eter after		
Inspected by (Printed	i) Dave Kuntz		market and the state of the sta
Approved by (Printed	) Carl Aldrich	Approved by (Signatu	re) — 7/ //

Entering your Dignature Fit indicates that the bargershows ower depended in accordance as indicated above and optrestive action has been inhated for any problems noted.



Equipment	INUGEUNI			Vessel/Asset:	Albert C	
Company:	Ingram Barg	ge Company	,	Waterway:	Illinois River	7 299.4
Inspection Date Time	06/11/2015	14 05		Location	SYS	
Load Status:	O Empty	O Partial @	Losded			
<ul> <li>areas and all safety according to boiler areas, machinery:</li> </ul>	essible areas w storage areas, ctive action mu:	rhere chemica welldecks and stibe initiated.	ils, oils, dry cargo, or at I eiher areas) [Ref: VC [Ref: VGP 4.1.1] (4) Th	more frequent. (2) Location her materiets are stored, mis IP 4.1.1] (3) If pollutants or d e term "sheen" is to be unde heet 3.4.4}	ked and used (including, a constituents of concern ar	s applicable, cargo holds, is determined to be ariginati
Are Decks Clean?	[Z	)	Any Violation	s Discovered during Insp	pection or any correcti	ive actions required?
If no, were decks cla	eaned?		NONE			
is the Water around th	e barge					
Was a sample take	n? [					
Maide and the company	- 45 - 5"					
Voids of Hopper Pump	1/4/					
Sheen present in w pumping?	aterater [					
Inspected by (Printed	) PATRICK	DONG				
Approved by (Printed)	) Antonio Lo	pez		Approved by (Signatu	ire)	
Entenag your Signature i problems noted	PIN indicates the	at the bargers	) have been inspected i	s accordance as indicated (	Anton	is Lopez

Equipment	RF960		Vessel/Asset:	Midwest Pride
Company ,	AEP Rive	r Operatio	s Waterway:	: Illinois River / 277
Inspection Date Time	06/12/201	5 07 25	Location	: Mobil Cake Upper
Load Status:	○ Emp	ity 🔾 Partia	I <b>⑥</b> Loaded	
areas and all safely acces boiler areas, machinery st from the barge(s), correct	saible areas lorage area tive action r	s where che s, welldecks nust be initis	per voyage, whichever is more frequent. (2) Location nicels, oils, dry cargo, or other materials are stored, m and other areas). [Ref: VGP 4.1.1] (3) if pollutents or ed. [Ref: VGP 4.1.1] (4) The term "sheen" is to be und	ixed and used (including, as applicable, cargo holds, constituents of concern are determined to be originating
Are Decks Clean?		V	Any Violations Discovered during Ins	pection or any corrective actions required?
If no, were decks clea	aned?			
is the Water around the free of sheen?	barge			
Was a sample taken	?			
Voids or Hopper Pumpe	d?			
Sheen present in wa pumping?	ler afler			
Inspected by (Printed)	PATRiC	K ERICKS	ON	
Approved by (Printed)	Tyshun	Griffin	Approved by (Signat	ture';
hatening your Dignature fo problems noted	iv noicates	thef the bar	pc(s) have been inspected it accordance as indicated	stor ELL

Equipment.	T13835			Vassel/Asset:	Midwest Prid	ie	
Company:	Ingram Bar	ge Company		Waterway:	Illinois River		1277
Inspection Date Time	05/12/2015	10 50		Location:	Mobil Coke (	Jpper	
Load Status:	() Empty	⊖Partial <b>®</b> Lo	paded				
areas and all safely acce boller areas, machinery si from the barge(s), correc	ssible areas v lorage areas, tive action mu	where chemicals, owelldecks and other welldecks and other at be initiated. [Re	yage, whichever is more frequibils, dry cargo, or other materialer areas). [Ref: VGP 4.1.1] (3) to VGP 4.1.1] (4) The term "she ils [Ref VGP Fact Sheet 3.4.4]	ls are stored, mit ) If pollutants or sen" is to be und	ked and used (in constituents of c	cluding, as applicab	le, cargo holds, red to be originat
Are Decks Clean?	[	]	Any Violations Discove	red during Ins	pection or any	corrective action	is required?
if no, were decks dea	aned? [						
Is the Water around the free of sheen?	barge	)					
Was a sample taken	? [						
Voids or Hopper Pumpe	ed?	]					
Sheen present in wa puniping?	terafter _						
Inspected by (Printed)	patrick er	ckson					
Approved by (Prinled)	Tyshum G	ri <b>ff</b> in	Аррго	ved by (Signati	ure)		
Coloring your Separate P couldn't exted.	Note thates in	Afthor English 19	er Leur inspendia in ana actar	U. 88 534 3160	ånne	SI Mag	<u> </u>



Vessel General Permit Compliance

Equipment. (	CBX2021			Vessel/Asset	Eileen C	
Company:	Canal Barge	Company		Waterway:	Illinois River	J 298
Inspection Date Time: (	06/12/2015	10:55		Location:	iMT Lemont (NRF)	
Load Status:	C Empty (	) Partial ® L	_oaded		, ,	
Instructions: (1) This form is to be compareds and all safety acces boiler areas, machinery strom the barge(s), correctifubricating alls, hydraulic of	sible areas wi prage areas, w ive action musi	here chemicals, velidecks and o t be initiated. [R	, oils, dry cargo, or other n ther areas) (Ref: VGP 4.: lef: VGP 4.1,1] (4) The ler	nateriuls are stored, mix 1.1] (3) If poliutants or c m "sheen" is to be unde	ed and used (including, a constituents of concern a	es applicable, cargo holds,
Are Decks Clean?	V	Amender	Any Violations Dis	covered during Insp	ection or any correct	tive actions required?
if no, were decks clea	ned? []					
Is the Water around the free of sheen?	barge 🗹					
Was a sample taken?						
TOO Q SUMPLE RENEATE						
Voids or Hopper Pumper	j? []					
Sheen present in wate pumping?	erafter [					
inspected by (Printed)	austin brau	ns				
Approved by (Printed)	Curtis Logs	don	A	pproved by (Signatu	re) (-1	2000
Entering your Signature 20	Taicates that	the bargers, h	ave been inspected in acc	vidance as indicated a		039000



problems notes

Vessel General Permit Compliance

Equipment: (	CBX2107	Vessel/Asset: Eileen C	
Company. (	Canal Barge Comp	any Waterway: Illinois River	/ 298
inspection Date Time: 0	06/12/2015 10 5	5 Location: IMT Lemont (NRF)	
Load Status:	○ Empty ○ Parti	al (® Loaded	
boiler areas, machinery sto from the barge(s), correcti	sible areas where che prage areas, welldeck ve action must be initia	or per voyage, whichever is more frequent. (2) Locations to be inspected. Safely accessible enticels, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable and other areas). [Ret: VGP 4.1.1] (3) If pollutants or constituents of concern are determined. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or graphic oils [Ref VGP Fact Sheet 3.4.4]	ie, cargo holds, led to be origination
Are Decks Clean?	<b>V</b>	Any Violations Discovered during Inspection or any corrective action	s required?
If no, were decks clea	ned?		
is the Water around the i	barge 🗸		
Was a sample taken?			
Voids or Hopper Pumped	1?		
Sheen present in wate pumping?	er after		
Inspected by (Printed)	austin brauns		
Approved by (Printed)	Curtis Logsdon	Approved by (Signature)	mdo-
Enterag yaar Signatora Pti.	admitted that the Lac	golisi basa basa magaratah ar inaminan di as mumateh ahari 🗸 😘 😘 🗸 🗸	الماري الم

VGPEXCHANGE

Equipment (	BY261		Vessel/Asset Ei	leen C	
Company: (	anal Barge Com	npany	Waterway: Illi	nois River	, 298
Inspection Date Time. C	6/12/2015 10	:55	Location: IIV	T Lernont (NRF)	
Load Status:	○ Empty ○ Pa	irlial 🖲 Loaded		, ,	
boiler areas, machinery sto	sible areas where c rage areas, welide ve action must be in	chemicals, olls, dry cargo, c cks and other areas). [Ref itilated. [Ref: VGP 4.1.1] (4	er is more frequent. (2) Locations to or other materials are stored, mixed : VGP 4.1.1] (3) if pollutants or con i) The term "sheen" is to be underst ct Sheet 3.4.4]	and used (including, as stituents of concern are	applicable, cargo holds,
Are Decks Clean?	Ø	Any Violat	ions Discovered during Inspec	tion or any correctiv	e actions required?
If no, were decks clea:	ned?				,
is the Water around the t free of sheen?	oarge 🕢				
Was a sample taken?					
Voids of Hopper Pumped	? П				
Sheen present in water pumping?	Luncia				
Inspected by (Printed)	austin brauns				
Approved by (Printed)	Curtis Logisdon		Approved by (Signature)	C	Indon
Entenog your Signature Pilv Broklens : ofed	indicates that the b	sige(s have teen inspec	ed in accordance as indicated abor	- Cura	Jogido-

Vessel General Permit Compliance Equipment: **CBY447** Vessel/Asset: Eileen C Company: Canal Barge Company Waterway: Illinois River / 298 Inspection Date Time 06/12/2015 10.55 Location: IMT Lemont (NRF) Load Status: O Empty O Partial @ Loaged (1) This form is to be completed once per week or per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo areas and all safely accessible areas where chemicals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, boiler areas, machinery storage areas, welldecks and other areas) [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originating from the barge(s), corrective action must be initiated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including lubricating oils, hydraulic oils, and vegetable, or organic oils [Ref VGP Fact Sheet 3.4.4] Are Decks Clean? V Any Violations Discovered during Inspection or any corrective actions required? If no, were decks cleaned? is the Water around the barge  $\odot$ free of sheen? Was a sample taken? Voids or Hopper Pumped? Sheen present in water after pumping? inspected by (Printed) austin brauns Approved by (Printed) Curtis Logsdon Approved by (Signature) with Logdon Entering your Signature Ptx indicates that the bargers' have treen inspected in accordance as indicated about



erribiens noted

Vessel General Permit Compliance

Equipment	IMT105			Vessel/Asset:	Eilsen C	
Company:	Canal Ba	rge Company		Waterway.	Illinois River	/ 298
Inspection Date Time:	06/12/201	15 10:55		Location:	IMT Lemont (NRF)	
Load Status:	○Emp	oty 🔾 Partial 📵 į	Loaded			
boiler areas, machinery s from the barge(s), correc	ssible areas forege area dive action r	s where chemicals s, welldecks and o must be initiated. [R	royage, whichever is more, alls, dry cargo, or other matter areas). [Ref: VGP 4.1.Ref: VGP 4.1.1] (4) The term oils [Ref VGP Fact Sheef	sterials are stored, mix 1] (3) If pollutents or o s"sheen" is to be unde	ed and used (including, constituents of concerns	as applicable, cargo holds,
Are Decks Clean?		$\square$	Any Violations Disc	overed during Insp	ection or any correc	tive actions required?
If no, were decks de	aned?					
is the Water around the free of sheen?	e barge	$\square$				
Was a sample taken	1?					
Voids or Hanner Dumpe	. d 5	F3				
Voids or Hopper Pumpe Sheen present in wa pumping?	ioroffor					
Inspected by (Printed)	austin b	rauns				
Approved by (Printed)	Curtis Lo	ogsdon	Ар	proved by (Signatu	re) ( -1	. Toppdo-
Entering your Signature P proteins noted	li espoaran	il at the bargers, b	nave been inspected in acco	rdance as indicated a		. 039,50

VGPEXCHANGE

Vessel General Permit Compliance

Equipment	T13606	Vessel/Asset: Mary C
Company:	Ingram Barge Co.	pany Waterway: Illinois River / 278
Inspection Date Time:	06/12/2015 11	Location, IMT Chan (Crane)
Load Status:	○Empty○Pa	isl <b>®</b> Loaded
boiler areas, machinery of from the barge(s), corre	essible areas where c storage areas, welide ctive action must be in	or per voyage, whichever is more frequent (2) Locations to be inspected: Safely accessible deck and cargo emicels, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, as and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originating lated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	<b>(</b> ₹)	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks cle	eaned?	
is the Water around the	e barge	
Was a sample taker	n? 🗀	
Voids or Hopper Pump	ed? ☑	
Sheen present in wa pumping?	aler after	
Inspected by (Printed	) Dave Kuntz	
Approved by (Printed)	Carl Aldrich	Approved by (Signature) - 2/ D/ J/

Entering your September 1980 indicates that the hargers' have been inspected in accordance as indicated above and contentive active bas their intribution sny problems insted



Equipment:	IN118500B	VesseVAsset: Windy City
Company:	Ingram Barge Con	ipany Waterway: Illinois River / 293
Inspection Date Time:	06/12/2015 12:	20 Location: OXBOW
Load Status:	○ Empty ○ Par	alal 🕲 Loaded
boiler areas, machinery st from the barge(s), correct	isible areas where ci prage areas, wellded ive action must be ini	or per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo emicals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, is and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originating lated. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including organic oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	Ø	Any Violations Discovered during Inspection or any corrective actions required?
lt no, were decks clea	ned?	
is the Water around the	barge 🖸	
Was a sample taken?	, <u> </u>	
	<b></b>	
Voids or Hopper Pumper	h.ves?	
Sheen present in wate pumping?	erafter	
Inspected by (Printed)	justin grooms	
Approved by (Printed)	Paul Roman	Approved by (Signature)  App (Inumboration)  (35/51 lieve has a spected in accordance as indicated above
Entering your folgostore Pit Enterins to test	indicates that the ha	gars have been aspected in accordance as indicated abov



Equipment	113835		Vessel/Asset:	Midwest Pride	
Company:	Ingram Barge Con	npany	Waterway:	Illinois River	1 279
inspection Date Time:	06/14/2015 07%	45	Location:	Load Fleet	
Load Status:	○ Empty ○ Par	tial 🏵 Loaded			
areas and all safely acces boiler areas, machinery st from the barge(s), correct	ssible areas where ch lorage areas, wellded live action must be init	temicals, oils, dry carge, or o ks and other areas) [Ref: V	ither meterials are stored, mb GP 4.1.1] (3) If pollutants or e the term "sheen" is to be unde	ted and used (includin constituents of concer	ely accessible deck and cargo g, as applicable, cargo holds, n are determined to be originat ation of oil or grease, including
Are Decks Clean?	[ <del>Z</del> ]	Any Violation	ns Discovered during Insp	ection or any corr	ective actions required?
If no, were decks clea	aned?				
is the Water around the free of sheen?	barge 📝				
Was a sample taken	?				
Voids of Hopper Pumps	d? <u>[~</u> ]				
Sheen present in wat	las offer				
pumping?					
Inspected by (Printed)	patrick erickson				
Approved by (Printed)	Tyshun Griffin		Approved by (Signatu	re)	
Eale wig your Signature F	i, nomales that the ha	ngelt bale nort mapeinen	a, acostoavite en moinațed ș	ito 🚉	I des



Equipment; (	BY275		Vessel/Asset: Alb	ert C	
Company: C	anal Barge (	Company	Waterway: Illin	ois River	/ 296
Inspection Date Time 0	6/14/2015	19.45	Location: IMT	ГММН (ММН)	
Load Status:	Empty C	Partial () L	oaded		
areas and all safety access baller areas, machinery sto from the barge(s), correcti	sible areas whi rage areas, we ve action must l	ere chemicals, elidecks and of pe initiated. [Re	oyage, whichever is more frequent. (2) Locations to boils, dry cargo, or other materials are stored, mixed a ther areas). [Ref: VGP 4.1.1] (3) If pollutants or constant. (3) If pollutants or constant. (4) The term "sheen" is to be understoods [Ref VGP Fact Sheet 5.4.4].	ind used (including, as applititions of concern are dete	icable, cargo holds, smined to be originating
Are Decks Clean?	<b>?</b>		Any Violations Discovered during Inspecti	ion or any corrective ac	tions required?
If no, were decks clear	ned?				
Is the Water around the t	oarge 🗹				
Was a sample taken?					
Voids or Hopper Pumped	? []				
Sheen present in water pumping?	r after 🗌				
Inspected by (Printed)	westley willi	ams			
Approved by (Printed)	Robert Derba	₹5	Approved by (Signature)		•
Enterlay your façnature Pt.	indicates that i	he harge-s] h	ave been inspected in arcordance as indicated above	Robert L	Derlas

Equipment.	ING6515		Ve	ssel/Asset.	Midwest Pride	
Company:	Ingram Ba	rge Company		Waterway.	Illinois River	1 277
Inspection Date Time:	06/15/2015	5 10 15		Location.	Mabil Coke Upper	
Load Status:	() Empt	y () Partial (🖲 Lo	oaded		. ,	
boiler areas, machinery st from the barge(s), correc	ssible areas torage areas tive action m	Where chemicals, , welldecks and off ust be initiated. [Re	yage, whichever is more frequent oils, dry cargo, or other malerials a her areas). [Ref: VGP 4.1.1] (3) if if: VGP 4.1.1] (4) The term "sheen" ils [Ref VGP Fact Sheet 3.4.4]	ire stored, mi pollutants or	xed and used (including, a constituents of concern a	is applicable, cargo holds,
Are Decks Clean?	[	21	Any Violations Discovered	i during Ins	pection or any correcti	ive actions required?
if no, were decks clea	aned? [					
Is the Water around the tree of sheen?	barge E	<u> </u>				
Was e sample taken	? [					
Voids or Hopper Pumpe	տ? [ <sup>-</sup>					
Sheen present in war pumping?		1				
Inspected by (Printed)	mike wail	lace				
Approved by (Printed)	Tyshun G	iriffin	Approved	l by (Signate	ire)	
Constantly on Signature Pi	t Hasher	rat the haracypi as	or them inspected in accordance.	es vincales.	ala: Q	Tong.

Equipment:	CBY275		Vessel/Asset:	Albert C	
Company:	Canal Barge	Company	Waterway:	Illinois River	/ 293
Inspection Date Time:	06/15/2015	10 35	Location:	OXBOW	
Load Status:	○ Empty (	) Partial 🌘	Loaded		
areas and all sately acce boiler areas, machinery a from the barge(s), correc	essible ereas wh storage areas, w ctive action must	ere chemica elidecks and be initiated.	r voyage, whichever is more frequent (2) Location (2), oils, dry cargo, or other materials are stored, mod other areas). [Ref: VGP 4.1.1] (3) if pollutants or [Ref: VGP 4.1.1] (4) The term "sheen" is to be undicted the triangle oils [Ref VGP Fact Sheet 3.4.4].	ked and used (including, a constituents of concern a	is applicable, cargo holds,
Are Decks Clean?	9		Any Violations Discovered during Ins	pection or any correct	ive actions required?
lfing, were decks cle	aned?		none		,
is the Water around the free of sheen?	e barge 🗹				
Was a sample taken	)?				
Voids or Hopper Pumpe	ed?				
Sheen present in wa pumping?	aterafter [	***************************************			
inspected by (Printed)	patrick don	3			
Approved by (Printed)	Antonio Lop	ez	Approved by (Signatu	re)	
En enng your Gigoature P problems ealer	dis policates that	he bargeis.	, have been inspected in accordance as indinated :	Anton	is Lopez

Equipment:	IN118500H		Vessel/Asset	Albert C	
Company	Ingram Barge Co	mpany	Waterway:	Illinois River	/ 301.2
Inspection Date Time.	06/15/2015 14	20	Location;	IMT Lemont (Upper Cr	ane)
Load Status:	○Empty ○Pa	ertial 🖲 Loaded			,
areas and all safely acce boiler areas, machinery s	ssible areas where of torage areas, welke tive action must be in	chemicals, oils, dry carg cks and other areas). [F nitiated. [Ref: VGP 4.1.1]	ever is more frequent. (2) Locations o, or other materials are stored, mix Ref: VGP 4.1.1] (3) If pollutents or o ] (4) The term "sheen" is to be under Fact Sheet 3.4.4]	ced and used (including, as constituents of concern are	applicable, cargo holds,
Are Decks Clean?	(·)	Any Vio	lations Discovered during Insp	section or any correctiv	e actions required?
lfina, were decks cle	aned?	none			
is the Water around the free of sheen?	barge 🗹				
Was a sample taken	3 📋				
Voids or Hopper Pumpe	ed?				
Sheen present in wa pumping?	der after				
Inspected by (Printed)	patrick dong				
Approved by (Printed)	Antonio Lopez		Approved by (Signatu	ite)	
Palentay, in Secundary 5 common aded	関(さなか <b>が</b> たられば fish is	A globe was been that	erzed miz owydłona e lasja i świałaż s	Antone	is Lopez



Vessel General Permit Compliance

Equipment:	T13826		Vessel/Asset:	Mary C	
Company:	Ingram Barg	e Company	Waterway.	Illinais River	ı 277
Inspection Date Time;	96/15/2015	15 00	Location.	Mobil Coke Upper	
Load Status:	() Empty	O Panial 🕲 L	oaded		
boller areas, machinery s from the barge(s), correct	essible areas w storage areas, i ctive action mus	here chemicals, welldecks and of it be initiated [Re	eyage, whichever is more frequent. (2) Location oils, dry cargo, or other materials are stored, migher areas). [Ref: VGP 4.1.1] (3) If pollutants or in the stored of the transfer of the tran	xed and used (including, as constituents of concern are	applicable, cargo holds, determined to be principation
Are Decks Clean?	[v]	, i	Any Violations Discovered during Ins	pection or any corrective	e actions required?
If no, were decks cle	aned? []				
Is the Water around the free of sheen?	e barge				
Was a sample taker	1? [				
Voids or Hopper Pump	ed?				
Sheen present in wa pumping?	aterațer []				
Inspected by (Printed)	) CALDRICH	i			
Approved by (Printed)	Carl Aldrici	1	Approved by (Signatu	ite) —	21 pld

Entering your Signature PM increases that the bargers of a volument in specified in accordance as indicated above and corrective action has been inhated for any problems incled.



Equipment:	IN075041		Vessel/Asset	Midwest Pride	
Company:	Ingram Bar	ge Company	Waterway:	Illinois River	1 277
Inspection Date Time.	06/16/2015	21 10	Location:	Mobil Coke Spout	
Load Status;	O Empty	/ O Partia: 🏵	Loaded		
bailer areas, machinery s from the barge(s), correc	ssible areas torage areas, tive action mo	where chemical welldecks and ust be initiated. [	voyage, whichever is more frequent. (2) Location s, oils, dry cargo, or other materials are stored, mother areas). [Ref: VGP 4.1.1] (3) if pollutants or Ref: VGP 4.1.1] (4) The term "sheen" is to be undiciplis [Ref VGP Fact Sheet 3.4.4].	xed and used (including, as applications and used (including, as applications).	sble, cargo holds, pined to be originati
Are Decks Clean?	[S	7)	Any Violations Discovered during Ins	pection or any corrective action	ons required?
If no, were decks cle	aned?	)			
is the Water around the	barge [	<u> </u>			
Was a sample taken	? [	n			
Voids or Hopper Pumpe	id? [				
Sheen present in wa pumping?	terafter [	]			
Inspected by (Printed)	james we	xelberg			
Approved by (Printed)	Tammy V	Valter	Approved by (Signate	ure)	
Enlessig your Signature P problems noted	Prindicales U	iation barge s	trave been inspected a accordance as indicated	ation	



Equipment:	ING5782		Vessel/Asset:	Windy City	
Company:	Ingram Barge Cor	npany	Waterway:	Illinois River	/ 293
Inspection Date Time	06/18/2015 23	15	Location.	OXBOW	
Load Status;	○ Empty ○ Pa	rtial 🏵 Loaded			
boiler areas, machinery st	ssible areas, where confided areas, wellded live action must be in	hemcals, oils, dry cargo, : cks and other areas): [Ref Haied. (Ref: VGP 4.1,1] (:	er is more frequent (2) Locations or other materials are stored, mo i: VGP 4.1.1] (3) If pollutants or o i) The term "sheen" is to be unde ct Sheet 3.4.4]	ted and used (including,	as applicable, cargo holds,
Are Decks Clean?	abla	Any Violat	ions Discovered during Insp	pection or any correc	ctive actions required?
lf no, were decks clea	ined?				
Is the Water around the tree of sheen?	barge 🗹				
Was a sample taken?					
Voids or Hopper Pumpe	d? 🗀	***************************************			
Sheen present in wat pumping?	123				
Inspected by (Printed)	justin grooms				
Approved by (Printed)	David Cullinan		Approved by (Signatu	•	
Esterno your Eighat mis 94 processor neted	Codmalys that the E	ages basemeninspe:	មេខារី ឧព្ធភាពនៃក្រុះ ឧម វត្តមេនី :	and Vacio	1 Cultinal

Equipment	IN135425				Vessel/Asset:	Albert C		
Company:	Ingram Ba	rge Com	pany		Waterway:	Illinois River		1 293
Inspection Date Time	06/19/201	5 00 0	5		Location	OXBOW		
Load Status:	○Emp	ty () Parti	al ® Loaded					
instructions: (1) This form is to be column areas and all safety accided areas, machinery from the barge(s), correlubricating oils, hydraulic	essible areas storage area: ctive action n	where chi s, welldeck nust be initia	emicals, oils, dry c s and other areas ated. [Ref: VGP 4.	argo, or other mate ) {Ref: VGP 4.1.1] 1.1] (4 <del>)</del> The term 's	rials are stored, mi (3) If pollutants or sheen" is to be und	xed and used (inconstituents of co	cluding, as appliced oncern are determi	ole, cargo holds, ined to be originating
Are Decks Clean?		2	Any	Violations Disco	vered during Ins	pection or any i	corrective actio	ns required?
if no, were decks cle	eaned?							
Is the Water around th	e barge	Ø						
Was a sample take	n?							
Voids or Hopper Pump	ed?							
Sheen present in w pumping?	ater after							
inspected by (Printed	) Peter Ko	osik						
Approved by (Printed	) Peter Ko	sik		Арр	roved by (Signat	ure)	,	
Entering your Signature processing noted	Phried Scates	met like bal	rge(s) havd beer	inspecien w andord	dance as indicatod	aber M	tr fhil	£ 'crany

Equipment: L	DX2054			Vessevasi	set: :::10	en C		
Company C	anal Barge C	Company		Waterw	/ay: Illino	ois River		/ 298
Inspection Date Time: 0	6/19/2015	01 20		Locati	on: :MT	Lemont (NRF	·}	
Load Status:	○ Empty ○	Partial 🏵 Lo	oaded					
Instructions: (1) This form is to be compareds and all safely accessionler areas, machinery signmenthe barge(s), correctifubricating oils, hydraulic oil	sible areas whe rage areas, we ve action must l	re chemicals, didecks and other initiated. [Re	oils, dry cargo, or ot ther areas) [Ref: VG ef: VGP 4.1.1] (4) Th	ner materials are stored P 4.1.1] (3) If poliutants e term "sheen" is to be	l, mixed al const	nd used (includin ituents of concer	ig, as appl in are dete	licable, cargo holds. ermined to be originating
Are Decks Clean?	V		Any Violations	B Discovered during	Inspecti	on or any corr	ective ac	tions required?
lf no, were decks clea	ned?							
Is the Water around the I	oarge 🗹							
Was a sample taken?								
Voids or Hopper Pumper	1?							
Sheen present in wate pumping?	erafer []							
Inspected by (Printed)	james cunni	ngham						
Approved by (Printed)	Curtis Logso	en		Approved by (Sig	nature)		1	Jogedo-
Entrology on Adjustice Pr protect to 1986	i notarek arst	he bardo in n	প্রতিষ্ঠার প্রতিষ্ঠার প্রতিষ্ঠার । বিশ্ববিদ্যালয় বিশ্ববিদ্যালয় বিশ্ববিদ্যালয় স্থানিক বিশ্ববিদ্যালয় বিশ্ববিদ্যালয় বিশ্ববিদ্যালয় বিশ্ববিদ্যালয়	1 20 20 1890. នេះ ប៉ុន្តែ	and <b>a</b> ces	Cu	المن	Osgran

### Vessel General Permit Compliance

Equipment: (	BY272			Vessel/Asset	Eileen C	
Company: (	Canal Barge Co	mpany		Waterway:	Illinois River	7 2 <b>9</b> 8
Inspection Date Time: 0	6/19/2015 (	1:20		Location	IMT Lemont (NRF)	
Load Status:	○ Empty ○ i	Partial <b>©</b> Load	ied			
instructions: (1) This form is to be compareds and all safety acces boiler areas, machinery sto from the barge(s), correctionaricating oils, hydraulic oils.	sible areas when trage areas, welk ve action must be	e chemicals, oils, decks and other initiated. [Ref: V	, dry cargo, or other m areas). [Ref: VGP 4.1 /GP 4.1.1] (4) The ten	aterials are stored, mo .1] (3) If pollulants or d n "sheen" is to be unde	ed and used (including, a constituents of concern a	s applicable, cargo holds, re determined to be originating
Are Decks Clean?	$\Box$		Any Violations Dis	covered during Insp	pection or any correcti	ive actions required?
if no, were decks clea	ned? 🔲					
Is the Water around the tree of sheen?	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	17 []					
Sheen present in water pumping?	er after					
Inspected by (Printed)	james cunnin	gham				
Approved by (Printed)	Curtis Logsdo	n	A	pproved by (Signatu	ire)	Jagrdo-
Entering your Signature Pit	estimatif	e bargers' have	been inspected in and	សាវងា ឯក ឧទ ១០១.៩៧១១	atov Cultural	039-

Equipment:

CBY272

### Vessel General Permit Compliance

Vessel/Asset: Eileen C

Company:	Canal Barg	e Company		:	Waterway:	Illinois Rive	ſ	/ 298
inspection Date Time:	06/19/2015	01 20			Location:	IMT Lemon	t (NRF)	
Load Status:	○ Empty	O Partial 🧐	Loaded					
Instructions: (1) This form is to be concreas and all safety acceboiler areas, machinery a from the barge(s), correctionicating oils, hydraulic	ssible areas v torage areas, tive action mu	where chemics welldecks and st be inhisted.	als, olls, dry cargo, d other areas) [Ref [Ref: VGP 4.1.1] (	or other materials ar f: VGP 4.1.1] (3) If p 4) The term "sheen"	e stored, mo ollutants or	ked and used constituents o	(including, as a f concern are d	pplicable, cargo holds, letermined to be originating
Are Decks Clean?	5	2	Any Viola	tions Discovered	during Ins	pection or a	y corrective	actions required?
If no, were decks cle	aned?							
is the Water around the free of sheen?	e barge [5	2						
Was a sample taker	1? [							
Voids or Hopper Pump	ed? [							
Sheen present in wa pumping?	aterafter [	]						
Inspected by (Printed	) james cu	nningham						
Approved by (Printed)	Curtis Lo	gsdon		Approved	by (Signat	ure)	-1	1-1
ke meng your Significati problem in leg	tr, universe t	vai þið barnafá	a Park Caer dispo	osed in appointance (	ନିଷ୍ଟ ଆଧିକ ଯାହିଛି	abr.	min	138120-



Equipment:

IMT124

Equipment:	ING5782		Vessel/Asset Windy City	
Company	Ingram Ba	ige Company	Waterway: Illinois River	7 299.4
Inspection Date Time	06/19/2019	07 50	Location: IMT Lemont (Lower C	rane)
Load Status:	○ Empt	y () Partial ®	Loaded	
areas and all safely acc boiler areas, machinery : from the barge(s), corre	essible areas storage areas ctive action m	where chemica welidecks and ust be initiated.	r voyage, whichever is more frequent, (2) Locations to be inspected: Safely a ils, cilis, dry cargo, or other materials are stored, mixed and used (including, as fother areas). [Ref: VGP 4.1.1] (3) If poliutants or constituents of concern ar [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration ic oils [Ref VGP Fact Sheet 3.4.4]	s applicable, cargo holds, e determined to be originating
Are Decks Clean?	[	2	Any Violations Discovered during Inspection or any correcti	ve actions required?
If no, were decks cle	eaned? [			
is the Water around th	e barge	71		
free of sheen? Was a sample take	•	_		
1125 d Sample lake				
Voids or Hopper Pump	ed? [			
Sheen presentin w pumping?	aterafter [	<b>]</b>		
Inspected by (Printed	n eric hans	sen		
Approved by (Printed			Approved by (Signature)	
Entering your Signature propler include	Piliprineles :	itel the benjair	where beer expected in accordance as indicated obey. Macaco	Rullinger

Equipment:	IN135425			Vessel/Asset	Albart C	
Company:		ge Company				. 664.8
inspection Date Time:		•		-	Illinois River	/ 301.2
Load Status:		r ○ Partial <b>®</b> £	_paded	Location:	IMT Lemont (Up	oer C≆zne}
belief areas, machinery a from the barge(s), corre	essible areas v storage areas, ctive action mu	where chemicals welldecks and o ist be initiated. [R	, ells, dry carge, or other ma ther areas). [Ref; VGP 4.1.	terials are stored, mix 1] (3) If pollutents or o "streen" is to be unde	ced and used (includ	ifely accessible deck and cargo ing, as applicable, cargo holds, ern are determined to be origination tration of oli or greese, including
Are Decks Clean?	٦	a	Any Violations Disc	overed during Insp	pection or any cor	rective actions required?
if no, were decks cla	aned?	]	n/a			
is the Water around the	e barge	` ]				
₩as a sample takei	n? [					
Voids or Hopper Pump	ed?	)				
Sheen present in wa pumping?	eterafter E					
Inspected by (Printed	) westley w	villiams				
Approved by (Printed)	Robert De	rbas	Ар	proved by (Signatu	ire)	
Entering your Rightstore for objects or fed	Milindicares th	althe marge sid	rave seas inspected in acco	niance as edicaled a	atair Rober	et & Derlas

Equipment:	IN015457		Vessel/As	set Wa	ndy City	
Company.	Ingram Ba	rge Compani	y Water	vay: Illin	ois River	/ 293
Inspection Date Time:	06/19/2019	5 10 00	Local	ion: OXI	BOW	
Load Status:	○ Empt	y 🔾 Partial 🍳	Dicaded			
areas and all safely acc boiler areas, machinery from the barge(s), corre	essible areas storage areas ctive action m	where chemic , welldecks an ust be initiated.	er voyage, whichever is more frequent. (2) Loc als, pils, dry cargo, or other materials are store id other areas). [Ref: VGP 4.1.1] (3) If pollulant . [Ref: VGP 4.4.1] (4) The term "sheen" is to be nic oils [Ref VGP Fact Sheet 3.4.4]	d, mixed a s or const	and used (including, as applicab tituents of concern are determi	ole, cargo holds, ined to be originating
Are Decks Clean?	[	<b>3</b>	Any Violations Discovered during	Inspecti	ion or any corrective action	ns required?
If no, were decks cle	eaned? (					
is the Water around th	e barge .					
free of sheen?		☑				
Was a sample take	n? [					
		edd.dda enganner en e e e e				
Voids or Hopper Pump	ed?				•	
Sheen present in w pumping?	ater after					
Inspected by (Printed	i) eric han:	son				
Approved by (Printed	) David Cu	llınan	Approved by (Si	(nature		
Entering your Signature problems onted	Pill indicates	inat the harge(	is; have been inspected a accordance as adic	ated abov	Naud C	ellinon



Equipment:	N135401		Vess	el/Asset.	Windy City		
Company: I	ngram Barge Co	mpany	W	Vaterway.	Illinois River		/ 293
nspection Date Time (	16/19/2015 13	05	1	Lecation:	OXBOW		
Load Status:	○ Empty ○ Pa	srtial <b>©</b> Loaded					
Instructions: (1) This form is to be compared and all safety occessioner areas, machinery statements by the barge(s), correct tubricating oils, hydraulic o	sible areas where o prage areas, wellde we action must be in	chemicals, oils, dry ce cks and other areas) itiated. [Ref: VGP 4.	ingo, or other materials are [Ref: VGP 4.1.1] (3) If po [.1] (4) The term "shoen" is	stored, mix ilutants or d	ked and used (inclu constituents of con	oding, as applicable ocem are determine	e, cargo holds. Ed to be originati
Are Decks Clean?	⊡	Any \	/iolations Discovered d	uring last	pection or any cr	orrective action:	s required?
if no, were decks clea	ned?						
Is the Water around the free of sheen?	barge 🗹						
Was a sample taken?							
Voids or Hopper Pumpe	d? []						
Sheen present in wat pumping?	erafier 🗀						
Inspected by (Printed)	Paul Roman						
Approved by (Printed)	Paul Roman		Approved b	y (Signati	ure) Apa	linant	92070.00
Entwing your Signature Pt proclems noted	. អាយុខទី៩៩៦៩២៩	tarçıyısı have been .	изульяес и асполбалов аз	s ನಡೆಯ <b>ಕ</b> ಾರೆ	sto.		



Equipment	IM I 119			Vessel/Asset:	Aggie-C	
Company:	Canal Barg	e Company		Walerway:	Illinois River	/ 329.9
Inspection Date Time:	06/19/2015	22 16		Location	WALSH FLEET	
Load Status:	CEmpty	O Partial	Loaded			
ereas and all safely acci- boiler areas, machinery:	essible areas v storage areas, ctive action mu	vhere chemical welldecks and stibe initiated. [	is, oils, dry cargo, or oth other areas). [Ref: VGI [Ref: VGP 4.1.1] (4) The	er materials are stored, mi 2.4.1.1] (3) If pollutants or term "sheen" is to be und	xed and used (including, a constituents of concern a	accessible deck and cargo as applicable, cargo holds, are determined to be originating on of oil or grease, including
Are Decks Clean?	[2	)	Any Violations	Discovered during Ins	pection or any correc	live actions required?
lf no, were decks cla	eaned? [	]				
is the Water around the	e barge	Ži				
Was a sample take	n?					
Voids or Hopper Pump	ed?	]				
Sheen present in w pumping?	aterafter [					
Inspected by (Printed	ı) Jeff Bloor	<b>ឃ</b> ៀទ[ជ				
Approved by (Printed	) Jeff Bloon	rfield		Approved by (Signal	ure) .	i
finterlag year Signacus Silottens until f	Etz e (catea n	na Kisilian eza	Pave bear signafad u	3), 20) ម៉ឺង១១៩ ឧទ. ១៨២៩២៨	one Gaffrey	. B. Georgiales



Equipment: IN	AT129			Vessel/Asset	Aggre-C	
Company: C	anal Barge	Company		Waterway:	Minois River	/ 329.9
Inspection Date Time' 0	6/19/2016	22 15		Location	WALSH FLEET	
Load Status.	O Empty (	⊜Partial 🏵	Loaded			
areas and all safely access boiler areas, machinery sto from the barge(a), correctly	sible areas w rage areas, w re action mus	here chemical velidecks and t be initiated. [	voyage, whichever is more tre is, offe, dry cargo, or other mate other areas) [Ref: VGP 4.1.1] [Ref: VGP 4.1.1] (4) The term "s c oils [Ref VGP Fact Sheet 3.4	rials are stored, mb (3) If pollutants or d sheen" is to be unde	red and used (including, a constituents of concern a	as applicable, cargo helds, are determined to be originaling
Are Decks Clean?			Any Violations Discov	vered during Inst	pection or any correct	tive actions required?
if no, were decks clear	ned?					
is the Water around the b	arge 🗹					
Was a sample taken?						
Voids of Hopper Pumped	? []					
Sheen present in wate pumping?	rafter 🗍					
Inspected by (Printed)	Jeff Bloom	field				
Approved by (Printed)	Jeff Bloomi	eld	Аррі	roved by (Signati	ire)	<i>;</i> ;
Fotering your Eliginature 한다. Elegtifiches ented	গ্ৰভাৱন্তৰ প্ৰভ	វ ម៉ាខ ដែលចុខ នៃ	have teen especial in appoint	ionee as mulales .	ones suffer	B bomfule

Equipment:	IMT142		Vessel/Asset: Aggi	e-C
Company:	Canal Bar	ge Compar	y Waterway: Illino	is River / 329.9
Inspection Date Time:	06/19/201	5 22.16	Location: WAL	SH FLEET
Load Status:	○ Emp	ty 🔾 Partial	€ Loaded	
ereas and at safely acce boiler areas, machinery a from the barge(s), correc	essible areas dorage areas ctive action n	where chen s, weldecks : nust be initiate	per voyage, whichever is more frequent. (2) Locations to be ichls, oils, dry cargo, or other materials are stored, mixed and other areas). [Ref; VGP 4.1.1] (3) If pollutants or constitute. (Ref; VGP 4.1.1] (4) The term "sheen" is to be understandance oils [Ref VGP Fact Sheet 3.4.4]	d used (including, as applicable, cargo holds, uents of concern are determined to be originating
Are Decks Clean?	[	<b>9</b>	Any Violations Discovered during Inspection	on or any corrective actions required?
if no, were decks cle	aned?			
is the Water around the free of sheen?	e barge	<b>2</b>		
Was a sample taker	ን?			
Voids or Hopper Pump	ed?			
Sheen present in wa pumping?	aler atter	ם		
Inspected by (Printed)	) Jeff Bloc	nnfield		
Approved by (Printed)	Jeff Bloo	mfield	Approved by (Signature)	. ,,
florering year Signature F purblerer redesi	Standicares	met the beig	File thave trees experiment in activities was that reserving in	Juffrey Blomfuld



Equipment	PB2006		Vessel/Asset: Ag	ggie-C	
Company:	Canal Barg	e Company	Waterway: Illi	inois River	/ 329.9
Inspection Date Time	06/19/2015	22:16	Location: W	ALSH FLEET	
Load Status:	○ Empty	O Partial	Loaded		
areas and all safely occe boiler areas, machinery a from the barge(s), correc	ssible areas v torage areas, tive action mu	vhere chomical welldecks and st be initiated. [	voyage, whichever is more frequent. (2) Locations to s, oils, dry cargo, or other materials are stored, mixed other areas). [Ref: VGP 4.1.1] (3) If pollutants or con Ref: VGP 4.1.1] (4) The term "sheen" is to be underst c oils [Ref VGP Fact Sheet 3.4.4].	and used (including, as stituents of concern are	applicable, cargo holds, determined to be originating
Are Decks Clean?	, L		Any Violations Discovered during Inspec	ction or any correctiv	e actions required?
If no, were decks cle	aned?				
Is the Water around the free of sheen? Was a sample taker					
Voids or Hopper Pump	ed? [	7			
Sheen present in wa pumping?	•				
Inspected by (Printed)	Jef Bloon	าโเอโฮ			
Approved by (Printed)	Jeff Bloom	nfield	Approved by (Signature)		- 1 .
Enfecting your Gerature P problems i to d	Rendriasea in	at the basses	भेकान देवहमा पश्चाद दोदव रा कर्यात्वा विकास करा आवीर अधिद अधि	n Gapting	B Georgiales

Equipment: T	13835		√esse	l/Asset:	Mary C	
Company	ngram Barge	e Company	Wa	aterway:	Illinois River	i 278
Inspection Date Time 0	6/19/2015	23.55	Ĺ	ocation:	IMT Chan (Crane)	
Load Status;	○Empty(	Partial <b>()</b> l	_0aded		•	
areas and all sately access boiler areas, machinery sto from the barge(s), correcting	sible areas wi Irage areas, w Ve action musi	iere chemicals relidecks and ( i be initiated, [F	royage, whichever is more frequent. (2), oils, dry cargo, or other materials are sither areas). [Reft VGP 4.1.1] (3) If polluteft VGP 4.1.1] (4) The term "sheen" is toils [Ref VGP Fact Sheet 3.4.4]	tored, mb Annis or d	ed and used (including, a constituents of concern a	is applicable, cargo helds, re determined to be originating
Are Decks Clean?	V		Any Violations Discovered du	ring Inst	ection or any correct	lve actions required?
If no, were decks clear	ned?					
is the Water around the lifee of sheen?	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	1? 📋					
Sheen present in wate pumping?	erafter 🗆					
Inspected by (Printed)	BARNARD.	/CALLAHAN				
Approved by (Printed)	Robert Smi	ih	Approved by	(Signatu	ite)	
Fotering your Signature Pili problems noted	r molentes that	the bargers	nave been inspected in accordance as it	s betaoibn	John John Co	Southful for any
						V

### Vessel General Permit Compliance

Vessel/Asset, Midwest Pride

IN075408

Equipment:

Company: Ir	ngram Bargi	e Company		Waterway.	Illinois River	/ 278
Inspection Date Time 0	6/19/2015	23 56		Location:	Rapps Fleet	
Load Status:	() Empty (	) Partial 🖲 i	_osded			
ereas and all sefely access boiler areas, machinery sto from the barge(s), correction	sible areas wi rage areas, w ve action musi	nere chemicals velidecks and d t be initiated. [F	, oils, dry cargo, or other mate ther areas} [Ref: VGP 4.1.1	erials are stored, mi   (3) If pollutants or   sheen" is to be und	xed and used (included) constituents of cond	afely accessible deck and cargo ding, as applicable, cargo holds, cern are determined to be originating ntration of oil or grease, including
Are Decks Clean?	v		Any Violations Disco	vered during Ins	pection or any co	rrective actions required?
If no, were decks clear	ned?		nane			
Is the Water around the t	parge 🖸					
Was a sample taken?						
	* * ·					
Voids or Hopper Pumped	i? []					
Sheen present in wate pumping?	er affer 🗀	· in a second residence of		4 - 12		
Inspected by (Printed)	BJ Thomas	•				
Approved by (Printed)	BJ Thomas		Apş	roved by (Signat	•	
Entering your Algorithms Pt. problems anted	indicates tha	t the Largers (	have been inspected in accord	dance as indicated	abov 10.xl	by for Thomas

Vessel General Permit Compliance

Equipment: If	1025309		Vess	el/Asset.	Midwest Pinde	
Company ir	ngram Barge	Company	W	/aterway:	Illinois River	ı 278
Inspection Date Time: 0	6/20/2015	09:05	i	Location:	Rapps Fleet	
Load Status:	○ Empty ○	Partial <b>®</b> L	oaded		,.	
boiler areas, machinery sto from the barge(s), correction	sible areas who rage areas, wo ve action must l	ere chemicals, eldecks and of se initiated. [Re	oyage, whichever is more frequent (2 oils, dry cargo, or other materials are her areas). [Ref: VGP 4.1.1] (3) if pol of: VGP 4.1.1] (4) The term "sheen" is oils [Ref VGP Fact Sheet 3.4.4]	stored, mb Estants or i	ked and used (including, constituents of concern.	as applicable, cargo holds,
Are Decks Clean?	[7]		Any Violations Discovered di	uring Ins;	pection or any correc	tive actions required?
lf no, were decks clear	ned?					
Is the Water around the tifree of sheen?	oarge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	?					
Sheen present in wate pumping?	raffer 🖂					
Inspected by (Printed)	james wexel	berg				
Approved by (Printed)	Tommy Walt	61	Approved by	/ (Signatu		
Enterley your Signature 61:	addines that	Se usrpetsi h	tur pees sepacted is accordance as	masoted :	sbov.	gen Ad With



problems coled

Equipment:	ING5524			Vessi	el/Asset:	Midwest F	ʻride		
Company:	Ingram Ba	arge Comp	any	řΛι	aterway:	Ilinois Riv	91	1	278
Inspection Date Time	06/20/201	15 10 <b>1</b> 5		L	.ocation:	Rapps Fle	et		
Load Status.	○Emp	oty O Partia	1 🖲 Loaded						
Instructions: (1) This form is to be congress and all safety acceptions areas, machinery a from the barge(s), correctlubricating oils, hydraulic	essible areas storage area ctive action r	s where che: is, welldecks must be initiat	nicals, oils, dry cargo, and other areas). [Re ed. [Ref: VGP 4,1,1] (	or other materials are s f: VGP 4.1.1] (3) if poli 4) The term "sheen" is	stored, mix utants or c	ed and used a streutiteno:	(moluding, as a f concern are	applicable, determined	cargo holds, to be precinating
Are Decks Clean?			Any Viola	tions Discovered du	ıring Insp	ection or a	ny corrective	e actions (	required?
If no, were decks cle	aned?						·		
Is the Water around the	e barge								
free of sheen?	<b>"</b>								
Was a sample taker	1?								
Voids or Hopper Pumpi	ed?								
Sheen present in wa pumping?	ater after								
inspected by (Frinted)	) james v	yexelberg							
Approved by (Printed)	Tommy	Walter		Approved by	(Signatu	re)			
Prieseljy zmáznakom k volumek nadel	ina terpapak	france cog	en Solikking timen neg e	rted mogenty dieny, elde	o englação	4.75	Sin. of	i	÷



Equipment If	M1109		Ves	sel/Asset: Ag	gie-C	
Company: C	anal Barge Com	pany		Waterway: Ilir	nois River	/ 329.9
Inspection Date Time 0	6/20/2015 18:	30		Location: W.	ALSH FLEET	
Load Status:	○ Empty ○ Par	rtial   Loaded				
Instructions: (1) This form is to be compared and all safety access boiler areas, machinery sto from the barge(s), correctifutoricating oils, hydraulic oil	sible areas where of rage areas, welided ve action must be ini	hemicals, oils, dry car cks and other areas). iliated. [Ref: VGP 4.1,	go, or other materials ar [Ref: VGP 4.1.1] (3) If p 1] (4) The term "sheen"	e stored, mixed : ollutants or cons	and used (including, as dituents of concern are	applicable, cargo holds. e determined to be originatino
Are Decks Clean?	7	Any Vi	olations Discovered	during Inspec	tion or any correctly	ve actions required?
lfino, ware decks clear	ned?	The same of the sa				
Is the Water around the t	oarge 🖸					
Was a sample taken?						
Voids or Hopper Pumped	?					
Sheen present in wate pumping?	er after	- Inchaspers o				
Inspected by (Printed)	Jeff Bloomfield					
Approved by (Printed)	Jeff Bloomfield		Approved	<b>by</b> (Signature)	4	s)
Entering your Signature Pila problems anted	indicates that the b-	argeisj have neen ms	ipented in accourdance o	is indicated above	( , explosing	B bromfacted



Vessel General Permit Compliance

Equipment:	OR5337		Vesse	Masset: Midwest	Pride	
Company:	Ingram Barq	je Company	Wa	terway: Illinois R	IVET	j 278
Inspection Date Time:	06/22/2015	12 10	L.	ocation: IMT Cha	nnahon Repair Do	ock
Load Status:	CEmpty	⊕Partial <b>®</b> Lo	oaded			
eress and all safety acc boller areas machinery from the barge(s), corre	essible areas v storage areas, ctive action mu	rhere chemicals, wellocks and of stibe initiated. (Re	yege, whichever is more frequent. (2) olfs, dry cargo, or other materials are s her areas). [Ref: VGP 4.1.1] (3) If pollu- if: VGP 4.1.1] (4) The term "sheen" is t ills [Ref VGP Fact Sheet 3.4.4]	tored, mixed and us tants or constituent	ed (including, as app s of concern are det	licable, cargo holds, esmined to be originatio
Are Decks Clean?	Z	]	Any Violations Discovered du	ring Inspection of	rany corrective at	ctions required?
If no, were decks clo	eaned?	]				
,						
is the Water around th	e barge	)				
Was a sample take	n? [	]				
Voids or Hopper Pump	ed?	)				
Sheen present in w pumping?	aterafter [					
Inspected by (Printed	f) james we	xelberg				
Approved by (Printed	) Tommy W	'alter	Approved by	(Signature)		
Enteriora yeur Sicestore	Eli distates tr	Antie targers in	ave teen an versed in ancordance as:	admated closs	! .	$\frac{1}{2} = \frac{1}{2} = \frac{e}{2}$

unitional void integration of a partition to a first arights. Take tipor unit, action in and realist as non-arraidude Light femilianist



Vessel General Permit Compliance

Equipment:	QR5337		Vessel/Asset: N	Aidwest Pride	
Company:	Ingram Barge Cor	npany	Waterway: II	linois River	<i>j</i> 278
Inspection Date Time:	06/22/2015 12:	10	Location: If	VIT Channahon Repair	Dock
Load Status:	○Empty ○Pa	riial 📵 Loaded			
areas and all safety acce boxer areas, machinery s from the barge(s), correc	essible areas where c dorage areas, wellded dive action must be in	hemicals, pils, dry cargo, er eks and other areas) [Ref: 1	is more frequent. (2) Locations to other materials are stored, mixed (GP 4.1.1) (3) If pollutants or control term "sheen" is to be undersubsect 3.4.4)	d and used (including, as a astituents of concern are d	pplicable, cargo holds. Jetermined to be originating
Are Decks Clean?	<b>3</b>	Any Violatio	ns Discovered during Inspe	ction or any corrective	actions regulred?
If no, were decks cle	aned?	No. all description of the control o			
is the Water around the free of sheen?	e barge				
Was a sample taker	n? 📋	and the second s			
Voids or Hopper Pump	ed?				
Sheen present in wa pumping?	ater after				
Inspected by (Printed)		9			
Approved by (Printed)	Tommy Walier		Approved by (Signature	<b>;</b> )	

Entering your Riginature PIN indicates that the bargers: have been inspected in accordance as indicated aborproblems noted.



#### Vessel General Permit Compliance

Equipment:	N107013		VesseV.	Asset	Midwest Pride	
Company:	ngram Barg	e Company	Wale	rway:	: Illinois River	/ 278
Inspection Date Time	06/22/2015	12 45	Lac	ation:	Rapps Fleet	
Load Status:	() Empty	⊃Partiat <b>⊕</b> l	.oaded			
areas and all safety access poller areas, machinery st from the barge(s), correct	ssible areas w orage areas, v tive action mus	here chemicals welldecks and i it be initiated. [f	royage, whichever is more frequent. (2) L , oils, dry cargo, or other materials are sto other areas) [Ref: VGP 4.1-1] (3) if pollute Ref: VGP 4.1-1] (4) The term "sheen" is to oils [Ref VGP Fact Sheet 3.4-4]	red, mi n <b>ts</b> or	ixed and used (including, a constituents of concern a	is applicable, cargo holds, re determined to be originating
Are Decks Clean?	V	-	Any Violations Discovered duri	ng Ins	spection or any correct	ive actions required?
if no, were decks clea	aned?					
is the Water around the free of sheen?	barge ☑					
Was a sample taken	?					
						,
Voids or Hopper Pumpe	d? <u></u>					
Sheen present in wa pumping?	ter after					
Inspected by (Printed)	jamės wex	telberg				
Approved by (Printed)	Tonimy W	alter	Approved by (	Signal	ture)	
					1	F 1

Fintering your Signature CN. Indicates that the barger's insize trees respect to it is accompanied as indicates above problems in the



Equipment:	CBY439		Vessel/Asset	Windy City	
Company;	Canal Bar	ge Compar	ny Waterway.	: Illinois River	1 293
Inspection Date Time.	06/23/201	5 10:40	Location	OXBOW	
Load Status.	○ Emp	ity 🔾 Partial	© Loaded		
areas and all safely accest boiler areas, machinery st from the barge(s), correc	ssible areas torage area: tive action n	where chems. welldecks: nust be initiate	per voyage, whichever is more frequent. (2) Location iicals, oils, dry cargo, or other materials are stored, mand other areas). [Ref: VGP 4.1.1] (3) If poliutants or ed. [Ref: VGP 4.1.1] (4) The term "sheen" is to be unopanic oils [Ref VGP Fact Sheet 3.4.4]	ixed and used (including, as applicable constituents of concern are determined.)	ile, cargo holds, ned to be originating
Are Decks Clean?			Any Violations Discovered during Ins	spection or any corrective action	ns required?
If no, were decks clea	aned?				
is the Water around the free of sheen? Was a sample taken	-	<b>2</b>			
Voids of Hopper Pumpe	ed?				
Sheen present in wa pumping?	ter after				
Inspected by (Printed)	eric han	son			
Approved by (Printed)	David Cu	ullman	Approved by (Signal	ture)	
Enternoj your Signati Le P postilana Indea	Ni edicares	that the barg	is si have been respected in arwordance as indicated	stor Main / C	Minor

Equipment:	IN065105		Vessel/Asset:	Midwest Pride	
Company:	Ingram Barg	e Company	Waterway:	Illinois River	<i>i</i> 278
inspection Date Time:	06/23/2015	22 15	Location:	Rapps Fleet	
Load Status:	CEmpty	OPartial 🍳	Loaded		
areas and all safely acce boiler areas, machinery a from the barge(s), correc	ssible areas waterage areas, to tage action mus	here chemica welldecks and it be initiated.	r voyage, whichever is more frequent. (2) Location ils, oils, dry cargo, or other materials are stored, mid I other areas). [Ref: VGP 4.1.1] (3) if pollutents or [Ref: VGP 4.1.1] (4) The term "sheen" is to be und ic oils [Ref VGP Faut Sheet 3.4.4]	xed and used (including, as constituents of concern ar	s applicable, cargo holds, re determined to be originati
Are Decks Clean?	Z		Any Violations Discovered during Ins	pection or any correcti	ve actions required?
If no, were decks cle	aned?		none		
is the Water around the	e barge				
Was a sample taker	ار [				
Voids or Hopper Pump	ed?				
Sheen present in wa pumping?	eter after				
Inspected by (Printed	) BJ Thoma	9			
Approved by (Printed)	BJ Thoma	5	Approved by (Signat	· ·	
Criecky your Signer he i problems educt	Per dicalest	stur bargor	:/ liver hacri ik spritted ik accerdance as inocated	ate Billy	Let Homen



Equipment: T	13835		Ve	ssel/Asset	Midwest Pride	
Company: li	igram Barge	Company		Waterway:	Illinois River	ı 279
Inspection Date Time: 0	6/24/2015	10 55		Location:	Farmer Bobs	
Load Status:	○ Empty ○	) Partial 🖲 L	oaded			
areas and all safely acces- boiler areas, machinery sto from the barge(s), correcti	sible areas wh prage areas, w ve action must	ere chemicals, elidecks and o be initiated, (R	oyage, whichever is more frequent oils, dry cargo, or other materials a ther areas). [Ref: VGP 4.1.1] (3) If ef: VGP 4.1.1] (4) The term "sheen oils [Ref VGP Fact Sheet 3.4.4]	are stored, mi poliutants or	xed and used (includin constituents of concer	g, as applicable, cargo holds, n are determined to be originating
Are Decks Clean?	$\Box$		Any Violations Discovered	d during Ins	pection or any corr	ective actions required?
If no, were decks clea	ned?					
is the Water around the tree of sheen?	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumpe	d? 🗀					
Sheen present in wat pumping?	erafter 🗀					
Inspected by (Printed)	james wax	alberg				
Approved by (Printed)	Tommy Wa	lter	Approve	d by (Signa	lure)	
Entering your Signature Pf protients noted	connectes that	ine hazgess i	have been inspected in accordance	e as indicated	addy	

Equipment: I	N005023	Vessel/Asset. Midwest Pride
Company:	ngram Barge Con	any Waterway: Illinois River / 278
Inspection Date Time.	06/24/2015 14	Location: Rapps Fleet
Load Status:	○Empty ○Par	el 🕲 Loaded
areas and all safely acces boiler areas, machinery st from the barge(s), correct	sible areas where conage areas, wellded ive action must be ini	r per voyage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo micals, oils dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, and other areas). [Ref: VGP 4.1.1] (3) if pollutants or constituents of concern are determined to be originating ted. [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grosse, including the genic oils [Ref VGP Fact Sheet 3.4.4].
Are Decks Clean?	<b>☑</b>	Any Violations Discovered during Inspection or any corrective actions required?
If no, were decks clea	ined?	
is the Water around the free of sheen?	parge 🖸	
Was a sample taken'	? 🗆	
Voids or Hopper Pumpe	d? []	
Sheen present in wat pumping?	terafter [_]	
Inspected by (Printed)	ismes wavelhan	
Approved by (Printed)		Approved by (Signature)
Approved by (minted)	Tommy vender	Approved by (orginalize)
Enranda your Signature Pl problems holed	ti makales that the t	gers, have been respected in accordance as indicated above.



Vessel General Permit Compliance

Vessel/Asset: Windy City

Company:	ngram Barg	e Company			Waterway:	Illinois River	r	/ 293
Inspection Date Time:	06/24/2015	14 35			Location:	WORKO		
Load Status:	○ Empty	O Partial 🕲	Loaded					
Instructions: (1) This form is to be compared and all safely acceptioner areas, machinery of from the barge(s), correct lubricating oils, hydrautic of	isible areas w orage areas. ive action mus	there chemicals welldecks and at be initiated. []	s, eils, dry cargo, i other areas), [Ref Ref: VGP 4.1.1] (4	or other materials a f: VGP 4.1.1] (3) if 4) The term "sheen	are slored, mb pollutants or e	ced and used ( constituents of	including, as appli concern are dete	cable, cargo holds, ermined to be originatin
Are Decks Clean?	E		Any Violat	tions Discovere	d during ins	pection or an	ıy corrective ac	tions required?
If no, were decks clea	aned?							
is the Water around the free of sheen?	barge 🗹							
Was a sample taken	? [							
Voids or Hopper Pumpe	d? [	,						
Sheen present in wa pumping?	•	)						
Inspected by (Printed)	baer							
Approved by (Printed)	Shannon I	Morlang		Арргоче	d by (Signat	ure) Shau	lueth met	U467
Emerica yaw Signstora P Judovenia notod	Hilagitates N	at the bargers .	, গ্রহণ হলত। একচেট	ciedin acculdanci	e as individud	HI I .		of er any



Equipment:

IN075211

Equipment:	N005023			Vessel/Asset	Midwest Pride	
Company:	Ingram Barg	ge Company		Waterway:	Illinois River	/ 278
Inspection Date Time:	06/24/2015	15:10		Location:	IMT Chan (Crane)	
Load Status:	O Empty	OPartial (9)	_oaded			
areas and all safely accer boiler areas, machinery st from the barge(s), correct	ssible areas v lorage areas, live action mu	there chemicals welldecks and out to initiated. [F	, oils, dry cargo, or other m other areas) [Ref: VGP 4.1	aterials are stored, mix .1] (3) If pollutants or c n "sheen" is to be unde	s to be inspected: Safety accessified and used (including, as applicionstituents of concern are determined as a concentration of oil of the concentration of the concentration of oil of the concentration of the concentration of the concentration of the concentration of oil of the concentration of oil	able, cargo holds, mined to be originating
Are Decks Clean?	Į.	]	Any Violations Dis	covered during inst	pection or any corrective acti	ons required?
If no, were decks clea	aned?					
is the Water around the free of sheen?	barge 🔀					
Was a sample taken	, [					
Voids or Hopper Pumpe	·47 [	ו				
Sheen present in wa pumping?		]				
Inspected by (Printed)	james we	xelberg				
Approved by (Printed)	Tommy W	alter	A	pproved by (Signate	·	
Entering your Signature P proclams noted	#I indicates th	of the barge(s)	høve been inspected in oc.	erdance as erdicaled	i ្	to by Maria



Equipment:	IN075211		Vessel/Asset	Albert C	
Company:	Ingram Barge	Company	Waterway:	Illinois River	1 299.4
Inspection Date Time:	06/24/2015	20 00	Location:	SYS	
Load Status:	O Empty (	Parlial 🏵	Loaded		
areas and all safely acce boiler areas, machinery s from the barge(s), correc	essible areas wh Morage areas, w ctive action must	ere chemica elidecks and be initiated	voyage, whichever is more frequent. (2) Location is, oils, dry cargo, or other materials are stored, mix other areas? [Ref; VGP 4.1.1] (3) if pollutaris or (Ref; VGP 4.1.1] (4) The term "sheen" is to be undicted to the collast of t	ked and used (including, as a) constituents of concern are d	pplicable, cargo hoids, letermined to be priopati
Are Decks Clean?	$\square$		Any Violations Discovered during Ins	pection or any corrective	actions required?
if no, were decks ale	aned? []		rione		
Is the Water around the free of sheen?	e barge				
Was a sample taker	1?				
		anan ye Product of Pundan			
Voids or Hopper Pump	ed? .				
Sheen present in wa pumping?	eteratter 🔲	****			
Inspected by (Printed)	) Fatrick Don	g			
Approved by (Printed)	Antonie Lep	ez	Approved by (Signatu	iie)	
Entrakty von Syntation f Großkon herted	de dituenden	t-witarge	flave rage mayerson to vocaro vilbe as indicated	Antonio	Lopez



### Vessel General Permit Compliance

Vessel/Asset. Midwest Pride

Company: Ir	igram Barge	Company		Waterway.	Illinois River	1 278
Inspection Date Time: 0	6/25/2015	11 05		Location:	Rapps Fleet	
Load Status:	○ Empty ○	) Partial 🏵 t	_osded			
areas and all safely access boiler areas, machinery sto	sible areas wh rage areas, w ve action must	ere chemicals elidecks and d be initiated. (F	, oils, dry cargo, or oth other areas) [Ref: VGI Ref: VGP 4.1.1] (4) The	er materials a a stored, mi 2 4.1.1] (3) If pollutants or term "shean" is to be und	exed and used (incl constituents of co	Safely accessible deck and cargo luding, as applicable, cargo holds, neern are determined to be originating entration of oil or grease, including
Are Decks Clean?	$oxed{oldsymbol{oldsymbol{arphi}}}$		Any Violations	Discovered during ins	spection or any c	corrective actions required?
if no, were decks clear	ned?		none			
is the Water around the I free of sheen?	barge 🗹					
Was a sample taken?						
Voids or Hopper Pumped	1? [``]					
Sheen present in wate pumping?						
Inspected by (Printed)	BJ Thomas					
Approved by (Printed)	BJ Thomas			Approved by (Signa		wi a
Entererg your Signature Pr products noted	, indicates that	ice brige s'	te æliker øspected i	accondigue as subspled	laver — —	they feet farmen



Equipment:

IN107013

Equipment:	IN096061		Vessel/Asset: Albert C	P
Company	Ingram Ba	rge Company	Waterway, Illinois River	/ 299,4
Inspection Date Time:	06/25/2019	5 13:00	Location: IMT Lemont (Lower	Crane)
Load Status:	○ Empl	y 🔾 Partial 🏵 l	Loaded	
areas and all safely acce boiler areas, machinery a from the barge(s), corre	essible areas storage areas ctive action m	where chemicals welldecks and out to be initiated. [f	voyage, whichever is more frequent. (2) Locations to be inspected: Safely soils, dry cargo, or other materials are stored, mixed and used (including, other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration oils [Ref VGP Fact Sheet 3.4.4]	as applicable, cargo holds. are determined to be originating
Are Decks Clean?		<b>2</b> ]	Any Violations Discovered during Inspection or any correc	tive actions required?
If no, were decks cleaned?				
is the Water around the free of sheen?	e barge	<u>J</u>		
Was a sample take	υş			
Voids or Hopper Pump	ed?			
Sheen present in w pumping?	ater after			
Inspected by (Printed	) Peter Ki	osik		
Approved by (Printed	) Peter Ko	sik	Approved by (Signalure)	,
bistering your Signature proof, his hided	PM indiceths	that the bargets	bave been hisperied in appridance as indicated above.	In & for any

Vessel General Permit Compliance

Vessel/Asset: Mary C

IN025309

Equipment:

Company:	Ingram Barg	e Company		Waterway:	Illinois River	1 278	
nspection Date Time:	06/25/2015	13:10		Location	IMT Chan (Crar	ie)	
_oad Status;	○ Empty	○ Partìal <b>⑥</b> I	Loaded				
ereas and all safety acce boiler areas, machinery a from the barge(s), correc	ssible areas w torage areas, v ctive action mus	here chemicals welldecks and o it be initiated. [f	i, oils, dry cargo, or other other areas) [Ref: VGP 4	materials are stored, mid .1.1] (3) If pollutants or rm "sheen" is to be und	ked and used (inclu constituents of con	Safely accessible deck and cargo ding, as applicable, cargo hous, cern are determined to be origina entration of oil or grease, including	itin
Are Decks Clean?	Ø	and the latest and th	Any Violations Di	scovered during Ins	pection or any co	orrective actions required?	
if no, were decks cle	aned?						
Is the Water around the free of sheen?	e barge ✓						
Was a sample taker	1?						
Voids or Hopper Pump	ed?						
Sheen present in wa pumping?	eterafter [						
Inspected by (Printed	; BARNARI	)/WALTERS	/CALLAHAN				
Approved by (Printed)	Robert Sm	ith		Approved by (Signat	nte)		
Perento vaur Egaetura I eter (en 8 i mis d	All Podescentin	Stipe ( arge.g	have then orped to sa	ता अजैन्यत्व <b>उप ४ में दक्षान्त्री</b>	over Johnst	In Saway term	ì)

Equipment:	T13826		Vessel/Asse	t: Midwest Pride	
Company:	Ingram Barg	je Company	Waterwa	y: Illinois River	<i>t</i> 279
Inspection Date Time:	06/25/2015	13:15	Location	r: Farmer Bobs	
Load Status:	○ Empty	() Partial ®	Loaded		
areas and all safely acce boiler areas, machinery s from the barge(s), correc	esible areas v torage areas, ctive action mu	rhere chemica welldecks and stibe initiated, j	voyage, whichever is more frequent. (2) Locations, oils, dry cargo, or other materials are stored, restored areas.) [Ref: VGP 4.1.1] (3) If pollutants of [Ref: VGP 4.1.1] (4) The term "sheen" is to be uncoils [Ref VGP Fact Shee1 3.4.4]	niked and used (includin r constituents of concer	ig, as applicable, cargo holds, rn are determined to be originating
Are Decks Clean?	<u> </u>		Any Violations Discovered Juring in	spection or any corr	ective actions required?
if no, were decks cle	aned?	)	none		
		Production 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	(Veri)		
Is the Water around the free of sheen?	e barge	)			
Was a sample taker	1?	)			
Voids or Hopper Pumpi	ed?	]			
Sheen present in wa pumping?	iterafter [				
Inspected by (Printed)	) - BJ Thoma	\$			
Approved by (Printed)	BJ Thoma	S	Approved by (Signs	_	
Amelog yawangost se P Litakha shika	选点 1550分钟长度	at 1997 11 6 6 8	१९५१ - इ.स.च. १९९६ - टॉन्टर १८ अंगाच्या रहेका १८ वर्ष कर्ता रही रहीन	ranz Billy	of fretherman



### Vessel General Pennit Compliance

Vessel/Asset Midwest Pride

IHG6515

Equipment

Company. I	ngram Barg	e Company		W	aterway.	Illinois River		1279
Inspection Date Time (	06/25/2015	14 15		Ļ	ocation:	Farmer Bobs		
Load Status;	CEmpty	🔾 Partial 🌘	Loaded					
Instructions: (1) This form is to be compareas and all safety accessoiler areas, machinery statement the barge(s), correction the barge(s), correction of the barge(s).	sible areas w arage areas, i ve action mus	here chemical welldecks and it be initiated.	ls, pils, dry cargo, or i other areas). [Ref: V [Ref: VGP 4.1.1] (4) ]	other materials are s 'GP 4.1.1] (3) If poll The term "sheen" is t	itored, mb itants or	ked and used (in constituents of c	cluding, as applica concern are determ	ble, cargo holds, ined to be originati
Are Decks Clean?	[Z		Any Violatio	ns Discovered du	ring Ins	pection or any	corrective action	ns required?
if no, were decks clea	ned? 🗀		none					
	a.	ļ						
is the Water around the free of sheen?	barge [고							
Was a sample taken?	?							
Voids or Hopper Pumpe	d? [							
Sheen present in wat pumping?	erafter C							
Inspected by (Printed)	BJ Thoma	S						
Approved by (Printed)	BJ Thoma:	S		Approved by	(Signat			
Enterrag voda Siçalatine F Volumba entra	i indidatea di	atibe anows	, nave been maps de	g in acromium se as	minsted	arby B	elly frets	home



Equipment:	IN118511B			Vessel/Asset	Albert C	
Company:	Ingram Bar	ge Company		Waterway	Illinois River	/ 293
Inspection Date Time	06/25/2015	14 15		Location:	OXBOW	
Load Status:	() Empty	○ Partial <b>®</b>	Loaded			
erees and all safely acce boiler areas, machinery s	ssible ereas v torage areas, tive action mu	where chemicals welldecks and at be initiated. [	s, oils, dry cargo, or otl other areas)[Ref: VG Ref: VGP 4.1.1] (4) Th	ner materials are stored, mb P 4.1.1] (3) if pollutants or o e term "sheen" is to be unde	ked and used (including constituents of concern	ly accessible deck and cargo , as applicable, cargo holds, , are determined to be originating tion of oil or grease, including
Are Decks Clean?	[5	<b>9</b>	Any Violations	Discovered during Ins	pection or any corre	ctive actions required?
If no, were decks cle	aned? [					
is the Water around the free of sheen?	ebarge [					
Was a sample taker	)? [	)				
Maida ar Manag Duman	ר מאס	7				
Voids or Hopper Pump Sheen present in wa pumping?	eter offer	]				
Inspected by (Printed)	) Peter Ko	sik				
Approved by (Printed)	Peter Kos	sik		Approved by (Signate	ure)	,
Entering your Spicelers Forel Kills Hoted	er administer h	retifik bergela)	have been imperied (	n Albant Sande as indepetat	stor fiter	for any

Equipment	T13826			Vessel/Asset:	Mary C	
Company:	Ingram Barg	e Company		Waterway:	Illinois River	/ 278
Inspection Date Time	06/25/2015	14-25		Location:	IMT Chan (Crane	)
Load Status:	○ Empty	O Partial ® L	oaded			
erees and all sefely acc boiler areas, machinery from the barge(s), corre	essible areas vi storage areas, ctive action mus	here chemicals welldecks and o it be initiated. [R	oils, dry cargo, or other mat ther areas). [Ref: VGP 4.1.1	erials are stored, mb [ (3) If pollutants or "sheen" is to be und	ced and used (includi constituents of conc	efely accessible deck and cargo ing, as applicable, cargo holds, ern are determined to be originating tration of oil or grease, including
Are Decks Clean?	₽.		Any Violations Disco	vered during Ins	pection or any cor	rective actions required?
if no, were decks cl	eaned?					
is the Water around th	e barge [✓					
Was a sample take	n? [					
Voids or Hopper Pump	ed?	)				
Sheen present in w pumping?	rater after	)				
Inspected by (Printed	a) BARNARI	O/WALTERS/	CALLAHAN			
Approved by (Printed	) Robert Sn	itn	Ap	proved by (Signat	ure)	
Extendig year Enginetians providents similar	≸d≱ admide∈2 to	af the bastanis i	inus neur i spected it kuns	វត្តកំពុម្ភ ឧស ៣៨៩៩២៩	John Lokel	w multy to any

### Vessel General Permit Compliance

IHG6515

Equipment.

Equipment.	NG6515		Vessel/Asset	Mary C	
Company: I	ngram Barge Cor	mpany	Waterway:	Illinois River	1 278
nspection Date Time: (	06/25/2015 15	.20	Location	IMT Chan (Crane)	
Load Status:	○Empty ○ Pa	rtial 🏵 Loaded			
areas and all safety acces boiler areas, machinery sto from the barge(s), correct	sible areas where corage areas, weliderive action must be in	chemicals, oils, dry cargo, o cks and other areas). [Ref:	r is more frequent (2) Location r other materials are stored, mi VGP 4.1.1] (3) If pollutants or ) The term "sheen" is to be und at Sheet 3.4.4]	xed and used (including, a constituents of concern at	s applicable, cargo holds. re detarmined to be originating
Are Decks Clean?	$oldsymbol{ol}}}}}}}}}}}}}}}}}}$	Any Violati	ons Discovered during Ins	pection or any correct	ive actions required?
if no, were decks clea	ined?				
is the Water around the free of sheen?	barge				
Was a sample taken	7 🗆	24. The state of t			
	per a cressa				
Voids or Hopper Pumpe	d? []				
Sheen present in wal pumping?	er after				
Inspected by (Printed)	6ARNARDAWA	LTERS/CALLAHAN			
Approved by (Printed)	Robert Smith		Approved by (Signat	ture)	
E we may your Separations be provide this proved	ে প্রস্থান্থ ক্রিয়া করে।	taige's law reer issued	ier in Socialdance as in ficilise	Tokul be	Succeed for any

Equipment:	T13826		V	essel/Asset	: Mary C	
Company:	Ingram Ba	rge Compa	ıy	Waterway:	Illinois River	1 279
Inspection Date Time	06/25/2015	5 15 43		Location:	: Load Fleet	
Load Status:	○Empt	y () Partial	<b>®</b> Loaded			
areas and all safely acce boller areas, machinery s from the barge(s), correc	ssible areas Norage areas Stive action m	where chemi , weldecks a ust be initiate	er voyage, whichever is more frequencials, oils, dry cargo, or other materials and other areas). [Ref: VGP 4.1.1] (3) !! [Ref: VGP 4.1.1] (4) The term "sheer oils [Ref VGP Fact Sheet 3.4.4]	cre stored, na f poliutants or	xed and used (including, as a constituents of concern are a	pplicable, cargo holds, fetermined to be orinication
Are Decks Clean?	[	☑	Any Violations Discovere	d during Ins	pection or any corrective	actions required?
lf no, were decks cle	aned? [			-		·
Is the Water around the free of sheen? Was a sample taker	- 6	9				
Voids or Hopper Pump Sheen present in wa pumping?	•					
Inspected by (Printed)	PARMAC	i Mayal TEI	I A HA LIAN PO			
Approved by (Printed)				d by (Signat	ura)	
					1 1	/ /
Patering your Supremier For other many of	SE odiceses n	bartherrya	<ul> <li>have then maybear him or charact</li> </ul>	ក្នុង កំពុំខេត្តកំពុ	Hobert les	weeky locany

#### Vessel General Permit Compliance

Vessel/Asset: Mary C

Waterway: Illinois River

IN075212

Ingram Barge Company

Equipment:

Company:

Inspection Date Time: 0	6/25/2015	18.20	Location: Mobil Coke Upper
Load Status:	O Empty (	) Partial <b>⊚</b> I	Loaded
areas and all safely access boiler areas, machinery sto from the barge(s), correction	sible areas wh rage areas, w ve action must	iere chemicals relidecka and d ba initiated. [F	royage, whichever is more frequent. (2) Locations to be inspected: Safety accessible deck and cargo, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds, other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originally Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including oils [Ref VGP Fact Sheet 3.4.4]
Are Decks Clean?	$ \mathbf{Q} $	1	Any Violations Discovered during Inspection or any corrective actions required?
lf no, were decks clear	ned? []		
Is the Water around the t	parge 💟		
Was a sample taken?		man temblish dala ay	
Voids or Hopper Pumped	l? []		
Sheen present in water pumping?	erafter 🗆		
Inspected by (Printed)	CALDRICH		
Approved by (Printed)	Carl Aldrich		Approved by (Signature)

Entering your Signature (Will obtained by the large (will have been inspected in accordance as indicated where and corrective active has been interesting any problems instead.



1277

Equipment:	IN1185116			Vessel/Asset	Albert C	
Company	Ingram Barge	Company		Waterway:	Illinois River	/ 299.4
Inspection Date Time	06/26/2015	07.55		Location:	MT Lemont (Low	er Crane)
Load Status:	C) Empty (	Partial <b>®</b> Lo	oaded			
areas and all safety accer bailer areas, machinery s from the barge(s), correc	ssible areas wt storage areas, w ctive action must	iere chemicals, i relidecks and off be initiated. [Re	olls, dry cargo, or other ma ner areas) [Ref: VGP 4.1.	iterials are stored, mb 1] (3) If pollutents or i i "sheen" is to be undi	ked and used (including constituents of concer	ely accessible deck and cargo ig, as applicable, cargo holds, in are determined to be originating ation of all or grease, including
Are Decks Clean?	V	į	Any Violations Disc	overed during Ins	pection or any corr	ective actions required?
If no, were decks cle	aned?					
is the Water around the	e barge 📝					
Was a sample taker	1?					
Voids of Hopper Pump	ed?					
Sheen present in wa pumping?	aterafier 🔲					
Inspected by (Printed	) Peter Kosi	k				
Approved by (Printed)	Peter Kosii	<	Ai	proved by (Signate	uie)	
Entering your dignature l groctems avied	Proindicates tha	(the cause, sub-	a ve ପ୍ରତ୍ୟ ୮୭,୧୯୯୩ଅଟି ଆ ୫୦୯	ordance as indicated	acci State	Mr & Tor any



Equipment:	IN075212			Vessel/Asset.	Mary C	
Company:	Ingram B	arge Compa	ny	Waterway:	Illinois River	/ 278
Inspection Date Time:	06/26/201	5 10 40		Location:	IMT Chan (Crane)	
Load Status:	() Emp	oty O Partial	<ul><li>Loaded</li></ul>			
areas and all safely acce boiler areas, machinery s	ssible area: torage area ctive action :	s where chem s. welldecks a nust be initiate	icels, oils, dry cargo, or and other areas). [Ref: d. [Ref: VGP 4.1.1] (4)	is more frequent. (2) Location other materials are stored, mo VGP 4.1.1] (3) If pollutants or a The term "streen" is to be under the term "streen" is to be under the term "streen".	ked and used (including, as constituents of concern are	applicable, cargo holds, determined to be originating
Are Decks Clean?			Any Violation	ons Discovered during Ins	pection or any correctiv	e actions required?
If no, were decks cle	aned?					
is the Water around the free of sheen? Was a sample taken	•	<b>3</b>				
Voids or Hopper Pump	ed?					
Sheen present in wa pumping?	ater after					
Inspected by (Printed	) BARNA	.RO/WALTE	RS/CALLAHN			
Approved by (Printed)	Robert S	Smith		Approved by (Signat	ure)	
Entering your Signistary t problems belief	್ಕ) ಇತ್ತಬ್ಚಾರಕ	that the barge	ns kase neer lege b	প্ৰ ি সভাৱ (dance ৰখ সকলবাহৰ	no Sobutter	weet for the engineery

Vessel General Permit Compliance

Vessel/Asset: Mary C

Company:	Ingram E	Jarge Company	Waterway: Illinois River / 278	
inspection Date Time:	06/26/20	15 11 35	Location: Rapps Fleet	
Load Status;	○ Em	pty () Partial (®	Loaded	
areas and all safely according to boiler areas, machinery to from the barge(\$), corre	essible area storage area ctive action	is where chemics as, welldacks and must be initiated,	voyage, whichever is more frequent. (2) Locations to be inspected. Safety accessible deck and is, olds, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, in coils [Ref VGP Fact Sheet 3.4.4]	holds, originaline
Are Decks Clean?		<b>2</b>	Any Violations Discovered during Inspection or any corrective actions requi	red?
if no, were decks cle	aned?			
		-		
is the Water around the free of sheen?	e barge	$\square$		
Was a sample takei	10			
		a ann a bhe a dhù ann an an an ann an ann an ann an ann an a		
Voids or Hopper Pump	ed?			
Sheen present in wa pumping?	ater after			
Inspected by (Printed	) BARNA	ARD/WALTERS	S/CALLAHAN	
Approved by (Printed)	Robert	Smith	Approved by (Signature)	
Entering your Signature to problems maked	Pri bdkoster	s that the sargers	trave been inspected in sopprishing as indicated error Hokul for multiple	for any

Equipment

IN995400

Equipment:	T13831			Vessel/Asset:	Midwest Pride	
Company:	Ingram Barge Co	ompany		Waterway:	Illinois River	/ 278
Inspection Date Time	06/26/2015 1	4-20		Location:	IMT Chan (Cra	ne)
Load Status:	○ Empty ○ P	artial ® Loaded				
areas and all safely acces boiler areas, machinery st	isible areas where orage areas, welld live action must be	chemicals, oils, dry ecks and other area initiated. [Ref: VGP	cargo, or other mater s) [Ref: VGP 4.1.1] ( 4.1.1] (4) The term 'sl	ials are stored, mb (3) If pollutants or ( heen" is to be und	xed and used (incl constituents of cor	Safely accessible deck and cargo uding, as applicable, cargo holds, neern are determined to be originating entration of oil or grease, including
Are Decks Clean?	<b>[</b> -]	An	y Violations Discov	ered during ins	pection or any c	orrective actions required?
If no, were decks clea	aned?	กดกร				
Is the Water around the free of sheen?	barge 🗹					
Was a sample taken	?					
Voids or Hopper Pumpe	2.2.2	, ,				
Sheen present in wa pumping?	ler affer					
Inspected by (Printed)	BJ Thomas					
Approved by (Printed)	EJ Thomas		Appr	oved by (Signati		
i areting your blypoline fi greb end salled	Classister traftse	harger - bove beer	ाक्ष्मकारका है। उटाका प्र	abbe as edunéas;	ation Bil	lly for Thomas

Equipment:	ING6538E	3		Vessel/Asset	Mary C	
Company:	Ingram Ba	arge Compan	ıy	Waterway	Illinois River	, 278
Inspection Date Time	06/26/201	5 15:10		Location	: IMT Chan (Crane)	
Load Status:	OEmp	nty O Partial (	<b>®</b> Loaded			
ereas and all safely acce- bolier areas, machinery st	ssible areas lorage area tive action r	s where chemic s, welldecks ar nust be initiated	cals, oils, dry cargo, or nd other areas). [Ref: \ I. [Ref: VGP 4.1,1] (4)	other materials are stored, mi /GP 4.1.1] (3) If pollutants or The term "sheen" is to be und	ixed and used (including constituents of concern	ly accessible deck and cargo , as applicable, cargo holds, are determined to be originating tion of oil or grease, including
Are Decks Clean?		<b>V</b>	Any Violatio	ns Discovered during Ins	pection or any corre	ctive actions required?
If no, were decks clea	anea?					
is the Water around the free of sheen?	barge	$\square$				
Was a sample taken	?					
Voids or Hopper Pumpe	d?					
Sheen present in wa pumping?	ter after					
Inspected by (Printed)	BARNA	RDWALTER	RS/CALLAHAN			
Approved by (Printed)	Robert S	Smith		Approved by (Signat	ure)	
Entering your Signature P problems nated	ll i indicates	that the bacyer	s) have then inspecte	d in accordance as incidated	about la	Such to any

Vessel General Permit Compliance

	eled once per ible areas wh age areas, w e action must	09:40 ) Partial ® ( week or per serie chemicals eldecks and o	Loi .eaded .eyage, whichever is more frequent. (2) L .elis. dry cargo, or other materials are sto	cation	Illinois River IMT Chan (Crane)	/ 278
Load Status;	Empty Celed once per ible areas whage areas, we action must	Partial (©) ( week or per v ere chemicals elidecks and o	.paded  royage, whichever is more frequent. (2) L , pils, dry cargo, or other materials are sto	ocation		
	eled once per ible areas wh age areas, w e action must	week or per v ere chemicals elidecks and o	royage, whichever is more frequent. (2) L , oils, dry cargo, or other materials are sto	ocation		
Imperiotion -	ible areas wh age areas, w e action must	ere chemicals elidecks and o	, oils, dry cargo, or other materials are sto	ocstion		
<ol> <li>This form is to be comple areas and all safely accessionler areas, machinery stor from the barge(s), corrective</li> </ol>	, and tagoter	de Indiated. (H Ne, of organic	ther eress) [Ref: VGP 4.1.1] (3) If poliuti lef: VGP 4.1.1] (4) The term "shoen" is to oils [Ref VGP Fact Sheef 3.4.4]	ents or	xed and used (including, as a constituents of concern are	applicable, cargo holds,
Are Decks Clean?	<b>[</b> ]	And the control of th	Any Violations Discovered duri	ng Ins	pection or any corrective	e actions required?
If no, were decks clean	ed? 🗀				,	
is the Water around the ba	arge 🗹					
Was a sample taken?						
Voids or Hopper Pumped?	? 🗆					
Sheen present in water pumping?	rafter 🗀	}				
Inspected by (Printed)	3ARNARO/	WALTERS/	CALLAHAN			
Approved by (Printed)	Robert Smit	n	Approved by (	Signali	иге)	
Specing your Signature Pik i problems apled	iadicates that	the pargérs i	iava caen hispected in accordance as inn	hoated	and Schul bus	nesty rooms
						ş

**IMT 1120** 

Equipment:	ING4794B			Vessel/As	set: A	Midwest Pride		
Company	Ingram Bar	ge Company	,	Waterv	vay: li	llinois River		1 279
Inspection Date Time	06/29/2015	14 05		Locat	on. [	Dock Barge Fleet		
Load Status:	Empty	r 🔾 Partial 🔾	Loaded					
preas and all safety acces buller areas, machinery st	sable areas v lorage areas, tive action mu	where chemics welldecks and ist be initiated.	is, oils, dry cargo, c Lother areas) [Ref [Ref: VGP 4.1.1] (4	or is more frequent. (2) Loci or other materials are stored or VGP 4.1.11 (3) if pollutants ) The term "sheen" is to be ct Sheet 3.4.41	f, mbke s or co	ed and used (including matituents of concern	g, as applicable n are determin	e, cargo helds, ed to be originati
Are Decks Clean?	[	a	Any Violat	ions Discovered during	Inspe	ection or any corre	ective action	s required?
If no were decks clea	aned? [		none					
Is the Water around the tree of sheen?	barge [	2						
Was a sample taken	? [	ן ר						
Voids or Hopper Pumpe	d?	1						
Sheen present in wa pumping?	ler after	]						
Inspected by (Printed)	BJ Thoma	as						
Approved by (Printed)	BJ Tnoma	18		Approved by (Sig	natur	· .		
r otering your Signature fo is obtains exted	N indicates ti	at the barooss	have been moper	ted in eucordance as mains	ded ab	m Billy	of Little	131-7-m-4

Equipment:	ING4794E		Vessel/Asset	Mary C	
Company	Ingram Bar	ge Company	Waterway:	Illinois River	/ 278
Inspection Date Time:	06/30/2015	11 00	Location:	IMT Chan (Crane)	
Load Status:	○Empty	OPartial ®	Loaded	,	
boller areas, machinery st from the barge(s), correct	ssible areas v lorage areas, tive action mu	vhere chemicals welldecks and ( at be initiated, [f	voyage, whichever is more frequent. (2) Location (3) olds, dry cargo, or other materials are alored, mighther areas). [Ref: VGP 4.1.1] (3) if pollutants or cases: VGP 4.1.1] (4) The term "sheen" is to be under olds [Ref: VGP Fact Sheet 3.4.4]	ced and used (including, as applicat constituents of concern are determined	ble, cargo holds,
Are Decks Clean?	[v	]	Any Violations Discovered during Ins	pection or any corrective actio	as required?
If no, were decks clea	aned?	]			
••					
is the Water around the free of sheen?	barge 🔄	3			
Was a sample taken	7 [	]			
Voids or Hopper Pumpe	a? [	)			
Sheen present in war pumping?	terafter [				
Inspected by (Printed)	BARNARI	D/WALTERS/	CALLAHAN		
Approved by (Printed)	Robert Sn	ith	Approved by (Signal)	ıre)	
Ordering your Eginatyra R Society on tod	is unleases th	riffe barge sir	na - El pen inspected in anomidation as indivision a	and John Sucr	for any

Equipment:	RMT323			Vessel/Asset.	Albert C		
Company:	Canal Barge Co	ompany		Waterway:	Illinois River	1 299.4	
Inspection Date Time	06/30/2015	14:10		Location:	IMT Lemont (Cle	anì	
Load Status;		Partial 🔿 Loaded	ı		·	•	
boiler areas, machinery	essible areas, well storage areas, well ctive action must be	e chemicals, oils, dr decks and other are initiated. [Ref: VGI	y cargo, or other mate (as) [Ref: VGP 4.1.1] (4.1.11 (4) The term ":	riels are stored, mb (3) If polulants or : sheen" is to be unde	ced and used (includi	Itely accessible deck and c ing, as applicable, cargo ho ern are determined to be or tration of oil or grease, inclu	olds.
Are Decks Clean?	oxive	Ai	ny Violations Disco	vered during ins	ection or any cor	rective actions require	d?
If no, were decks cle	eaned?						
is the Water around the free of sheen?	e barge						
Was a sample taker	n? 🔲						
Voids or Hopper Pump	ed?						
Sheen present in wa pumping?	ater after						
inspected by (Printed	) Peter Kosik						
Approved by (Printed)	Peter Kosik		Аррі	roved by (Signatu	re)		
Creating your Segmature F Creations Catem	Ti so her that the	) mango(s. have bus	a naphrean korra	larkon as indicary di	Ater	1 8 to	any any

Vessel General Permit Compliance Equipment: OR5212 Vessel/Asset: Aggie-C Company: Ingram Barge Company Waterway: Illinois River / 278 Inspection Date Time: 06/30/2015 15-24 Location. Rapps Fleet Load Status: ○ Empty ○ Partial ® Loaded instructions: (1) This form is to be completed once per week or per voyage, whichever is more frequent (2) Locations to be inspected. Safety accessible deck and cargo areas and all safety accessible areas where chemicals, oils, dry cargo, or other materials are stored, mixed and used (including, as applicable, cargo holds. boiler areas, machinery storage areas, welldecks and other areas). [Ref: VGP 4.1.1] (3) If pollutants or constituents of concern are determined to be originating from the barge(s), corrective action must be initiated [Ref: VGP 4.1.1] (4) The term "sheen" is to be understood as a concentration of oil or grease, including lubricating oils, hydraulic sils, and vegetable, or organic oils [Ref VGP Fact Sheet 3.4,4] Are Decks Clean? [2] Any Violations Discovered during Inspection or any corrective actions required?

If no, were decks cleaned? is the Water around the barge  $\mathbf{Y}$ free of sheen? Was a sample taken? Voids or Hopper Pumped? Sheen present in water after pumping? Inspected by (Printed) Ivar Von Waldenburg 14 mg 12 23 - 1 Approved by (Printed) Ivar Von Waldenburg

Approved by (Signature)

"mer ng ya mililigikaman (milimmatishes mer ilian kangalin dikun koloni i ndolona i makondalaya bisi miliki wad abbocontinue reserve



Equipment:	ING5752		Vessel/Asset	Midwest Pride	
Company:	Ingram Barge Cor	npany	Waterway	Illinois River	ı <b>27</b> 7
Inspection Date Time	06/30/2015 15	50	Cocation	Mobil Cake Upper	
Load Status:	Empty () Par	ntial 🗘 Losded		F. C.	
boiler areas, machinery st	ssiole areas where c orage areas, wellded tive action must be int	nemicals, oils, dry cargo, i iks and other areos). [Ref tiated, [Ref: VGP 4,1,1] (4	er is more frequent. (2) Location or other materiels are stored, mo I: VGP 4.1.1] (3) If pollutants or a 4) The term "sheen" is to be under lot Sheet 3.4.4]	ed and used (including, as	s applicable, cargo holds.
Are Decks Clean?	<b>I</b>	Any Violat	ions Discovered during Insp	ection or any correcth	/e actions required?
If no, were decks clea	aned?	none			,
is the Water around the free of sheen?	barge 🗹				
Was a sample taken?	? 🗆				
Voids or Hopper Pumpe	d? [~]				
Sheen present in wat pumping?					
Inspected by (Printed)	8J Thomas				
Approved by (Printed)	BJ Thomas		Approved by (Signatu		
Peterag your Bightenin Pe Detikene notes	n i Sti Mek Haffariya	Migers i have more in especi	ien ir storidas, e as ir bolled s	m Billy y	Home



Vessel General Permit Compliance

Equipment	OR5337			Vessel/Asset:	Aggie-C		
Company:	Ingram Barge Cr	ompany		Waterway:	Illinois River		/ 278
Inspection Date Time:	06/30/2015 1	5:56		Location;	Rapps Fleet		
Load Status:	○ Empty ○ P	artial 🌘 Loaded					
Instructions: (1) This form is to be co areas and all safely acc boiler areas, machinery from the barge(s), corre lubricating oils, hydrauling	essible areas where storage areas, welld ective action must be	chemicals, oils, dr ecks and other are initiated. (Ref: VGI	y cargo, or other m as) [Ref: VGP 4.1 24.1.1] (4) The terr	aterials are stored, mb .1] (3) If pollutants or i n "sheen" is to be und	ked and used (in constituents of c	cluding, as applicab cancern are determin	ile, cargo holds, ned to be originating
Are Decks Clean?	Ø	A	ny Violations Dis	covered during Insi	pection or any	corrective action	as required?
il no, were decks cl	eaned?						
is the Water around th	ne barge						
Was a sample take	n?						
Voids or Hopper Pump	oed?						
Sheen present in w pumping?	rater after						
Inspected by (Printer	i) İvar Von Waldı	enburg					
Approved by (Printed	i) Ivar Von Walde	enburg	A	pproved by (Signati	ure)	24	

Entering your Sign/fore PN inniviates that the barge(s) have been inspected in accommode as indicated abov.

